

managing risk with responsibility

Jeffrey S. Moquin, Director Risk Management Department

Signature on File

Telephone: 754-321-3200 Facsimile: 754-321-3290

April 23, 2007

TO:

Ms. Robin David, Principal

Royal Palm Elementary School

FROM: Edward See, Project Manager, Occupational Health and Environmental Control

Risk Management Department

SUBJECT: Indoor Air Quality (IAQ) Assessment

FISH 134

On March 15, 2007 I conducted an assessment of FISH 134 at **Royal Palm Elementary School**. This evaluation included observations of the flooring system, ceiling tiles, false ceiling plenum, environmental surfaces, interior and exterior walls, and the accessible ventilation equipment. Additionally, environmental parameter measurements were taken to include temperature, relative humidity, and carbon dioxide. The detailed findings, along with the recommended corrective action can be found on the attached IAQ Assessment Worksheets.

The IAQ assessment did identify one or more existing conditions impacting IAQ and has generated appropriate work orders to correct deficiencies in systems and maintenance that could contribute to decreased indoor air quality. At the time of the assessment, these concerns were not an immediate health or safety concern to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact me at 754-321-3200.

cc: Dr. Harry LaCava, Area Superintendent

Fran Bolden, Area Director

Jeffrey S. Moquin, Director, Risk Management

Israel Rodriguez-Soto, Project Manager, Facilities and Construction Management

Robert Goode, Project Manager, Facilities and Construction Management

Gary Itzkowitz, Broward Teachers Union

Mark Dorsett, Manager 1, Physical Plant Operations Division, Zone 1

Roy Norton, Manager Custodial/Grounds, Physical Plant Operations Division Robert Krickovich, Coordinator, LEA, Facilities and Construction Management

ES/tc Enc.

Royal Palm Elementary School					Evaluation Requeste	January 12, 2007
Time of Day	1:00 pm				Evaluation Da	March 15, 2007
Outdoor Condi	tions Temp	perature [Relative Humidity	Ami	bient CO2
Fish	Temperature R	ange Re	lative Humidity	Range	CO2 F	Range # Occupants
134	74.9 72	- 78	55.6	30% - 60%	1016 Max 7	00 > Ambient 0
Noticeable Odor No		da	Visible water mage / staining	Visible micro growth?	obial Amount of affect	
Ceiling Type			Yes	No	Alo	ng Kiln roof seal
Wall Type	Drywall		No	Yes Along North wall		ong North wall
Flooring	Vinyl		No	No		None
Clean Minor Dust Needs Corrective Action Required						
Ceiling	Yes	No	No			
Walls	Yes	No	No			
Flooring	No	Yes	Yes		Clean and san	itize
HVAC Supply	Grills					
HVAC Return Grills No Ye		Yes	Yes	CI	Clean with Wexcide disinfectant	
Ceiling at Sup Grills	ply					
Surfaces in Ro	oom No	Yes	Yes		Clean as appro	priate
bservations						
Findings: (Kiln Room) - Dust and debris on HVAC return grill. Appears that return grill is not operational. - Custodial staff advised that kiln is not being used - Roof vent is not operational - Visible microbial growth on North wall - Rust/staining around roof seal at kiln - Door hinges are rusted -Recommendations: Site Based Maintenance: - Clean HVAC return grill with Wexcide disinfectant solution						
 Continue to wipe down North wall with Wexcide disinfectant as necessary Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as 						

appropriate

Physical Plant Operations:
- Evaluate HVAC return grill to determine if operational
- Evaluate and repair roof vent

- Evaluate roof seal at kiln - Evaluate and repair/replace door hinges as appropriate

IAQ Assessment

1851

Location Number