

managing risk with responsibility

Telephone: 754-321-3200 Facsimile: 754-321-3290

February 2, 2	009 Signature on File
TO:	Mr. Charles Radkowski, Principal Sawgrass Elementary School
FROM:	Edward See, Project Manager Risk Management Department
SUBJECT:	Indoor Air Quality (IAQ) Assessment FISH 101M, 101N, 101P and 856

Custodial Issues Addressed Custodial Issues Not Addressed
Custodial Issues Not Addressed

On January 21, 2009 I conducted an assessment of FISH 101M, 101N, 101P and 856 at **Sawgrass Elementary School**. This evaluation included observations of the flooring system, ceiling tiles, false ceiling plenum, environmental surfaces, interior and exterior walls, and the accessible ventilation equipment. Additionally, environmental parameter measurements were taken to include temperature, relative humidity, and carbon dioxide. The detailed findings, along with the recommended corrective action can be found on the attached IAQ Assessment Worksheets.

The IAQ assessment did identify one or more existing conditions impacting IAQ and has generated appropriate work orders to correct deficiencies in systems and maintenance that could contribute to decreased indoor air quality. At the time of the assessment, these concerns were not an immediate health or safety concern to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Please ensure that your Head Facilities Serviceperson receives a copy of this correspondence so that the recommendations requiring their attention can be addressed. Within two weeks a representative from the Custodial/Grounds Department will conduct a follow-up visit to ensure that all issues have been appropriately addressed.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact me at 754-321-3200.

cc: Dr. Verda Farrow, Area Superintendent Michaelle Pope, Area Director Jeffrey S. Moquin, Executive Director, Support Operations James Carballo, Project Manager, Facilities and Construction Management Ruby Fitzgerald, Broward Teachers Union Roy Jarrett, National Federation of Public and Private Employees Mark Dorsett, Manager 1, Physical Plant Operations Division, Zone 1 Roy Norton, Manager Custodial/Grounds, Physical Plant Operations Division Robert Krickovich, Coordinator, LEA, Facilities and Construction Management

ES/tc Enc.

			IAQ As	sessment	Locati	on Number	3401	
	Sav	vgrass Elementa	ry School		Evalua	tion Requested	November	r 26, 2008
Time of Day						Evaluation Date	January	21, 2009
Outdoor Cond	litions Te	emperature	57.9	Relative Hum	idity 41.	l Ambie	nt CO2	375
Fish	Temperature	Range Rela	ative Humidity	Range	CO2	Ran	ge # (Occupants
101M	72.8	72 - 78	37.1	30% - 60%	947	Max 700	> Ambient	3
Noticeable O	dor No		Visible water nage / staining		microbial wth?	Amount of mat affected	terial	
Ceiling Type	2 x 4	1	No	N	lo		None	
Wall Type	Drywall/P	laster	No	N	lo		None	
Flooring	Carpe	et	No	N	lo		None	
	Clean	Minor Dust / Debris	Needs Cleaning	I	Corre	ctive Action Re	equired	
Ceiling	Yes	No	No					
Walls	Yes	No	No					
Flooring	Yes	No	No					
HVAC Supply	Grills Yes	No	No					
HVAC Return	Grills Yes	No	No					
Ceiling at Sup Grills	oply Yes	No	No					
Surfaces in R	oom Yes	No	No					

Findings:

- No signs of water intrusion or microbial growth

- Physical Plant recently cleaned coils on November 8, 2008 (FISH 103)

- 1 potted plant in room

Recommendations:

Site Based Maintenance:

- Remove plant from room. Soil is a source of microbial growth.

- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

			IAQ Ass	sessment	Location	Number	3401	
	Sawg	rass Elementa	ry School		Evaluation	Requested	Novembe	er 26, 2008
Time of Day					Eva	luation Date	January	21, 2009
Outdoor Condit	tions Tem	perature	57.9	Relative Humidity	41.1	Ambie	nt CO2	375
Fish 1	Femperature F	Range Rela	tive Humidity	Range	CO2	Ran	ige #	Occupants
101N	72.5 7	2 - 78	37.1	30% - 60%	1005	Max 700	> Ambient	3
Noticeable Od	or No		/isible water nage / staining	Visible micro ? growth?	bial A	mount of ma affected	terial	
Ceiling Type	2 x 4		Νο	No			None	
Wall Type	Drywall/Plas	ster	No	No			None	
Flooring	Carpet		No	No			None	
Ceiling	Clean Yes	Minor Dust / Debris No	Needs Cleaning No		Correctiv	ve Action Re	equired	
Walls	Yes	No	No					
Flooring	Yes	No	No					
HVAC Supply	Grills Yes	No	Νο					
HVAC Return (Grills Yes	No	No					
Ceiling at Supp Grills	oly Yes	No	No					
Surfaces in Ro	om Yes	No	No					

Findings: - No signs of water intrusion or microbial growth

Recommendations:

Site Based Maintenance: - Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

			IAQ As	sessment	Location Nu	ımber	3401	
	Sawg	rass Elementar	y School		Evaluation R	equested	Novembe	er 26, 2008
Time of Day					Evalu	ation Date	January	21, 2009
Outdoor Cond	itions Terr	nperature	57.9	Relative Humidity	41.1	Ambie	nt CO2	375
Fish	Temperature	Range Rela	tive Humidity	Range	CO2	Ran	ge #	Occupants
101P	70.3 7	2 - 78	39.2	30% - 60%	954	Max 700	> Ambient	2
Noticeable Oc	dor No		/isible water age / staining	Visible micro growth?	obial Am	ount of mat affected	terial	
Ceiling Type	2 x 4		No	No			None	
Wall Type	Drywall/Pla	ster	No	No			None	
Flooring	Carpet		No	No			None	
	Clean	Minor Dust / Debris	Needs Cleaning		Corrective	Action Re	equired	
Ceiling	Yes	Νο	No					
Walls	Yes	No	No					
Flooring	Yes	No	No					
HVAC Supply	Grills Yes	No	No					
HVAC Return	Grills Yes	No	No					
Ceiling at Sup Grills	oply Yes	No	No					
Surfaces in R	oom Yes	Νο	No					

Findings:

- No signs of water intrusion or microbial growth

- Temperature was low at the time of the assessment

Recommendations:

Site Based Maintenance:

- Adjust thermostat to increase temperature. If temperature does not improve, contact COMPASS to generate a work order for Physical Plant Operations to evaluate.

- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

			IAQ Ass	essment	Location	Number	3401	
	Sawgr	ass Elementary	v School		Evaluation	Requested	Novembe	er 26, 2008
Time of Day					Eva	luation Date	January	21, 2009
Outdoor Conditio	ons Tem	perature 5	7.9 F	Relative Humidi	ty 41.1	Ambie	nt CO2	375
Fish Te	mperature R	ange Relat	ive Humidity	Range	CO2	Ran	nge #	Occupants
856	68.7 7 2	2 - 78	34	30% - 60%	1259	Max 700	> Ambient	2
Noticeable Odo	r Yes		isible water age / staining?	Visible mic growtł		mount of ma affected	terial	
Ceiling Type	2 x 4		No	No] [None	
Wall Type	Drywall/Plas	ster	Yes	Yes] [@3	square feet	
Flooring	12 x 12		No	No] [None	
	Clean	Minor Dust / Debris	Needs Cleaning		Correctiv	ve Action Re	equired	
Ceiling	Yes	No	No					
Walls	No	Yes	Yes		Repair/rep	place wall m	aterial	
Flooring	Yes	No	No					
HVAC Supply G	rills Yes	No	No					
HVAC Return G	rills Yes	No	No					
Ceiling at Suppl Grills	y Yes	Νο	No					
Surfaces in Roo	m Yes	No	No					

Findings:

- Temperature was low and CO2 level was slightly elevated at the time of the assessment
- Musty odor in room
- Window at back door shows signs of paint bubbling

Recommendations:

Site Based Maintenance:

- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

Physical Plant Operations:

Evaluate HVAC system for proper operation and repair as appropriate to increase temperature and lower CO2 level
Evaluate cause of bubbling paint around window at back door and repair as appropriate. Repair/replace wall material as necessary.