THE SCHOOL BOARD OF BROWARD COUNTY, FLORIDA ENVIRONMENTAL HEALTH & SAFETY DEPARTMENT

FACSIMILE: (754) 321-4285

TELEPHONE (754) 321-4200

September 26	5, 2017	Signature on File	For Custodial Supervisor Use Only
TO:	Irina Shearer, Princ Silver Palms Elem	±	Custodial Issues Addressed Custodial Issues Not Addressed
FROM:		xy, Project Manager alth & Safety Department	
SUBJECT:	Indoor Air Quality	(IAQ) Assessment	

On September 25, 2017, I conducted an assessment at **Silver Palms Elementary School.** Attached are findings and recommendations for further assessment, remediation, or corrective actions needed.

The IAQ assessment did identify one or more existing conditions impacting IAQ and has generated appropriate work orders to correct deficiencies in systems and maintenance that could contribute to decreased indoor air quality. At the time of the assessment, these concerns were not an immediate health or safety concern to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Please ensure that your Head Facilities Serviceperson receives a copy of this correspondence so that the recommendations requiring their attention can be addressed. In an attempt to separate IAQ issues from general maintenance items, the attached assessment may contain direction for site based staff to generate a work order through COMPASS. Within two weeks a representative from the Custodial/Grounds Department will conduct a follow-up visit to ensure that all site based custodial issues have been appropriately addressed.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact us at 754-321-4200.

AW:smn Enc.

cc: Sam Bays, Director, Maintenance Operations
Shelley Meloni, Director, Pre-Construction
Mark Dorsett, Manager, Zone 1, Physical Plant Operations Division
Greg Neiman, Area Supervisor, Zone 1
Kurt Wirz, Area Manager Trades
Gerald Devio, Supervisor II Custodial
Benjamin Osborne, Supervisor II Custodial
Mark Murray, Supervisor II Custodial
Broward Teachers Union
Federation of Public Employees

Multiple Room IAQ Assessment

Silver F	•	ation Date September 2	5, 2017 Time of Day	1230
Outdoor Conditions	emperature 84.8	Relative Humidity 8	Ambient CO	2 583
Temperature Range in the	essed 76, 172, 169, 167,161, 152, 148, e Rooms Assessed was Between ge in the Rooms Assessed was Between as Assessed was between	72.1 And	78.3 Acceptable Range 54.8 Acceptable Range 984 Acceptable Range	72 - 78 30% - 60% MAX 700 > Ambient
Noticeable Odor Ceiling 2' X 4' Lay Walls Drywall Floor 12" x 12" Vi	Yes	nage / Visible microl growth? No Yes No	bial Amount material aff 1CT (1 behind cabinets	ected
Ceiling Clean Walls Clean Flooring Clean Room Surfaces Clean	Grills Clear Inside of S Duct Clear Ceiling at S	Supply Yes	HVAC Retu Grills Clear Inside of R Duct Clean	n Yes
Trash Removed Yes	S Exhaust Fans W	orking Yes	Unapproved Chen Cleaners in Room	
Signs of Pests Room Cluttered No.	_	Room is N/A	Air Fresheners in Room	No

Multiple Room IAQ Assessment
Silver Palms Elem. School Evaluation Date September 25, 2017 Time of Day 1230
Outdoor Conditions Temperature 84.8 Relative Humidity 80.1 Ambient CO2 583
HVAC System
Mechanical Equipment Location FISH 185, 186, 189 Mechanical Room Clean Yes
Filters Installed Properly Yes Filters Clean Yes Inside of HVAC Unit Clean Yes
Condensate Pan Clean Yes Cooling Coil Clean Yes N/A in this section = Not Accessible
Fresh Air Intake Location
Pollutant Sources Near Air Intake No ▼
Observations
All classrooms assessed on East side of building had water intrusion as a result of window leaks or roof leak. Most
water damaged or moldy drywall present behind baseboard and likely behind cabinets. Worst rooms near southeast corner of buildng. FISH 176 and 167 have wet wall material floor to ceiling. Went to each room and discussed what
should be removed with AP.
FISH 148 reportedly had a leak/water from ceiling down wall and onto bulletin board. No wet building materials
present, no odor observed.

Corrective Actions to be Completed by Site Based Staff

Corrective Actions to be completed by oite based of	<u> </u>
Evaluate and repair cause of stained ceiling tile	
Remove and replace stained ceiling tile	
If stains return, contact COMPASS for work order	
Thoroughly clean ALL surfaces after repairs made	▼
Remove and replace A/C Filters after repairs made	\blacksquare
	▼
	▼
	▼
	▼
	▼
	▼
	▼

Corrective Actions to be Completed by PPO

Evaluate and repair cause of water damaged	▼
wall material (behind cabinets)	▼
Remove and replace wall material as needed	▼
	▼
	▼
	▼
	▼
	▼
	▼
	▼
	▼
	▼
	▼

<u>▼</u>

_	•	
eded ▼	Evaluate and repair HVAC system as needed	
els 🔻	Repair HVAC to Reduce Humidity Levels	
▼	Evaluate for HVAC coil cleaning	
on 🔻	Evaluate restroom exhaust fan ope	
▼		
▼		
▼		
▼		