



Jeffrey S. Moquin, Director Risk Management Department Telephone: 754-321-3200 Facsimile: 754-321-3290

August 10, 2005

TO:	Mr. Alfred Dobronz, Principal Stirling Elementary School					
FROM:	Robert J. Krickovich, Coordinator, LEA Facilities and Construction Management, Environmental Division					
SUBJECT:	Indoor Air Quality (IAQ) Assessment Portable 43					
On Amount 4	2005 the IAO Accessment Team conducted an accessment of Portable 43					

On August 4, 2005 the IAQ Assessment Team conducted an assessment of Portable 43 at **Stirling Elementary School**. The evaluation consisted of a walkthrough of the identified areas to assess the current condition of the location with regard to indoor air quality. This assessment included observations of the carpet, floor tile, ceiling tile, interior walls, false ceiling plenum, and accessible ventilation equipment.

Attached are the findings of this assessment along with recommendations for further assessment, remediation, or corrective actions, if needed.

Generally, the IAQ Assessment did not identify any existing conditions significantly impacting IAQ and thereby presenting immediate health and safety concerns to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact me at 754-321-1638.

cc: Sam Gregg, Area Superintendent Margaret Underhill, Area Director Jeffrey S. Moquin, Director, Risk Management Bertram Lewars, Project Manager II, Facilities and Construction Management Diane Watts, Broward Teachers Union Mark Dorsett, Manager 1, Physical Plant Operations Division, Zone 1 Roy Norton, Manager Custodial/Grounds, Physical Plant Operations Division

RK/tc Enc.

IAQ Assessment										
Stirling Elementary School						Evaluation Requested		August 3, 2005		
Time of Day 12:50 pm					Evaluation Date August 4, 2005			4, 2005		
Outdoor Conditions	s Temp	berature	93	Relative Humidity 60.3			nt CO2	417		
Fish Temp	erature R	ange Rela	ative Humidity	Range	CO2	Ran	ge #	Occupants		
P 43 7	75.9 72	- 78	41.6	30% - 60%	569	Max 700	> Ambient	3		
Noticeable Odor Yes			Visible water Visible micr damage / staining? growth			Amount of material affected				
Ceiling Type	Ceiling Type Homosote		No		10	None				
Wall Type	Homosote		No		10	None				
Flooring	Carpet		No	Ν	Νο		None			
	Clean	Minor Dust / Debris	Needs Cleaning		Correc	ctive Action Re	equired			
Ceiling	Yes	No	No							
Walls	Yes	No	No							
Flooring	Yes	No	No							
HVAC Supply Grills	s Yes	Νο	No							
HVAC Return Grills	Yes	No	No							
Ceiling at Supply Grills	Yes	No	No							
Surfaces in Room	Yes	No	No							

Observations

Findings:

- Dust and debris on filter for HVAC unit on South wall
- Dust and debris on HVAC coils South unit
- Odor emitting from above ceiling area and can be noticed from the walkway outside of portable
- Water damaged siding on exterior North wall
- Caulking at facia boards is damaged/missing and facia needs to be repainted
- HVAC unit on South wall is not sealed properly and is allowing water intrusion into the wall

Recommendations:

Site Based Maintenance:

- Change filters on HVAC units

- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

Physical Plant Operations Division:

- Clean HVAC coils on South unit
- Evaluate cause of odor above ceiling and repair as appropriate
- Evaluate roofing and need for ventilation above ceiling
- Evaluate and repair/replace water damaged exterior siding North wall
- Reseal exterior of portable around HVAC units and facia and repaint facia as necessary