

# RISK MANAGEMENT...

managing risk with responsibility

Jeffrey S. Moquin, Director  
Risk Management Department

Telephone: 754-321-3200  
Facsimile: 754-321-3290

November 7, 2008

**Signature re on File**

TO: Mr. Lewis Jackson, Principal  
**Sunshine Elementary School**

FROM: Edward See, Project Manager  
Risk Management Department

SUBJECT: Indoor Air Quality (IAQ) Assessment  
**FISH 155, 156, 157 and 158**

<u>For Custodial Supervisor Use Only</u>	
<input type="checkbox"/>	Custodial Issues Addressed
<input type="checkbox"/>	Custodial Issues Not Addressed
_____	
_____	

On October 23, 2008 I conducted an assessment of FISH 155, 156, 157 and 158 at **Sunshine Elementary School**. This evaluation included observations of the flooring system, ceiling tiles, false ceiling plenum, environmental surfaces, interior and exterior walls, and the accessible ventilation equipment. Additionally, environmental parameter measurements were taken to include temperature, relative humidity, and carbon dioxide. The detailed findings, along with the recommended corrective action can be found on the attached IAQ Assessment Worksheets.

The IAQ assessment did identify one or more existing conditions impacting IAQ and has generated appropriate work orders to correct deficiencies in systems and maintenance that could contribute to decreased indoor air quality. At the time of the assessment, these concerns were not an immediate health or safety concern to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

*Please ensure that your Head Facilities Serviceperson receives a copy of this correspondence so that the recommendations requiring their attention can be addressed. Within two weeks a representative from the Custodial/Grounds Department will conduct a follow-up visit to ensure that all issues have been appropriately addressed.*

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact me at 754-321-3200.

cc: Dr. Joel Herbst, Area Superintendent  
Valerie Wanza, Area Director  
Jeffrey S. Moquin, Director, Risk Management  
Rey Olivera, Project Manager, Facilities and Construction Management  
Diane Watts, Broward Teachers Union  
Roy Jarrett, Federation of Public Employees  
Mark Dorsett, Manager 1, Physical Plant Operations Division, Zone 1  
Roy Norton, Manager Custodial/Grounds, Physical Plant Operations Division  
Robert Krickovich, Coordinator, LEA, Facilities and Construction Management

ES/tc  
Enc.

# IAQ Assessment

Location Number 1171  
 Evaluation Requested October 15, 2008  
 Evaluation Date October 23, 2008

Sunshine Elementary School

Time of Day

Outdoor Conditions      Temperature 81.1      Relative Humidity 73.5      Ambient CO2 390

Fish	Temperature	Range	Relative Humidity	Range	CO2	Range	# Occupants
155	75.3	72 - 78	58.5	30% - 60%	663	Max 700 > Ambient	2
Noticeable Odor		Visible water damage / staining?		Visible microbial growth?		Amount of material affected	
Ceiling Type		Yes		No		Ceiling A/C Panel	
Wall Type		No		No		None	
Flooring		No		No		None	

	Clean	Minor Dust / Debris	Needs Cleaning	Corrective Action Required
Ceiling	No	Yes	Yes	Repair/replace ceiling A/C panel
Walls	Yes	No	No	
Flooring	Yes	No	No	
HVAC Supply Grills	Yes	No	No	
HVAC Return Grills	Yes	No	No	
Ceiling at Supply Grills	Yes	No	No	
Surfaces in Room	Yes	No	No	

**Observations**

**Findings:**

- Occupant complaint of dryness, headaches and sneezing
- Ceiling A/C panel is rusted

**Recommendations:**

**Site Based Maintenance:**

- Generate a work order through COMPASS to repair/replace ceiling A/C panel
- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

# IAQ Assessment

Location Number 1171  
 Evaluation Requested October 15, 2008  
 Evaluation Date October 23, 2008

Sunshine Elementary School

Time of Day

Outdoor Conditions      Temperature 81.1      Relative Humidity 73.5      Ambient CO2 390

Fish	Temperature	Range	Relative Humidity	Range	CO2	Range	# Occupants
<span style="border: 1px solid black; padding: 2px;">157</span>	<span style="border: 1px solid black; padding: 2px;">73.9</span>	<span style="border: 1px solid black; padding: 2px;">72 - 78</span>	<span style="border: 1px solid black; padding: 2px;">60.5</span>	<span style="border: 1px solid black; padding: 2px;">30% - 60%</span>	<span style="border: 1px solid black; padding: 2px;">667</span>	<span style="border: 1px solid black; padding: 2px;">Max 700 &gt; Ambient</span>	<span style="border: 1px solid black; padding: 2px;">2</span>
Noticeable Odor		Visible water damage / staining?		Visible microbial growth?		Amount of material affected	
Ceiling Type		Yes		Yes		Northwest corner	
Wall Type		No		No		None	
Flooring		No		No		None	

	Clean	Minor Dust / Debris	Needs Cleaning	Corrective Action Required
Ceiling	<span style="border: 1px solid black; padding: 2px;">No</span>	<span style="border: 1px solid black; padding: 2px;">Yes</span>	<span style="border: 1px solid black; padding: 2px;">Yes</span>	<span style="border: 1px solid black; padding: 2px;">Remove and replace ceiling tiles</span>
Walls	<span style="border: 1px solid black; padding: 2px;">Yes</span>	<span style="border: 1px solid black; padding: 2px;">No</span>	<span style="border: 1px solid black; padding: 2px;">No</span>	<span style="border: 1px solid black; padding: 2px;"></span>
Flooring	<span style="border: 1px solid black; padding: 2px;">Yes</span>	<span style="border: 1px solid black; padding: 2px;">No</span>	<span style="border: 1px solid black; padding: 2px;">No</span>	<span style="border: 1px solid black; padding: 2px;"></span>
HVAC Supply Grills	<span style="border: 1px solid black; padding: 2px;">Yes</span>	<span style="border: 1px solid black; padding: 2px;">No</span>	<span style="border: 1px solid black; padding: 2px;">No</span>	<span style="border: 1px solid black; padding: 2px;"></span>
HVAC Return Grills	<span style="border: 1px solid black; padding: 2px;">Yes</span>	<span style="border: 1px solid black; padding: 2px;">No</span>	<span style="border: 1px solid black; padding: 2px;">No</span>	<span style="border: 1px solid black; padding: 2px;"></span>
Ceiling at Supply Grills	<span style="border: 1px solid black; padding: 2px;">Yes</span>	<span style="border: 1px solid black; padding: 2px;">No</span>	<span style="border: 1px solid black; padding: 2px;">No</span>	<span style="border: 1px solid black; padding: 2px;"></span>
Surfaces in Room	<span style="border: 1px solid black; padding: 2px;">No</span>	<span style="border: 1px solid black; padding: 2px;">Yes</span>	<span style="border: 1px solid black; padding: 2px;">Yes</span>	<span style="border: 1px solid black; padding: 2px;">Clean as appropriate</span>

**Observations**

**Findings:**

- Stained ceiling tiles in Northwest corner of room with visible microbial growth
- Ceiling A/C panel has minor rust
- Heavy dust build up on environmental surfaces throughout the room
- Thermostats are old style and can be adjusted by occupants
- Humidity level was slightly elevated at the time of the assessment

**Recommendations:**

**Site Based Maintenance:**

- Remove and replace stained ceiling tiles until Physical Plant Operations can evaluate for cause
- Thoroughly clean environmental surfaces throughout the room
- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

**Physical Plant Operations:**

- Evaluate cause of stained ceiling tiles in Northwest corner of room and repair as appropriate. Replace ceiling tiles as necessary.
- Evaluate HVAC for proper operation and repair as appropriate to lower humidity level

# IAQ Assessment

Location Number 1171  
 Evaluation Requested October 15, 2008  
 Evaluation Date October 23, 2008

Sunshine Elementary School

Time of Day

Outdoor Conditions      Temperature 81.1      Relative Humidity 73.5      Ambient CO2 390

Fish	Temperature	Range	Relative Humidity	Range	CO2	Range	# Occupants
<span style="border: 1px solid black; padding: 2px;">156/158</span>	<span style="border: 1px solid black; padding: 2px;">73</span>	<span style="border: 1px solid black; padding: 2px;">72 - 78</span>	<span style="border: 1px solid black; padding: 2px;">58</span>	<span style="border: 1px solid black; padding: 2px;">30% - 60%</span>	<span style="border: 1px solid black; padding: 2px;">611</span>	<span style="border: 1px solid black; padding: 2px;">Max 700 &gt; Ambient</span>	<span style="border: 1px solid black; padding: 2px;">2</span>
Noticeable Odor	<span style="border: 1px solid black; padding: 2px;">No</span>		Visible water damage / staining?		Visible microbial growth?		Amount of material affected
Ceiling Type	<span style="border: 1px solid black; padding: 2px;">2 x 4</span>		<span style="border: 1px solid black; padding: 2px;">Yes</span>		<span style="border: 1px solid black; padding: 2px;">No</span>		<span style="border: 1px solid black; padding: 2px;">2 ceiling A/C panels</span>
Wall Type	<span style="border: 1px solid black; padding: 2px;">Homasote</span>		<span style="border: 1px solid black; padding: 2px;">No</span>		<span style="border: 1px solid black; padding: 2px;">No</span>		<span style="border: 1px solid black; padding: 2px;">None</span>
Flooring	<span style="border: 1px solid black; padding: 2px;">12 x 12 Vinyl</span>		<span style="border: 1px solid black; padding: 2px;">No</span>		<span style="border: 1px solid black; padding: 2px;">No</span>		<span style="border: 1px solid black; padding: 2px;">None</span>

	Clean	Minor Dust / Debris	Needs Cleaning	Corrective Action Required
Ceiling	<span style="border: 1px solid black; padding: 2px;">No</span>	<span style="border: 1px solid black; padding: 2px;">Yes</span>	<span style="border: 1px solid black; padding: 2px;">Yes</span>	<span style="border: 1px solid black; padding: 2px;">Repair/replace ceiling A/C panel</span>
Walls	<span style="border: 1px solid black; padding: 2px;">Yes</span>	<span style="border: 1px solid black; padding: 2px;">No</span>	<span style="border: 1px solid black; padding: 2px;">No</span>	<span style="border: 1px solid black; padding: 2px;"></span>
Flooring	<span style="border: 1px solid black; padding: 2px;">Yes</span>	<span style="border: 1px solid black; padding: 2px;">No</span>	<span style="border: 1px solid black; padding: 2px;">No</span>	<span style="border: 1px solid black; padding: 2px;"></span>
HVAC Supply Grills	<span style="border: 1px solid black; padding: 2px;">Yes</span>	<span style="border: 1px solid black; padding: 2px;">No</span>	<span style="border: 1px solid black; padding: 2px;">No</span>	<span style="border: 1px solid black; padding: 2px;"></span>
HVAC Return Grills	<span style="border: 1px solid black; padding: 2px;">Yes</span>	<span style="border: 1px solid black; padding: 2px;">No</span>	<span style="border: 1px solid black; padding: 2px;">No</span>	<span style="border: 1px solid black; padding: 2px;"></span>
Ceiling at Supply Grills	<span style="border: 1px solid black; padding: 2px;">Yes</span>	<span style="border: 1px solid black; padding: 2px;">No</span>	<span style="border: 1px solid black; padding: 2px;">No</span>	<span style="border: 1px solid black; padding: 2px;"></span>
Surfaces in Room	<span style="border: 1px solid black; padding: 2px;">No</span>	<span style="border: 1px solid black; padding: 2px;">Yes</span>	<span style="border: 1px solid black; padding: 2px;">Yes</span>	<span style="border: 1px solid black; padding: 2px;">Clean as appropriate</span>

**Observations**

**Findings: (Two rooms open to each other)**

- Occupant complaint of pungent odor in the morning, allergies and temperature fluctuation
- Two (2) ceiling A/C panels are rusted
- Heavy dust build up on environmental surfaces throughout the room
- Door was ajar to the outside

**Recommendations:**

**Site Based Maintenance:**

- Generate a work order through COMPASS to repair/replace ceiling A/C panels
- Thoroughly clean environmental surfaces throughout the room
- Ensure that all doors to the exterior remain closed. Open doors or windows allow humid untreated air into occupied environment.
- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate