

managing risk with responsibility

| Aston A. Henry, Director | |
|---------------------------|---|
| Risk Management Departmen | t |

 Telephone:
 754 321-1900

 Fax:
 754 321-1917

| February 12, | , 2014 Signature on File | For Custodial Supervisor Use Only |
|--------------|---|---|
| TO: | Michael Breslaw, Principal Tradewinds Elementary School | Custodial Issues Addressed Custodial Issues Not Addressed |
| FROM: | Robert Krickovich, Coordinator I, LEA Risk Management Department | |
| SUBJECT: | Indoor Air Quality (IAQ) Assessment | |

On January 31, 2014, I conducted an assessment at **Tradewinds Elementary School**. Attached are findings and recommendations for further assessment, remediation, or corrective actions needed.

The IAQ assessment did identify one or more existing conditions impacting IAQ and has generated appropriate work orders to correct deficiencies in systems and maintenance that could contribute to decreased indoor air quality. At the time of the assessment, these concerns were not an immediate health or safety concern to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Please ensure that your Head Facilities Serviceperson receives a copy of this correspondence so that the recommendations requiring their attention can be addressed. In an attempt to separate IAQ issues from general maintenance items, the attached assessment may contain direction for site based staff to generate a work order through COMPASS. Within two weeks a representative from the Custodial/Grounds Department will conduct a follow-up visit to ensure that all site based custodial issues have been appropriately addressed.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact us at 754-321-1907.

cc: Shelley Meloni, Task Assigned Chief Facilities & Construction Officer, Facilities & Construction Mark Dorsett, Manager, Zone 1, Physical Plant Operations Division Roy Norton, Manager, Custodial/Grounds, Physical Plant Operations Division Aston Henry, Director, Risk Management Sonja Coley, Senior Project Manager, Facilities & Construction Broward Teachers Union Federation of Public Employees

RK/tc Enc.

| IAQ Assessment | | | |
|--|---|---|--|
| Tradewinds | Elementary Evaluation Da | te January 31, 2014 | Time of Day 12:00 |
| Outdoor Conditions Tempera | ature 85.4 Relative | e Humidity 73.4 | Ambient CO2 483 |
| | | Range CO ² % - 60% 495 | Range# OccupantsMAX 700 >4Ambient |
| Noticeable Odor No | Visible water damage / staining? | Visible microbial growth? | Amount of material affected |
| Ceiling 2' X 4' Lay in Walls Drywall Floor 12" x 12" Vinyl | Yes No | Yes | 3 tiles All walls spotty |
| | No | No | |
| Ceiling Clean Yes | HVAC Supply Grills Clean | No | HVAC Return Grills Clean Yes |
| Walls CleanYesFlooring CleanYes | Inside of Supply Duct Clean | Yes | Inside of Return Duct Clean Yes |
| Room Surfaces Yes Clean | Ceiling at Supply Grills Clean | Yes | |
| Trash Removed Yes | Exhaust Fans Working | Yes | Unapproved Chemicals / Cleaners in Room |
| Signs of Pests No | Drain Traps Wet | Yes | |
| Room Cluttered No | Food if Stored in Room is in Sealed Containers | N/A | Air Fresheners No in Room |
| Mechanical Equipment Location | Wall Mounted Unit | | Mechanical Room Clean N/A |
| Filters Installed Properly Yes | Filters Clean | N/A | Inside of HVAC Unit Clean N/A |
| Condensate Pan Clean N/A | Cooling Coil Clean | N/A | |
| Fresh Air Intake Location Pollutant Sources Near Air | Outside of Unit | ▼ | Fresh Air Intake Free Yes |
| Intake | None | ▼ | |
| Observations 3 stained ceiling tiles with micro | hial arouth _ microhial arouth | a spotty on wells | |
| Thermostat fan set to ON positio | | | bed to 73.4% |
| | | | |

Corrective Actions to be Completed by Site Based Staff

| ▼ |
|---|
| ▼ |
| ▼ |
| ▼ |
| ▼ |
| ▼ |
| ▼ |
| ▼ |

Corrective Actions to be Completed by PPO

| Evaluate and repair cause of stained ceiling tiles | ▼ |
|---|---|
| Remove and replace stained ceiling tiles | ▼ |
| Repair HVAC to reduce humidity level | ▼ |
| Clean and paint all walls with anti-microbial paint | ▼ |
| | ▼ |
| | ▼ |
| Check HVAC in all modular units | ▼ |
| Fans continue to run when compressors shut off | |

| IAQ Assessment | | | | |
|--|--|--|--|---------------|
| Tradewinds | Elementary Evaluation Dat | e January 31, 2014 | Time of Day 1 | 2:00 |
| Outdoor Conditions Temper | ature 85.4 Relative | Humidity 73.4 | Ambient CO2 4 | 83 |
| | | Range CO % - 60% 531 | | ccupants 5 |
| Noticeable Odor Yes | Visible water damage / staining? | Visible microbial growth? | Amount of material affected | |
| Ceiling 2' X 4' Lay in | Yes | Yes | 10 tiles at supply gri | ills |
| Walls Drywall | No | Yes | Spotty South wall | |
| Floor 12" x 12" Vinyl | No | No | | |
| Ceiling Clean Yes Walls Clean Yes | HVAC Supply Grills Clean | Yes | HVAC Return Grills Clean | Yes |
| Flooring Clean Yes | Inside of Supply Duct Clean | Yes | Inside of Return Duct Clean | Yes |
| Room Surfaces Yes Clean | Ceiling at Supply Grills Clean | Yes | | |
| Trash Removed Yes | Exhaust Fans Working | Yes | Unapproved Chemicals / Cleaners in Room | No |
| Signs of PestsNoRoom ClutteredNo | Drain Traps Wet Food if Stored in Room is in Sealed Containers | Yes N/A | Air Fresheners in Room | No |
| Mechanical Equipment Location | Wall Mounted Unit | | Mechanical Room Clean | N/A |
| Filters Installed Properly Ye | s Filters Clean | N/A | Inside of HVAC Unit Clean | N/A |
| Condensate Pan Clean | Cooling Coil Clean | N/A | | |
| Fresh Air Intake Location | Outside of Unit | ▼ | Fresh Air Intake Free of Obstruction | Yes |
| Pollutant Sources Near Air Intake | None | ▼ | or obstruction | |
| Observations | | | | |
| Musty odor - microbial growth o spotty on walls - microbial grov board with microbial growth | | | | |

Thermostat fan set to ON position - when compressor shut off humidity in room climbed to 73.4%

Corrective Actions to be Completed by Site Based Staff

| Relocate occupant to different classroom | ▼ |
|--|---|
| until repairs are completed | ▼ |
| | ▼ |
| | ▼ |
| | ▼ |
| | ▼ |
| | ▼ |
| | ▼ |

Corrective Actions to be Completed by PPO

| Evaluate and repair cause of stained ceiling tiles | ▼ |
|---|---|
| Remove and replace stained ceiling tiles | ▼ |
| Replace restroom door | ▼ |
| Repair HVAC to reduce humidity level | ▼ |
| Clean and paint all walls with anti-microbial paint | ▼ |
| | ▼ |
| Check HVAC in all modular units | ▼ |
| Fans continue to run when compressors shut off | ▼ |