

managing risk with responsibility

Telephone: 754-321-3200 Facsimile: 754-321-3290

Jeffrey S. Moquin, Director Risk Management Department

August 10, 2005

TO: Mr. Edmond Wade, Principal

Blanche Ely High School

FROM: Robert J. Krickovich, Coordinator, LEA

Facilities and Construction Management, Environmental Division

SUBJECT: Indoor Air Quality (IAQ) Assessment

FISH 331 and Science Building

On July 28, 2005 and August 4, 2005 the IAQ Assessment Team conducted an assessment of FISH 331 and the Science Building at **Blanche Ely High School**. The evaluation consisted of a walkthrough of the identified areas to assess the current condition of the location with regard to indoor air quality. This assessment included observations of the carpet, floor tile, ceiling tile, interior walls, false ceiling plenum, and accessible ventilation equipment.

Attached are the findings of this assessment along with recommendations for further assessment, remediation, or corrective actions, if needed.

Generally, the IAQ Assessment did not identify any existing conditions significantly impacting IAQ and thereby presenting immediate health and safety concerns to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact me at 754-321-1638.

cc: Dr. Joanne Harrison, Area Superintendent
Craig Anderson, Area Director
Jeffrey S. Moquin, Director, Risk Management
Rigo Zubizarreta, Project Manager II, Facilities and Construction Management
LaFrances Trotter, Broward Teachers Union
Mark Dorsett, Manager 1, Physical Plant Operations Division, Zone 1
Roy Norton, Manager Custodial/Grounds, Physical Plant Operations Division

RK/tc Enc.

IAQ Assessment

	ВІ	anche Ely High	School		Evaluation R	equested	July 28, 2005
Time of Day	1:00 pm				Evalu	ation Date	July 28, 2005
Outdoor Condition	s Temp	perature 9	2.1	Relative Humidity	66.5	Ambien	nt CO2 424
Fish Tem	perature R	ange Relat	ive Humidity	Range	CO2	Rang	ge # Occupants
331	88.5 72	- 78	68.8	30% - 60%	442	Max 700 >	> Ambient 1
Noticeable Odor	No		isible water age / staining	Visible micro growth?	obial Am	ount of mate affected	erial
Ceiling Type	2 x 4 Lay Ir	n	Yes	No		One stain	ed tile in 330C
Wall Type	Plaster		No	No		N	None
Flooring	12 x 12 Viny	1	No	No			None
	Clean	Minor Dust / Debris	Needs Cleaning		Corrective	Action Red	quired
Ceiling	Yes	No	No				
Walls	Yes	No	No				
Flooring	Yes	No	No				
HVAC Supply Gril	Is No	Yes	Yes	С	lean with We	xcide disir	nfectant
HVAC Return Grill	s				N/A th	ough door	•
Ceiling at Supply Grills	No	Yes	Yes	С	lean with We	excide disir	nfectant
Surfaces in Room	Yes	No	No				

Observations

Findings:

- Visible microbial growth on wall in air handler room (330E)
- HVAC unit was turned off at time of assessment
- One stained ceiling tile in room 330C (outside of 330E)
- Dust and debris on HVAC supply grills
- Dust and debris on ceiling at HVAC supply grills

Recommendations:

Site Based Maintenance:

- Clean HVAC supply grills with Wexcide disinfectant solution
- Clean ceiling at HVAC supply grills
- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

Physical Plant Operations Division:

- Evaluate and repair cause of stained ceiling tile in room 330C and repair as appropriate and replace ceiling tile
- Evaluate and remove and replace damaged drywall in room 330E
- Evaluate HVAC unit for proper operation and instruct site based staff on proper operation of unit

IAQ Assessment

		Blanche Ely Hig	h School		Evaluation Reques	August 4, 2005
Time of Day	12:00 pm]			Evaluation I	Date August 4, 2005
Outdoor Condit	tions Ter	mperature 8	39.6	Relative Humidity	58.8 Ar	mbient CO2 423
Fish 1	Temperature	Range Rela	tive Humidity	Range	CO2	Range # Occupants
Science	72.1	72 - 78	56.3	30% - 60%	441 Max	700 > Ambient 2
Noticeable Od	or No		/isible water nage / staining	Visible micro ? growth?		of material cted
Ceiling Type	2 x 4 Lay	[/] In	Yes	Yes	Ar	ound exhaust fans
Wall Type	Drywa	ı	No	No		None
Flooring	12 x 12 Vi	nyl	Yes	No	U	nder exhaust fans
	Clean	Minor Dust / Debris	Needs Cleaning		Corrective Actio	n Required
Ceiling	No	Yes	Yes		Clean as appr	opriate
Walls	Yes	No	No			
Flooring	Yes	No	No			
HVAC Supply (Grills No	Yes	Yes	С	lean with Wexcide	disinfectant
HVAC Return (Grills No	Yes	Yes	С	lean with Wexcide	disinfectant
Ceiling at Supp Grills	oly No	Yes	Yes		Clean as appr	opriate
Surfaces in Ro	om Yes	No	No			

Observations

Findings: Entire Science Building

- Microbial growth on ceiling tiles around and under exhaust fan duct work
- Heavy dust and debris on ceiling and fire sprinklers
- Dust and debris on HVAC supply and return grills
- Heavy dust and debris on ceiling at HVAC supply grills
- One damper actuator not wired
- Building is in negative pressure

Recommendations:

Site Based Maintenance:

- Clean ceiling and fire sprinklers as appropriate
- Clean HVAC supply and return grills with Wexcide disinfectant solution
- Clean ceiling at HVAC supply grills as appropriate
- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

Physical Plant Operations Division:

- Evaluate HVAC for proper operation and check all controls and repair as appropriate
- Evaluate damper actuators for proper operation and repair as appropriate (one was not wired)
- Insulate duct as necessary and evaluate exhaust ducts for proper operation
- Replace all damaged ceiling tiles and check interlock of all exhaust fans