

managing risk with responsibility

Telephone: 754-321-3200 Facsimile: 754-321-3290

Jeffrey S. Moquin, Director Risk Management Department

January 5, 2005

TO: Dr. Timothy Gadson, Principal

Boyd Anderson High School

FROM: Robert J. Krickovich, Project Manager II, Environmental

Facilities and Construction Management

SUBJECT: Indoor Air Quality (IAQ) Assessment

FISH 185 and 194

On December 21, 2004 the IAQ Assessment Team conducted an assessment of FISH 185 and 194 at **Boyd Anderson High School**. The evaluation consisted of a walkthrough of the identified areas to assess the current condition of the location with regard to indoor air quality. This assessment included observations of the carpet, floor tile, ceiling tile, interior walls, false ceiling plenum, and accessible ventilation equipment.

Attached are the findings of this assessment along with recommendations for further assessment, remediation, or corrective actions, if needed.

Generally, the IAQ Assessment did not identify any existing conditions significantly impacting IAQ and thereby presenting immediate health and safety concerns to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact me at 954-760-7326.

cc: Dr. Harry LaCava, Area Superintendent

Fran Bolden, Area Director

Jeffrey S. Moquin, Director, Risk Management

Israel Rodriguez-Soto, Project Manager II, Facilities and Construction Management

Dane Ramson, Broward Teachers Union

Mark Dorsett, Manager 1, Physical Plant Operations Division, Zone 1

RK/tc

IAQ Assessment **Evaluation Requested** December 14, 2004 Boyd Anderson High School **Evaluation Date** December 21, 2004 Time of Day 1:15 pm **Outdoor Conditions Temperature** 70.3 62 **Relative Humidity Ambient CO2** 412 Temperature Fish CO₂ **Relative Humidity** Range Range Range # Occupants 56.6 871 185 66.9 72 - 78 < 1,000 PPM 3 30% - 60% Visible water Visible microbial Amount of material **Noticeable Odor** No damage / staining? growth? affected **Ceiling Type** 2x4 Lay In No None No **Wall Type** Drywall None No No **Flooring** Vinyl None No No Clean **Minor Dust Needs Corrective Action Required** Cleaning / Debris Ceiling Yes No No Yes No No Walls Clean and sanitize flooring **Flooring** No Yes Yes HVAC Supply Grills | Yes No No HVAC Return Grills | Yes No No **Ceiling at Supply** Yes No No **Grills Surfaces in Room** No Yes Yes Clean/Dust surfaces **Observations** Findings: Dust and debris on flooring Papers in piles on floor and empty soda cans in room on tables Dust/dirt accumulation on environmental surfaces Recommendations: Site Based Maintenance: Clean and sanitize flooring Clean/dust environmental surfaces Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as

- appropriate

IAQ Assessment

Boyd Anderson High School					Evaluation Requested December 14, 2004		
Time of Day	1:15 pm				ı	Evaluation Date	December 21, 2004
Outdoor Condition	ons Te	mperature	70.3	Relative Humidity	62	Ambient	CO2 412
Fish Te	mperature	Range	Relative Humidity	/ Range	CO2	Range	# Occupants
194	69.4	72 - 78	54.4	30% - 60%	1182	< 1,000 P	PM 3
Noticeable Odor No			Visible water damage / stainin	Visible water Visible microbial lamage / staining? growth?		Amount of materi affected	al
Ceiling Type	Ceiling Type 2x4 Lay In		No No			None	
Wall Type	Plaster		Yes No			180 Square Feet	
Flooring	Vinyl		No	No		No	one
Calling	Clean	Minor D / Debr		9	Corre	ctive Action Requ	iired
Ceiling	163	140	140				
Walls	Yes	No	No				
Flooring No Yes		Yes		Clean and sanitize flooring			
HVAC Supply G	rills Yes	No	No				
HVAC Return G	rills Yes	No	No				
Ceiling at Suppl Grills	y No	Yes	Yes		Clean o	lust from ceiling t	illes
Surfaces in Roo	m No	Yes	Yes		Cle	an/Dust surfaces	

Observations

Findings:

- Tackable wall surface (20' x 9') on west wall is water damaged from previous roof leak
- Non SBBC chemicals identified under sink in room (clorox bleach, glass plus and 409 spray cleaner)
- Dust and debris on flooring
- Dust on ceiling tiles
- Dust/dirt accumulation on environmental surfaces
- Slightly elevated carbon dioxide level detected

Recommendations:

Site Based Maintenance:

- Remove non SBBC chemicals
- Clean and sanitize flooring
- Clean dust from ceiling tiles
- Clean/dust environmental surfaces
- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

Physical Plant Operations Division:

- Remove tackable wall surface and repair as needed and evaluate roofing repairs performed on 12/20/04 to ensure that problem has been corrected
- Evaluate and repair as appropriate the fresh air damper in order to lower the carbon dioxide level