

Portable 1233C

managing risk with responsibility

Telephone: 754-321-3200

Facsimile: 754-321-3290

Jeffrey S. Moquin, Director Risk Management Department

June 4, 2008	Signature on File	For Custodial Supervisor Use Only			
TO:	Mr. Charles Neely, Principal Cypress Bay High School	Custodial Issues Addressed Custodial Issues Not Addressed			
FROM:	Edward See, Project Manager Risk Management Department				
SUBJECT:	Indoor Air Quality (IAQ) Assessment				

On May 19, 2008 I conducted an assessment Portable 1233C at Cypress Bay High School. This evaluation included observations of the flooring system, ceiling tiles, false ceiling plenum, environmental surfaces, interior and exterior walls, and the accessible ventilation equipment. Additionally, environmental parameter measurements were taken to include temperature, relative humidity, and carbon dioxide. The detailed findings, along with the recommended corrective action can be found on the attached IAQ Assessment Worksheets.

The IAQ assessment did identify one or more existing conditions impacting IAQ and has generated appropriate work orders to correct deficiencies in systems and maintenance that could contribute to decreased indoor air quality. At the time of the assessment, these concerns were not an immediate health or safety concern to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Please ensure that your Head Facilities Serviceperson receives a copy of this correspondence so that the recommendations requiring their attention can be addressed. Within two weeks a representative from the Custodial/Grounds Department will conduct a follow-up visit to ensure that all issues have been appropriately addressed.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact me at 754-321-3200.

Cc: Dr. Verda Farrow, Area Superintendent
 Jan Beal, Area Director
 Jeffrey S. Moquin, Director, Risk Management
 Gerry Usallan, Project Manager, Facilities and Construction Management
 Ralph Eckhardt, Broward Teachers Union
 Roy Jarrett, Federation of Public Employees
 Mark Dorsett, Manager 1, Physical Plant Operations Division, Zone 1
 Roy Norton, Manager Custodial/Grounds, Physical Plant Operations Division
 Robert Krickovich, Coordinator, LEA, Facilities and Construction Management

ES/tc Enc.

		Cypress Bay F	ligh School		⊏vaiuati	ion Requested	May 7, 2008	
Time of Day	3:30 pm				E	Evaluation Date	May 14, 2008	
Outdoor Conditions Temperature 87.9 Relative Humidity 54.5 Ambient CO2 397								
<u> </u>	Temperature	Range R	elative Humidity	Range	CO2	Ran		
P-1233C	68	72 - 78	55.3	30% - 60%	2170	Max 700	> Ambient 3	
Noticeable Od	lor No	d	Visible water Visible micr damage / staining? growth			obial Amount of material affected		
Ceiling Type	5 x 7	7	No	No			None	
Wall Type	Plaster/D	rywall	No	No]	None		
Flooring	12 x 12 \	√inyl	No	No]		None	
	Clean	Minor Dus / Debris	Cleaning		Correc	ctive Action Re	quired	
Ceiling	Yes	No	No					
Walls	No	Yes	Yes		Wipe down walls			
Flooring	No	Yes	Yes		Clean and sanitize			
HVAC Supply	Grills Yes	No	No					
HVAC Return	Grills Yes	No	No					
Ceiling at Sup Grills	ply Yes	No	No					
Surfaces in Ro	oom No	Yes	Yes		Clea	an as appropri	ate	
Observations								

IAQ Assessment

3041

Location Number

Findings:

- Dust build up on walls
- Dust and debris on floor
- Dust build up on environmental surfaces (window sills, desks, etc.)
- Temperature was low at the time of the assessment
- CO2 level was slightly elevated at the time of the assessment

Recommendations:

Site Based Maintenance:

- Wipe down walls to remove dust build up
- Thoroughly clean and sanitize floor
- Thoroughly clean environmental surfaces
- Adjust thermostat to increase temperature
- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

Physical Plant Operations:

Evaluate A/C for proper operation and repair as appropriate to lower CO2 level