

Aston A. Henry, Supervisor Risk Management Department

managing risk with responsibility

 Telephone:
 754 321-1900

 Fax:
 754 321-1917

June 22, 2009	Signature on File	For Custodial Supervisor Use Only			
TO:	Mr. Charles Neely, Principal Cypress Bay High School	Custodial Issues Addressed Custodial Issues Not Addressed			
FROM:	Edward See, Project Manager Risk Management Department				
SUBJECT:	Indoor Air Quality (IAQ) Assessment Portable 1215C				

On April 22, 2009 I conducted a follow-up assessment Portable 1215C at **Cypress Bay High School**. The assessment consisted of a reevaluation walkthrough of the previously identified areas to assess the current condition of the location with regard to indoor air quality. This assessment included reviewing previously generated work orders, if applicable, as well as observation of the area of concern as stated in the IAQ Assessment performed on October 17, 2008. Attached are the findings of this assessment along with recommendations for further assessment, remediation, or corrective actions, if needed.

Generally, the IAQ Assessment did not identify any existing conditions significantly impacting IAQ and thereby presenting immediate health and safety concerns to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Please ensure that your Head Facilities Serviceperson receives a copy of this correspondence so that the recommendations requiring their attention can be addressed. Within two weeks a representative from the Custodial/Grounds Department will conduct a follow-up visit to ensure that all issues have been appropriately addressed.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact me at 754-321-1900.

cc: Dr. Verda Farrow, Area Superintendent Fran Bolden, Area Director Jeffrey S. Moquin, Executive Director, Support Operations Aston A. Henry, Supervisor, Risk Management Gerry Usallan, Project Manager, Facilities and Construction Management Ralph Eckhardt, Broward Teachers Union Roy Jarrett, Federation of Public Employees Mark Dorsett, Manager 1, Physical Plant Operations Division, Zone 1 Roy Norton, Manager Custodial/Grounds, Physical Plant Operations Division Robert Krickovich, Coordinator, LEA, Facilities and Construction Management

ES/tc Enc.

			IAQ Ass	sessment	Location Numb	er [3623	
	C	ypress Bay Hig	h School		Evaluation Requested		March 17, 2009	
Time of Day	2:35 pm]			Evaluatio	n Date	April 2	2, 2009
Outdoor Condi	itions Ter	nperature	83	Relative Humidity	32.1	Ambien	nt CO2	406
Fish	Temperature	Range Relat	ive Humidity	Range	CO2	Rang	ge #	Occupants
P-1215C	66	72 - 78	42.5	30% - 60%	633 M	ax 700 >	Ambien	t 2
Noticeable Od	lor No	-	/isible water age / staining	Visible micro ? growth?	/	nount of ial affect	ed	
Ceiling Type	3 x 15 Pa	nel	No	No			None	
Wall Type	Wood Ver	ieer	No	No		١	None	
Flooring	12 x 12 Vi	nyl	No	No			None	
	Clean	Minor Dust / Debris	Needs Cleaning		Corrective Ac	tion Red	quired	
Ceiling	Yes	No	No					
Walls	Yes	No	No					
Flooring	Yes	No	No					
HVAC Supply	Grills Yes	No	No					
HVAC Return	Grills Yes	No	No					
Ceiling at Sup Grills	ply Yes	No	No					
Surfaces in Ro	oom No	Yes	Yes		Clean as ap	opropria	te	

Observations

Findings:

- Temperature was low at the time of the assessment

- Dust build up on environmental surfaces due to excessive clutter

Recommendations:

Site Based Maintenance:

 Thoroughly clean environmental surfaces throughout the room. Encourage occupant to reduce clutter to assist custodial staff with their cleaning efforts.

- Adjust thermostat to increase temperature

- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate