

managing risk with responsibility

Jeffrey S. Moquin, Director Risk Management Department Telephone: 754-321-3200 Facsimile: 754-321-3290

September 8, 2	008 Signature on File
TO:	Ms. Merceda Stanley, Principal Dillard High School
FROM:	Edward See, Project Manager Risk Management Department
SUBJECT:	Indoor Air Quality (IAQ) Assessment FISH 531, 533, 541, 634, 641, 646 and 647

On August 27, 2008 I conducted an assessment of FISH 531, 533, 541, 634, 641, 646 and 647 at **Dillard High School**. This evaluation included observations of the flooring system, ceiling tiles, false ceiling plenum, environmental surfaces, interior and exterior walls, and the accessible ventilation equipment. Additionally, environmental parameter measurements were taken to include temperature, relative humidity, and carbon dioxide. The detailed findings, along with the recommended corrective action can be found on the attached IAQ Assessment Worksheets.

The IAQ assessment did identify one or more existing conditions impacting IAQ and has generated appropriate recommendations to correct deficiencies in systems and maintenance that could contribute to decreased indoor air quality. At the time of the assessment, these concerns were not an immediate health or safety concern to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Please ensure that your Head Facilities Serviceperson receives a copy of this correspondence so that the recommendations requiring their attention can be addressed. Within two weeks a representative from the Custodial/Grounds Department will conduct a follow-up visit to ensure that all issues have been appropriately addressed.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact me at 754-321-3200.

cc: Dr. Verda Farrow, Area Superintendent Michaelle Pope, Area Director Jeffrey S. Moquin, Director, Risk Management Frank Alfieri, Project Manager, Facilities and Construction Management Charles Ricks, Project Manager, Facilities and Construction Management Dane Ramson, Broward Teachers Union Roy Jarrett, National Federation of Public and Private Employees Mark Dorsett, Manager 1, Physical Plant Operations Division, Zone 1 Roy Norton, Manager Custodial/Grounds, Physical Plant Operations Division Robert Krickovich, Coordinator, LEA, Facilities and Construction Management

ES/tc Enc.

		IAQ As	sessment	Location Number	0371
	Di	llard High School		Evaluation Requested	August 25, 2008
Time of Day				Evaluation Date	August 27, 2008
Outdoor Condition	ns Temperatu	re 88.8	Relative Humidity	73.9 Ambie	ent CO2 380
Fish Tem	perature Range	Relative Humidity	Range	CO2 Rar	nge # Occupants
531	76.6 72 - 78	50.1	30% - 60%	764 Max 700	> Ambient 3
Noticeable Odor	No	Visible water damage / stainin	Visible micro g? growth?	obial Amount of ma affected	terial
Ceiling Type	2 x 4 Lay In	No	No		None
Wall Type	Plaster/Drywall	No	No		None
Flooring	Tile	No	No		None
	/ De	r Dust Needs ebris Cleaning	9	Corrective Action R	equired
Ceiling	Yes	No No			
Walls	Yes	No			
Flooring	Yes	No			
HVAC Supply Gril	lls Yes	No			
HVAC Return Gril	ls Yes	No			
Ceiling at Supply Grills	Yes	No			
Surfaces in Room	Yes	lo No			

Findings:

- Environmental parameters were acceptable

- No signs of water intrusion or microbial growth

Recommendations:

Site Based Maintenance:

- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

			IAQ As	sessment	Location N	Number	0371	
		Dillard Hig	h School		Evaluation	Requested	August	25, 2008
Time of Day					Eva	luation Date	August	27, 2008
Outdoor Condit	tions Terr	perature 8	38.8	Relative Humidity	73.9	Ambie	nt CO2	380
Fish 1	Temperature	Range Rela	tive Humidity	Range	CO2	Rar	nge #	Occupants
533	71 7	2 - 78	52.3	30% - 60%	729	Max 700	> Ambient	2
Noticeable Od	or No		/isible water hage / staining	Visible micro growth?		mount of ma affected	terial	
Ceiling Type	2 x 4 Lay	In	No	No			None	
Wall Type	Plaster/Dry	wall	No	No			None	
Flooring	Tile		No	No			None	
	Clean	Minor Dust / Debris	Needs Cleaning		Correctiv	e Action Re	equired	
Ceiling	Yes	No	No					
Walls	Yes	No	No					
Flooring	Yes	No	No					
HVAC Supply	Grills Yes	No	No					
HVAC Return (Grills Yes	No	No					
Ceiling at Supp Grills	ply Yes	No	No					
Surfaces in Ro	oom Yes	Νο	No					

Findings:

- Temperature was low at the time of assessment

- No signs of water intrusion or microbial growth

Recommendations:

Site Based Maintenance:

- Adjust thermostat to increase temperature

- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

		IAQ As	sessment	Location	Number	0371	
	Dil	ard High School		Evaluation	n Requested	August	25, 2008
Time of Day				Eva	aluation Date	August	27, 2008
Outdoor Conditior	ns Temperatu	e 88.8	Relative Humidity	73.9	Ambie	nt CO2	380
	perature Range	Relative Humidity	Range	CO2	Ran	ge #	Occupants
541	72 - 78		30% - 60%		Max 700	> Ambient	
Noticeable Odor	No	Visible water damage / stainin	Visible micro g? growth?	bial A	Amount of main affected	terial	
Ceiling Type	Concrete	No	No			None	
Wall Type	Concrete	No	No			None	
Flooring	Concrete	No	No			None	
	/ De		9	Correcti	ve Action Re	equired	
Ceiling	Yes	o No					
Walls	Yes	No					
Flooring	Yes	o No					
HVAC Supply Gril	Is Yes	o No					
HVAC Return Gril	Is Yes	o No					
Ceiling at Supply Grills	Yes	o No					
Surfaces in Room	Yes	o No					

Findings: Air Handler Room

- Visible microbial growth on all pipes

- Visible condensation on units

Recommendations:

Site Based Maintenance:

- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

Physical Plant Operations:

- Evaluate cause of condensation on units and microbial growth on pipes and repair as appropriate

			IAQ As	sessment	Location	Number	0371	
		Dillard Hig	h School		Evaluation	Requested	August	25, 2008
Time of Day]			Eva	luation Date	August	27, 2008
Outdoor Cond	litions Te	mperature 8	8.8	Relative Humidity	73.9	Ambie	ent CO2	380
Fish	Temperature	Range Rela	tive Humidity	Range	CO2	Ran	nge #	Occupants
634	69.8	72 - 78	52.6	30% - 60%	629	Max 700	> Ambient	2
Noticeable O	dor No		/isible water age / staining	Visible micr growth		mount of ma affected	terial	
Ceiling Type	2 x 4 Lay	/ In	No	No			None	
Wall Type	Plaster/Dr	ywall	No	Yes		@5 s	square feet	
Flooring	Tile		No	No			None	
	Clean	Minor Dust / Debris	Needs Cleaning		Correctiv	ve Action Re	equired	
Ceiling	Yes	No	No					
Walls	No	Yes	Yes		clean with V	Vexcide disi	nfectant	
Flooring	Yes	No	No					
HVAC Supply	Grills No	Yes	Yes		lean with W	Vexcide disi	nfectant	
HVAC Return	Grills Yes	No	No					
Ceiling at Sup Grills	pply Yes	Νο	No					
Surfaces in R	oom Yes	No	No					

Findings:

- Temperature was low at the time of assessment

- Visible microbial growth on North and East wall - @5 square feet

- Dust and debris on HVAC supply grills

Recommendations:

Site Based Maintenance:

- Adjust thermostat to increase temperature

- Wipe down walls with Wexcide disinfectant solution

- Clean HVAC supply grills with Wexcide disinfectant solution

- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

		L	AQ Assess	sment	Locatio	n Number	0371	
		Dillard High Sch	nool		Evaluation	on Requested	August	25, 2008
Time of Day					E	valuation Date	August	27, 2008
Outdoor Condition	ns Tempera	ture 88.8] Rela	tive Humidity	73.9	Ambie	nt CO2	380
Fish Tem	nperature Rang	e Relative H	lumidity R	ange	CO2	Ran	ge #	Occupants
641	72 - 78	3	30%	60%		Max 700	> Ambien	t
Noticeable Odor	No		e water staining?	Visible micro growth?	obial	Amount of mat affected	terial	
Ceiling Type	Concrete	N	0	No			None	
Wall Type	Concrete	N	0	No			None	
Flooring	Concrete		0	No	[None	
		Debris C	Needs leaning		Correc	tive Action Re	equired	
Ceiling	Yes	Νο	Νο					
Walls	Yes	Νο	No					
Flooring	Yes	No	Νο					
HVAC Supply Gri	lls Yes	Νο	No					
HVAC Return Gril	lls Yes	Νο	No					
Ceiling at Supply Grills	Yes	No	Νο					
Surfaces in Room	Yes	Νο	No					

Findings: Air Handler Room

- Visible microbial growth on all pipes

- Visible condensation on units

Recommendations:

Site Based Maintenance:

- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

Physical Plant Operations:

- Evaluate cause of condensation on units and microbial growth on pipes and repair as appropriate

			IAQ As	sessment	Locatio	n Number	0371	
		Dillard Hi	gh School		Evaluatio	on Requested	August	25, 2008
Time of Day					E	valuation Date	August	27, 2008
Outdoor Cond	itions Terr	perature	88.8	Relative Humidity	73.9	Ambie	nt CO2	380
Fish	Temperature	Range Rela	ative Humidity	Range	CO2	Ran	ge #	Occupants
646	71.1 7	2 - 78	52.6	30% - 60%	633	Max 700	> Ambien	t 2
Noticeable Oc	dor No		Visible water nage / staining	Visible micr g? growth		Amount of mat affected	terial	
Ceiling Type	2 x 4 Lay	In	No	No			None	
Wall Type	Plaster/Dry	wall	No	No			None	
Flooring	Tile		No	No	[None	
	Clean	Minor Dust / Debris	Needs Cleaning		Correc	tive Action Re	equired	
Ceiling	Yes	Νο	No					
Walls	Yes	Νο	No					
Flooring	Yes	Νο	No					
HVAC Supply	Grills Yes	Νο	No					
HVAC Return	Grills No	Yes	Yes		lean with	Wexcide disi	nfectant	
Ceiling at Sup Grills	oply Yes	No	No					
Surfaces in Ro	oom Yes	No	No					

Findings:

- Temperature was low at the time of assessment

- Dust and debris on HVAC return grills

Recommendations:

Site Based Maintenance:

- Adjust thermostat to increase temperature

- Clean HVAC return grills with Wexcide disinfectant solution

- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

			IAQ Ass	sessment	Location Nur	nber	0371	
		Dillard Higl	n School		Evaluation Re	quested	August	25, 2008
Time of Day					Evalua	tion Date	August	27, 2008
Outdoor Cond	litions Terr	nperature 8	8.8	Relative Humidity	73.9	Ambie	nt CO2	380
Fish	Temperature	Range Rela	tive Humidity	Range	CO2	Ran	ge #	Occupants
647	73.4 7	/2 - 78	57.8	30% - 60%	1260	Max 700	> Ambient	46
Noticeable O	dor No		ïsible water age / staining	Visible micro ? growth?	obial Amo	unt of mat affected	erial	
Ceiling Type	2 x 4 Lay	In	No	No			None	
Wall Type	Plaster/Dry	wall	No	Yes		@4 s	quare feet	
Flooring	Tile		No	No			None	
	Clean	Minor Dust / Debris	Needs Cleaning		Corrective A	Action Re	quired	
Ceiling	Yes	No	No					
Walls	No	Yes	Yes	C	lean with Wex	cide disi	nfectant	
Flooring	Yes	No	No					
HVAC Supply	Grills No	Yes	Yes	C	lean with Wex	cide disi	nfectant	
HVAC Return	Grills Yes	No	No					
Ceiling at Sup Grills	oply Yes	No	No					
Surfaces in R	oom Yes	No	No					

Findings:

- Visible microbial growth on South wall @4 square feet
- Dust and debris on HVAC supply grills FISH 647A
- Non-approved chemicals in room (air freshener and incense)

Recommendations:

Site Based Maintenance:

- Wipe down wall with Wexcide disinfectant solution
- Clean HVAC supply grills with Wexcide disinfectant solution FISH 647A
- Remove non-approved chemicals from room
- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate