

Report: PPO

**CHARLES W. FLANAGAN**

Walkthrough Date: 05/01/2006 Temp RH CO2

Outdoor Parameters: 73.8 46.4 899

Room	Priority	Responsible	Answer	Recommendation
001	Inside Parameters:	Temp	RH	CO2
		73.8	46.4	899

2 PPO Gaps in doors identified at the time of assessment. Door for FISH 120. Physical Plant Operations to evaluate and repair as appropriate.

Room	Priority	Responsible	Answer	Recommendation
175	Inside Parameters:	Temp	RH	CO2
		71	48.8	894

1 PPO Signs of water intrusion. Stained ceiling tiles. Physical Plant Operations to evaluate for leaks and repair as appropriate and replace ceiling tiles as appropriate.

Room	Priority	Responsible	Answer	Recommendation
512	Inside Parameters:	Temp	RH	CO2
		72.8	46.4	814

1 PPO Signs of water intrusion. Stained ceiling tiles. Physical Plant Operations to evaluate for leaks and repair as appropriate and replace ceiling tiles as appropriate.

Room	Priority	Responsible	Answer	Recommendation
521	Inside Parameters:	Temp	RH	CO2
		72.3	45.9	922

1 PPO Signs of water intrusion. Stained ceiling tiles. Physical Plant Operations to evaluate for leaks and repair as appropriate and replace ceiling tiles as

appropriate.

Room	Priority	Responsible	Answer	Recommendation
901	Inside Parameters:	Temp	RH	CO2
		73.1	47.3	836

2

PPO

Windows and doors are operable and are kept closed. However, stress crack identified under window on left side.

Physical Plant Operations to evaluate and repair as appropriate.

Room	Priority	Responsible	Answer	Recommendation
927	Inside Parameters:	Temp	RH	CO2
		75.1	45.2	952

3

PPO

Evaluate floor under window at baseboard.

Physical Plant Operations to evaluate and repair as appropriate.