

Aston A. Henry, Supervisor
Risk Management Department

Telephone: 754 321-1900
Fax: 754 321-1917

February 21, 2013

Signature on File

TO: Estella Eckhardt, Principal
Hallandale High School

FROM: Richard Rosa, Project Manager
Facilities Design and Construction

SUBJECT: Indoor Air Quality (IAQ) Assessment

<u>For Custodial Supervisor Use Only</u>	
<input type="checkbox"/>	Custodial Issues Addressed
<input type="checkbox"/>	Custodial Issues Not Addressed
<hr/>	
<hr/>	

On February 7, 2013, I conducted an assessment at **Hallandale High School**. Attached are findings and recommendations for further assessment, remediation, or corrective actions needed.

The IAQ assessment did identify one or more existing conditions impacting IAQ and has generated appropriate work orders to correct deficiencies in systems and maintenance that could contribute to decreased indoor air quality. At the time of the assessment, these concerns were not an immediate health or safety concern to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Please ensure that your Head Facilities Serviceperson receives a copy of this correspondence so that the recommendations requiring their attention can be addressed. In an attempt to separate IAQ issues from general maintenance items, the attached assessment may contain direction for site based staff to generate a work order through COMPASS. Within two weeks a representative from the Custodial/Grounds Department will conduct a follow-up visit to ensure that all site based custodial issues have been appropriately addressed.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact us at 754-321-1907.

cc: Directors, School Performance & Accountability
Shelley Meloni, Executive Director, Facilities Design and Construction
Mark Dorsett, Manager, Zone 1, Physical Plant Operations Division
Roy Norton, Manager, Custodial/Grounds, Physical Plant Operations Division
Aston Henry, Supervisor, Risk Management
Sonja Coley, Senior Project Manager, Facilities Design and Construction
Broward Teachers Union
Federation of Public Employees

RR/tc
Enc.

IAQ Assessment

Hallandale High

Evaluation Date February 7, 2013

Time of Day 1:00

Outdoor Conditions Temperature 79.8

Relative Humidity 60.2

Ambient CO2 426

Fish	Temperature	Range	Relative Humidity	Range	CO ²	Range	# Occupants
600	70.8	72 - 78	65.6	30% - 60%	823	MAX 700 > Ambient	
Noticeable Odor		No	Visible water damage / staining?		Visible microbial growth?		Amount of material affected
Ceiling	2' x 4'		No		No		
Walls	Drywall		No		No		
Floor	12" x 12" Vinyl		No		No		

Ceiling Clean	No	HVAC Supply Grills Clean	No	HVAC Return Grills Clean	No
Walls Clean	Yes	Inside of Supply Duct Clean	No	Inside of Return Duct Clean	No
Flooring Clean	Yes	Ceiling at Supply Grills Clean	No		
Room Surfaces Clean	No				

Trash Removed	Yes	Exhaust Fans Working	N/A	Unapproved Chemicals / Cleaners in Room	No
Signs of Pests	No	Drain Traps Wet	N/A	Air Fresheners in Room	No
Room Cluttered	No	Food if Stored in Room is in Sealed Containers	N/A		

Mechanical Equipment Location	FISH 604	Mechanical Room Clean	Yes
Filters Installed Properly	Yes	Filters Clean	Yes
Condensate Pan Clean	Yes	Cooling Coil Clean	Yes
		Inside of HVAC Unit Clean	Yes

Fresh Air Intake Location	Roof top ▼	Fresh Air Intake Free of Obstruction	Yes
Pollutant Sources Near Air Intake	Ongoing roofing project ▼		

Observations

The filter spacer in the HVAC system is not the proper size. There is a 1" gap allowing unfiltered air to bypass the filter system. Above the drop ceiling is the HVAC return air plenum.

Corrective Actions to be Completed by Site Based Staff

Clean dust from ceiling tiles or replace	▼
Thoroughly clean horizontal surfaces	▼
Clean HVAC supply and return grills with Wexcide	▼
Clean dust from perimeter ceiling grid	▼
	▼
	▼
	▼
	▼

Corrective Actions to be Completed by PPO

Repair HVAC to reduce humidity level	▼
Install appropriate filter spacer in HVAC	▼
Clean HVAC supply drops	▼
	▼
	▼
	▼
	▼

IAQ Assessment

Hallandale High

Evaluation Date

Time of Day

Outdoor Conditions Temperature

Relative Humidity

Ambient CO2

Fish	Temperature	Range	Relative Humidity	Range	CO ²	Range	# Occupants
<input type="text" value="603"/>	<input type="text" value="73.2"/>	<input type="text" value="72 - 78"/>	<input type="text" value="59.8"/>	<input type="text" value="30% - 60%"/>	<input type="text" value="1012"/>	<input type="text" value="MAX 700 > Ambient"/>	<input type="text"/>
Noticeable Odor		<input type="text" value="No"/>	Visible water damage / staining?		Visible microbial growth?		Amount of material affected
Ceiling	<input type="text" value="2' x 4'"/>		<input type="text" value="No"/>		<input type="text" value="No"/>	<input type="text"/>	
Walls	<input type="text" value="Drywall"/>		<input type="text" value="No"/>		<input type="text" value="No"/>	<input type="text"/>	
Floor	<input 12"="" type="text" value="12" vinyl"="" x=""/>		<input type="text" value="No"/>		<input type="text" value="No"/>	<input type="text"/>	
Ceiling Clean	<input type="text" value="No"/>		HVAC Supply Grills Clean	<input type="text" value="No"/>		HVAC Return Grills Clean	<input type="text" value="No"/>
Walls Clean	<input type="text" value="Yes"/>		Inside of Supply Duct Clean	<input type="text" value="No"/>		Inside of Return Duct Clean	<input type="text" value="No"/>
Flooring Clean	<input type="text" value="Yes"/>		Ceiling at Supply Grills Clean	<input type="text" value="No"/>			
Room Surfaces Clean	<input type="text" value="No"/>						
Trash Removed	<input type="text" value="Yes"/>		Exhaust Fans Working	<input type="text" value="N/A"/>		Unapproved Chemicals / Cleaners in Room	<input type="text" value="No"/>
Signs of Pests	<input type="text" value="No"/>		Drain Traps Wet	<input type="text" value="N/A"/>		Air Fresheners in Room	<input type="text" value="No"/>
Room Cluttered	<input type="text" value="No"/>		Food if Stored in Room is in Sealed Containers	<input type="text" value="N/A"/>			
Mechanical Equipment Location	<input type="text" value="FISH 604"/>					Mechanical Room Clean	<input type="text" value="Yes"/>
Filters Installed Properly	<input type="text" value="Yes"/>		Filters Clean	<input type="text" value="Yes"/>		Inside of HVAC Unit Clean	<input type="text" value="Yes"/>
Condensate Pan Clean	<input type="text" value="Yes"/>		Cooling Coil Clean	<input type="text" value="Yes"/>			
Fresh Air Intake Location	<input type="text" value="Roof top"/>					Fresh Air Intake Free of Obstruction	<input type="text" value="Yes"/>
Pollutant Sources Near Air Intake	<input type="text" value="Ongoing roofing project"/>						

Observations

The filter spacer in the HVAC system is not the proper size. There is a 1" gap allowing unfiltered air to bypass the filter system. Above the drop ceiling is the HVAC return air plenum.

Corrective Actions to be Completed by Site Based Staff

Clean dust from ceiling tiles or replace	▼
Thoroughly clean horizontal surfaces	▼
Clean HVAC supply and return grills with Wexcide	▼
Clean dust from perimeter ceiling grid	▼
	▼
	▼
	▼
	▼

Corrective Actions to be Completed by PPO

Repair HVAC to reduce humidity level	▼
Install appropriate filter spacer in HVAC	▼
Clean HVAC supply drops	▼
	▼
	▼
	▼
	▼

IAQ Assessment

Hallandale High

Evaluation Date February 7, 2013

Time of Day 2:00

Outdoor Conditions Temperature 79.8

Relative Humidity 60.2

Ambient CO2 426

Fish	Temperature	Range	Relative Humidity	Range	CO ²	Range	# Occupants
608	72.3	72 - 78	61.9	30% - 60%	894	MAX 700 > Ambient	
Noticeable Odor		No	Visible water damage / staining?		Visible microbial growth?		Amount of material affected
Ceiling	2' x 4'		No	No			
Walls	Drywall		No	No			
Floor	12" x 12" Vinyl		No	No			
Ceiling Clean	No	HVAC Supply Grills Clean	No	HVAC Return Grills Clean	No		
Walls Clean	Yes	Inside of Supply Duct Clean	No	Inside of Return Duct Clean	No		
Flooring Clean	Yes	Ceiling at Supply Grills Clean	No				
Room Surfaces Clean	No						
Trash Removed	Yes	Exhaust Fans Working	N/A	Unapproved Chemicals / Cleaners in Room	No		
Signs of Pests	No	Drain Traps Wet	N/A	Air Fresheners in Room	No		
Room Cluttered	No	Food if Stored in Room is in Sealed Containers	N/A				
Mechanical Equipment Location	FISH 604				Mechanical Room Clean	Yes	
Filters Installed Properly	Yes	Filters Clean	Yes	Inside of HVAC Unit Clean	Yes		
Condensate Pan Clean	Yes	Cooling Coil Clean	Yes				
Fresh Air Intake Location	Roof top ▼				Fresh Air Intake Free of Obstruction	Yes	
Pollutant Sources Near Air Intake	Ongoing roofing project ▼						

Observations

The filter spacer in the HVAC system is not the proper size. There is a 1" gap allowing unfiltered air to bypass the filter system. Above the drop ceiling is the HVAC return air plenum.

Corrective Actions to be Completed by Site Based Staff

Clean dust from ceiling tiles or replace	▼
Thoroughly clean horizontal surfaces	▼
Clean HVAC supply and return grills with Wexcide	▼
Clean dust from perimeter ceiling grid	▼
	▼
	▼
	▼
	▼

Corrective Actions to be Completed by PPO

Repair HVAC to reduce humidity level	▼
Install appropriate filter spacer in HVAC	▼
Clean HVAC supply drops	▼
	▼
	▼
	▼
	▼

IAQ Assessment

Hallandale High

Evaluation Date February 7, 2013

Time of Day 2:15

Outdoor Conditions Temperature 79.8

Relative Humidity 60.2

Ambient CO2 426

Fish	Temperature	Range	Relative Humidity	Range	CO ²	Range	# Occupants
609	72.3	72 - 78	62.3	30% - 60%	883	MAX 700 > Ambient	
Noticeable Odor		No	Visible water damage / staining?		Visible microbial growth?		Amount of material affected
Ceiling	2' x 4'		No		No		
Walls	Drywall		No		No		
Floor	12" x 12" Vinyl		No		No		

Ceiling Clean	No	HVAC Supply Grills Clean	No	HVAC Return Grills Clean	No
Walls Clean	Yes	Inside of Supply Duct Clean	No	Inside of Return Duct Clean	No
Flooring Clean	Yes	Ceiling at Supply Grills Clean	No		
Room Surfaces Clean	No				

Trash Removed	Yes	Exhaust Fans Working	N/A	Unapproved Chemicals / Cleaners in Room	No
Signs of Pests	No	Drain Traps Wet	N/A	Air Fresheners in Room	No
Room Cluttered	No	Food if Stored in Room is in Sealed Containers	N/A		

Mechanical Equipment Location	FISH 604	Mechanical Room Clean	Yes
Filters Installed Properly	Yes	Filters Clean	Yes
Condensate Pan Clean	Yes	Cooling Coil Clean	Yes
		Inside of HVAC Unit Clean	Yes

Fresh Air Intake Location	Roof top ▼	Fresh Air Intake Free of Obstruction	Yes
Pollutant Sources Near Air Intake	Ongoing roofing project ▼		

Observations

The filter spacer in the HVAC system is not the proper size. There is a 1" gap allowing unfiltered air to bypass the filter system. Above the drop ceiling is the HVAC return air plenum.

Corrective Actions to be Completed by Site Based Staff

Clean dust from ceiling tiles or replace	▼
Thoroughly clean horizontal surfaces	▼
Clean HVAC supply and return grills with Wexcide	▼
Clean dust from perimeter ceiling grid	▼
	▼
	▼
	▼
	▼

Corrective Actions to be Completed by PPO

Repair HVAC to reduce humidity level	▼
Install appropriate filter spacer in HVAC	▼
Clean HVAC supply drops	▼
	▼
	▼
	▼
	▼

IAQ Assessment

Hallandale High

Evaluation Date February 7, 2013

Time of Day 2:30

Outdoor Conditions Temperature 79.8

Relative Humidity 60.2

Ambient CO2 426

Fish	Temperature	Range	Relative Humidity	Range	CO ²	Range	# Occupants
610	71.8	72 - 78	62.1	30% - 60%	928	MAX 700 > Ambient	
Noticeable Odor		No	Visible water damage / staining?		Visible microbial growth?		Amount of material affected
Ceiling	2' x 4'		No		No		
Walls	Drywall		No		No		
Floor	12" x 12" Vinyl		No		No		

Ceiling Clean	No	HVAC Supply Grills Clean	No	HVAC Return Grills Clean	No
Walls Clean	Yes	Inside of Supply Duct Clean	No	Inside of Return Duct Clean	No
Flooring Clean	Yes	Ceiling at Supply Grills Clean	No		
Room Surfaces Clean	No				

Trash Removed	Yes	Exhaust Fans Working	N/A	Unapproved Chemicals / Cleaners in Room	No
Signs of Pests	No	Drain Traps Wet	N/A	Air Fresheners in Room	No
Room Cluttered	No	Food if Stored in Room is in Sealed Containers	N/A		

Mechanical Equipment Location	FISH 604		Mechanical Room Clean	Yes	
Filters Installed Properly	Yes	Filters Clean	Yes	Inside of HVAC Unit Clean	Yes
Condensate Pan Clean	Yes	Cooling Coil Clean	Yes		

Fresh Air Intake Location	Roof top ▼	Fresh Air Intake Free of Obstruction	Yes
Pollutant Sources Near Air Intake	Ongoing roofing project ▼		

Observations

The filter spacer in the HVAC system is not the proper size. There is a 1" gap allowing unfiltered air to bypass the filter system. Above the drop ceiling is the HVAC return air plenum.

Corrective Actions to be Completed by Site Based Staff

Clean dust from ceiling tiles or replace	▼
Thoroughly clean horizontal surfaces	▼
Clean HVAC supply and return grills with Wexcide	▼
Clean dust from perimeter ceiling grid	▼
	▼
	▼
	▼
	▼

Corrective Actions to be Completed by PPO

Repair HVAC to reduce humidity level	▼
Install appropriate filter spacer in HVAC	▼
Clean HVAC supply drops	▼
	▼
	▼
	▼
	▼

IAQ Assessment

Hallandale High

Evaluation Date

Time of Day

Outdoor Conditions Temperature

Relative Humidity

Ambient CO2

Fish	Temperature	Range	Relative Humidity	Range	CO ²	Range	# Occupants
<input type="text" value="612"/>	<input type="text" value="71.2"/>	<input type="text" value="72 - 78"/>	<input type="text" value="64.3"/>	<input type="text" value="30% - 60%"/>	<input type="text" value="865"/>	<input type="text" value="MAX 700 > Ambient"/>	<input type="text"/>
Noticeable Odor		<input type="text" value="No"/>	Visible water damage / staining?		Visible microbial growth?		Amount of material affected
Ceiling	<input type="text" value="2' x 4'"/>		<input type="text" value="No"/>		<input type="text" value="No"/>	<input type="text"/>	
Walls	<input type="text" value="Drywall"/>		<input type="text" value="No"/>		<input type="text" value="No"/>	<input type="text"/>	
Floor	<input 12"="" type="text" value="12" vinyl"="" x=""/>		<input type="text" value="No"/>		<input type="text" value="No"/>	<input type="text"/>	
Ceiling Clean		<input type="text" value="No"/>	HVAC Supply Grills Clean		<input type="text" value="No"/>	HVAC Return Grills Clean	
Walls Clean		<input type="text" value="Yes"/>	Inside of Supply Duct Clean		<input type="text" value="No"/>	Inside of Return Duct Clean	
Flooring Clean		<input type="text" value="Yes"/>	Ceiling at Supply Grills Clean		<input type="text" value="No"/>		
Room Surfaces Clean		<input type="text" value="No"/>					
Trash Removed		<input type="text" value="Yes"/>	Exhaust Fans Working		<input type="text" value="N/A"/>	Unapproved Chemicals / Cleaners in Room	
Signs of Pests		<input type="text" value="No"/>	Drain Traps Wet		<input type="text" value="N/A"/>	Air Fresheners in Room	
Room Cluttered		<input type="text" value="No"/>	Food if Stored in Room is in Sealed Containers		<input type="text" value="N/A"/>		
Mechanical Equipment Location			<input type="text" value="FISH 604"/>			Mechanical Room Clean	
Filters Installed Properly		<input type="text" value="Yes"/>	Filters Clean		<input type="text" value="Yes"/>	Inside of HVAC Unit Clean	
Condensate Pan Clean		<input type="text" value="Yes"/>	Cooling Coil Clean		<input type="text" value="Yes"/>		
Fresh Air Intake Location			<input type="text" value="Roof top"/>			Fresh Air Intake Free of Obstruction	
Pollutant Sources Near Air Intake			<input type="text" value="Ongoing roofing project"/>			<input type="text" value="Yes"/>	

Observations

The filter spacer in the HVAC system is not the proper size. There is a 1" gap allowing unfiltered air to bypass the filter system. Above the drop ceiling is the HVAC return air plenum.

Corrective Actions to be Completed by Site Based Staff

Clean dust from ceiling tiles or replace	▼
Thoroughly clean horizontal surfaces	▼
Clean HVAC supply and return grills with Wexcide	▼
Clean dust from perimeter ceiling grid	▼
	▼
	▼
	▼
	▼

Corrective Actions to be Completed by PPO

Repair HVAC to reduce humidity level	▼
Install appropriate filter spacer in HVAC	▼
Clean HVAC supply drops	▼
	▼
	▼
	▼
	▼

IAQ Assessment

Hallandale High

Evaluation Date February 7, 2013

Time of Day 3:15

Outdoor Conditions Temperature 79.8

Relative Humidity 60.2

Ambient CO2 426

Fish	Temperature	Range	Relative Humidity	Range	CO ²	Range	# Occupants
613	72.1	72 - 78	63.7	30% - 60%	832	MAX 700 > Ambient	
Noticeable Odor		No	Visible water damage / staining?		Visible microbial growth?		Amount of material affected
Ceiling	2' x 4'		No		No		
Walls	Drywall		No		No		
Floor	12" x 12" Vinyl		No		No		

Ceiling Clean	No	HVAC Supply Grills Clean	No	HVAC Return Grills Clean	No
Walls Clean	Yes	Inside of Supply Duct Clean	No	Inside of Return Duct Clean	No
Flooring Clean	Yes	Ceiling at Supply Grills Clean	No		
Room Surfaces Clean	No				

Trash Removed	Yes	Exhaust Fans Working	N/A	Unapproved Chemicals / Cleaners in Room	No
Signs of Pests	No	Drain Traps Wet	N/A	Air Fresheners in Room	No
Room Cluttered	No	Food if Stored in Room is in Sealed Containers	N/A		

Mechanical Equipment Location	FISH 604	Mechanical Room Clean	Yes
Filters Installed Properly	Yes	Filters Clean	Yes
Condensate Pan Clean	Yes	Cooling Coil Clean	Yes
		Inside of HVAC Unit Clean	Yes

Fresh Air Intake Location	Roof top ▼	Fresh Air Intake Free of Obstruction	Yes
Pollutant Sources Near Air Intake	Ongoing roofing project ▼		

Observations

The filter spacer in the HVAC system is not the proper size. There is a 1" gap allowing unfiltered air to bypass the filter system. Above the drop ceiling is the HVAC return air plenum.

Corrective Actions to be Completed by Site Based Staff

Clean dust from ceiling tiles or replace	▼
Thoroughly clean horizontal surfaces	▼
Clean HVAC supply and return grills with Wexcide	▼
Clean dust from perimeter ceiling grid	▼
	▼
	▼
	▼
	▼

Corrective Actions to be Completed by PPO

Repair HVAC to reduce humidity level	▼
Install appropriate filter spacer in HVAC	▼
Clean HVAC supply drops	▼
	▼
	▼
	▼
	▼