

Report: PPO

MCARTHUR HIGH

Walkthrough Date: 05/08/2006 Temp RH CO2

Outdoor Parameters: 89.6 45.6 528

Room	Priority	Responsible	Answer	Recommendation
001	Inside Parameters:	Temp	RH	CO2
		78.1	49	795
1		PPO	No leaks identified. Signs of previous water intrusion as evidenced by stains in cabinet.	Physical Plant Operations to evaluate and repair as appropriate.
1		PPO	Noise coming from air handler.	Physical Plant Operations to evaluate and repair as appropriate.
2		PPO	Exhaust fan is not functioning properly. Loud screeching coming from air handler.	Physical Plant Operations to evaluate and repair as appropriate.
Room	Priority	Responsible	Answer	Recommendation
2108	Inside Parameters:	Temp	RH	CO2
		70	55.9	821
1		PPO	No visible condensation at the time of assessment. Signs of previous water intrusion as evidenced by stains on walls. Mold & moisture noted on walls. 2108, 2109, 2110	Physical Plant Operations to evaluate and repair as appropriate.
1		PPO	Signs of water intrusion. Stained ceiling tiles. Mold identified in FISH 2108, 2109 and 2110.	Physical Plant Operations to evaluate for leaks and repair as appropriate and replace ceiling tiles as appropriate.
Room	Priority	Responsible	Answer	Recommendation
806	Inside Parameters:	Temp	RH	CO2
		71.9	58.1	847
1		PPO	Signs of water intrusion. Leak identified.	Physical Plant Operations to evaluate for leaks and repair as appropriate.

Room	Priority	Responsible	Answer	Recommendation
944	Inside Parameters:	Temp 75.7	RH 48.6	CO2 1431
	3	PPO	Windows are not operable. Open doors and windows allow humid untreated air into occupied environment.	Physical Plant Operations to evaluate and repair as appropriate. However site based administration to encourage staff to keep doors and windows closed.