

managing risk with responsibility

Jeffrey S. Moquin, Director Risk Management Department

December 20, 2007 Signature on File

TO: Ms. Deborah Davey, Principal

Miramar High

FROM: Richard Rosa, Project Manager

Facilities and Construction Management

SUBJECT: Indoor Air Quality (IAQ) Assessment

FISH 159, 224 and Office Area

For Custodial Supervisor Use Only								
	Custodial Issues Addressed							
	Custodial Issues Not Addressed							
-								

Telephone: 754-321-3200

Facsimile: 754-321-3290

On November 20, 2007 I conducted an assessment of FISH 159, 224 and Office Area at **Miramar High**. This evaluation included observations of the flooring system, ceiling tiles, false ceiling plenum, environmental surfaces, interior and exterior walls, and the accessible ventilation equipment. Additionally, environmental parameter measurements were taken to include temperature, relative humidity, and carbon dioxide. The detailed findings, along with the recommended corrective action can be found on the attached IAQ Assessment Worksheets.

Generally, the IAQ Assessment did not identify any existing conditions significantly impacting IAQ and thereby presenting immediate health and safety concerns to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Please ensure that your Head Facilities Serviceperson receives a copy of this correspondence so that the recommendations requiring their attention can be addressed. Within two weeks a representative from the Custodial/Grounds Department will conduct a follow-up visit to ensure that all issues have been appropriately addressed.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact me at 754-321-1637.

cc: Dr. Joel Herbst, Area Superintendent

Jacquelyn Box, Area Director

Jeffrey S. Moquin, Director, Risk Management

Rey Olivera, Project Manager, Facilities and Construction Management

Steve Feldman, Broward Teachers Union

Roy Jarrett, Federation of Public Employees

Mark Dorsett, Manager 1, Physical Plant Operations Division, Zone 1

Roy Norton, Manager Custodial/Grounds, Physical Plant Operations Division

RR/tc Enc.

		Mira	mar High S	chool			Evaluati	on Requested	Novem	ber 16, 2007
Time of Day	8:20 8	am					E	valuation Date	Novem	ber 20, 2007
Outdoor Cond	itions	Temperatu	re 76.7		Relative Hur	midity	55.3	Ambie	nt CO2	339
Fish	Temperate	ure Range	Relative	Humidity	Range		CO2	Ran	ige	# Occupant
159	74.5	72 - 78	50	0.8	30% - 60%		732	Max 700	> Ambie	nt 1
Noticeable Odor No				Visible water Visible micro damage / staining? growth?			7 tillouite of mutorius			
Ceiling Type	2 >	c 4 Lay In		No		No		None		
Wall Type		Plaster		No		No		None		
Flooring	12	x 12 Vinyl		No		No	[None	
Ceiling	Cle	/ De	r Dust ebris 'es	Needs Cleaning Yes		Cl		tive Action Re	<u> </u>	
Cennig	<u>L.</u>		<u> </u>	103			can or i	cpiace as app	лорпасс	
Walls	Y	es	No	No						
Flooring	1	No Y	es	Yes			Cle	an and sanitiz	ze	
HVAC Supply	Grills Y	es	No	No						
HVAC Return	Grills Y	es	No	No						
Ceiling at Sup Grills	pply N	No Y	es	Yes		CI	ean or r	replace as app	propriate	
Surfaces in R	oom N	No Y	es	Yes			Clea	ın as appropri	ate	
bservations										
Findings:										

IAQ Assessment

1751

Location Number

- 1 broken ceiling tile
- Dust and debris on ceiling tiles (6) at HVAC supply grills
- Dust and debris in corners on floor
- Dust and debris on environmental surfaces (low and high areas shelving, behind mobile work station, in corners)
- No signs of microbial growth or water intrusion
- Environmental parameters were acceptable at the time of assessment

Recommendations:

Site Based Maintenance:

- Remove and replace broken ceiling tile
- Thoroughly clean or remove and replace ceiling tiles (6) at HVAC supply grills
- Thoroughly clean and sanitize floor, especially corners
- Thoroughly clean all environmental surfaces, especially high and low areas
- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

Time of Day	8:20 am]	<u> </u>		ı	Evaluation Date	Novembe	er 20, 2007
Outdoor Condi	tions Ter	nperature	76.7	Relative Humidi	ty 55.3	Ambie	ent CO2	339
Fish 1	Temperature	Range Rel	ative Humidity	Range	CO2	Ran	nge #	Occupants
224	72.3	72 - 78	50.3	30% - 60%	808	Max 700	> Ambient	6
Noticeable Odor No] da	Visible water Visible microbial damage / staining? growth?			Amount of material affected		
Ceiling Type	Ceiling Type 2 x 4 Lay In		Yes	Yes No		1 ceiling tile		
Wall Type	Plaste	r	No	No		None		
Flooring	12 x 12 Vi	inyl	No	No]		None	
	Clean	Minor Dust / Debris	Needs Cleaning		Corre	ctive Action Re	equired	
Ceiling	Yes	No	No					
Walls	Yes	No	No					
Flooring	Yes	No	No					
HVAC Supply	Grills No	Yes	Yes		Clean wit	h Wexcide dis	infectant	
HVAC Return (Grills No	Yes	Yes		Clean wit	h Wexcide dis	infectant	
Ceiling at Supp Grills	oly No	Yes	Yes		Cle	an as appropri	ate	
Surfaces in Ro	oom No	Yes	Yes		Cle	an as appropri	ate	

IAQ Assessment

Miramar High School

1751

Evaluation Requested November 16, 2007

Location Number

Observations

Findings:

- Dust and debris on HVAC supply and return grills and on ceiling at supply grills. Excessive dust in the return.
- Dust and debris on environmental surfaces (low and high areas shelving, behind mobile work station, in corners)
- No signs of microbial growth or water intrusion
- Environmental parameters were acceptable at the time of assessment
- One stained ceiling tile adjacent to sprinkler drop in West section of teacher planning area

Recommendations:

Site Based Maintenance:

- Clean HVAC supply and return grills with Wexcide disinfectant solution and ceiling at supply grills. Vacuum East air conditioning return.
- Thoroughly clean all environmental surfaces, especially high and low areas
- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

Facilities and Construction Management:

- Sprinkler system should be under warranty. Project Manager to facilitate investigatation of sprinkler system for leaks and initiate repair as appropriate.

Time of Day	8:20 am				I	Evaluation Date November 20, 2007			
Outdoor Condi	tions Tem	nperature	76.7	Relative Humidit	y 55.3	Ambient CO2 339			
<u> </u>	1		ative Humidity	Range	CO2	Range # Occupants			
Office Area	75.3	72 - 78	52.3	30% - 60%	954	Max 700 > Ambient 2			
Noticeable Od	or No		Visible water nage / staining'	Visible mic growth?		Amount of material affected			
Ceiling Type	2 x 4 Lay	In	Yes	No]	1 ceiling tile			
Wall Type	Plaster		No	No]	None			
Flooring	Carpet		No	No]	None			
		<u> </u>			<u>-</u>				
	Clean	Minor Dust / Debris	Needs Cleaning		Corre	ctive Action Required			
Ceiling	No	Yes	Yes		Clean or	replace as appropriate			
Walls	Yes	No	No						
Flooring	No	Yes	Yes		CI	ean and sanitize			
HVAC Supply	Grills Yes	No	No						
HVAC Return	Grills Yes	No	No						
Ceiling at Sup Grills	ply Yes	No	No						
Surfaces in Ro	oom Yes	No	No						
Dbservations									
Findings:									
1 stained ceilingDust and debri									
	crobial growth or	water intrusion	l						
- Environmental				sessment. Air co	nditioning	was down at the time of the			
Recommendati	assessment.								
Site Based Maintenance: - Remove and replace stained ceiling tile									
- Thoroughly clean and sanitize floor									
 Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate 									

IAQ Assessment

Miramar High School

1751

November 16, 2007

Location Number
Evaluation Requested