

# managing risk with responsibility

| Aston A. Henry, Supervisor | Telephone: | 754 321-1900 |
|----------------------------|------------|--------------|
| Risk Management Department | Fax:       | 754 321-1917 |
|                            |            |              |

January 26, 2012 Signature on File

TO: Jonathan Williams, Principal

**Northeast High School** 

FROM: Robert Krickovich, Coordinator, LEA

Facilities and Construction Management

SUBJECT: Indoor Air Quality (IAQ) Assessment

| For Custodial Supervisor Use Only |                                |  |  |  |  |  |  |
|-----------------------------------|--------------------------------|--|--|--|--|--|--|
|                                   | Custodial Issues Addressed     |  |  |  |  |  |  |
|                                   | Custodial Issues Not Addressed |  |  |  |  |  |  |
| -                                 |                                |  |  |  |  |  |  |
| -                                 | -                              |  |  |  |  |  |  |

On October 6, 2011 I conducted an assessment at Northeast High School. Attached are findings and recommendations for further assessment, remediation, or corrective actions needed.

The IAQ assessment did identify one or more existing conditions impacting IAQ and has generated appropriate work orders to correct deficiencies in systems and maintenance that could contribute to decreased indoor air quality. At the time of the assessment, these concerns were not an immediate health or safety concern to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Please ensure that your Head Facilities Serviceperson receives a copy of this correspondence so that the recommendations requiring their attention can be addressed. In an attempt to separate IAQ issues from general maintenance items, the attached assessment may contain direction for site based staff to generate a work order through COMPASS. Within two weeks a representative from the Custodial/Grounds Department will conduct a follow-up visit to ensure that all issues have been appropriately addressed.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact us at 754-321-1907.

Area Superintendent cc:

Area Directors

Shelley Meloni, Executive Director, Facilities and Construction Management Mark Dorsett, Acting Director, Physical Plant Operations Division, Maintenance Sonja Coley, Project Manager III, Facilities and Construction Management Roy Norton, Manager Custodial/Grounds, Physical Plant Operations Division Aston Henry, Supervisor, Risk Management Broward Teachers Union

Federation of Public Employees

RK/tc Enc.

|                          |                         | Northeas          | t High School                      |                             | Evaluati       | on Requested            | Septembe             | er 21, 2011 |
|--------------------------|-------------------------|-------------------|------------------------------------|-----------------------------|----------------|-------------------------|----------------------|-------------|
| Time of Day              | 1:00 PM                 |                   |                                    |                             | E              | valuation Date          | October              | · 6, 2011   |
| Outdoor Condi            | tions                   | Temperature       | 85.1                               | Relative Humidity           | 51.6           | Ambie                   | nt CO2               | 445         |
| Fish 121                 | <b>Temperature</b> 66.9 | Range<br>72 - 78  | Relative Humidity<br>58.2          | Range<br>30% - 60%          | <b>CO2</b> 730 | Ran<br>Max 700          | nge # 0<br>> Ambient | Occupants 2 |
| Noticeable Od            | or No                   |                   | Visible water<br>damage / staining | Visible micro<br>g? growth? |                | Amount o material affec | ted                  |             |
| Ceiling Type             | 2 x 4 l                 | ∟ay In            | Yes                                | Yes                         | l              |                         | 1 tile               |             |
| Wall Type                | Pla                     | ster              | No                                 | No                          | [              |                         | None                 |             |
| Flooring                 | 12 x 12                 | 2 Vinyl           | No                                 | No                          |                |                         | None                 |             |
|                          | Clean                   | Minor D<br>/ Debr |                                    | l                           | Correc         | tive Action Re          | equired              |             |
| Ceiling                  | No                      | Yes               | Yes                                |                             | Clea           | n as appropri           | ate                  |             |
| Walls                    | No                      | Yes               | Yes                                |                             | Clea           | ın as appropri          | ate                  |             |
| Flooring                 | Yes                     | No                | No                                 |                             |                |                         |                      |             |
| HVAC Supply              | Grills No               | Yes               | Yes                                |                             | Cle            | an with Wexci           | de                   |             |
| HVAC Return              | Grills No               | Yes               | Yes                                |                             | Cle            | an with Wexci           | de                   |             |
| Ceiling at Sup<br>Grills | ply No                  | Yes               | Yes                                |                             | Clea           | ın as appropri          | ate                  |             |
| Surfaces in Ro           | oom No                  | Yes               | Yes                                |                             | Clea           | ın as appropri          | ate                  |             |

1241

**Location Number** 

## **Observations**

## Findings

- Temperature was low at the time of the assessment
- Dust build up on walls, ceiling and surfaces throughout the room
- Heavy dust build up on HVAC supply and return grills.
- Visible microbial growth on ceiling tile at emergency light

## Site Based Maintenance:

- Thoroughly clean walls, ceiling and all surfaces throughout the room
- Clean HVAC supply and return grills with Wexcide disinfectant solution
- Contact COMPASS to generate a work order to remove and replace ceiling tile at emergency light
- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

## Physical Plant Operations:

- Evaluate HVAC system for proper operation and repair as appropriate to increase temperature
- NOTE: Work order EQ02168 generated 10/17/2011 to address HVAC system

|   |             |               | IAQ As                             | sessment       | Locatio            | on Number               | 1241               |
|---|-------------|---------------|------------------------------------|----------------|--------------------|-------------------------|--------------------|
|   |             | Northeas      | t High School                      |                | Evaluati           | ion Requested           | September 21, 2011 |
| Time of Day   | 1:00 PM     |               |                                    |                | E                  | Evaluation Date         | October 6, 2011    |
| Outdoor Condition   | s T         | emperature    | 85.1                               | Relative Hur   | midity 51.6        | Ambie                   | nt CO2 445         |
| Fish Tem  | perature    | Range         | Relative Humidity                  | Range          | CO2                | Rar                     | nge # Occupants    |
| 145   | 72.1        | 72 - 78       | 41.5                               | 30% - 60%      | 914                | Max 700                 | > Ambient 2        |
| Noticeable Odor   | No          |               | Visible water<br>damage / staining |                | microbial<br>owth? | Amount o material affec | cted               |
| Ceiling Type  | 2 x 4 L     | ay In         | Yes                                |                | No                 |                         | 2 tiles            |
| Wall Type   | Plas        | ter           | Yes                                |                | No                 | \                       | /arious            |
| Flooring  | 12 x 12     | Vinyl         | No                                 |                | No                 |                         | None               |
|   | Clean       | Minor D       |                                    |                | Correc             | ctive Action Re         | equired            |
| Ceiling   | Yes         | No            | No                                 |                |                    |                         |                    |
| Walls   | No          | Yes           | Yes                                |                | Clea               | an as appropri          | ate                |
| Flooring  | Yes         | No            | No                                 |                |                    |                         |                    |
| HVAC Supply Gril  | Is Yes      | No            | No                                 |                |                    |                         |                    |
| HVAC Return Gril  | ls Yes      | No            | No                                 |                |                    |                         |                    |
| Ceiling at Supply<br>Grills   | No          | Yes           | Yes                                |                | Remove a           | ind replace ce          | iling tiles        |
| Surfaces in Room  | No          | Yes           | Yes                                |                | Clea               | an as appropri          | ate                |
| bservations   |             |               |                                    |                |                    |                         |                    |
| Findings - Fan on roof makin - All sinks (10) dry a - Heavy dust build u  | and floor d | rain at eye w |                                    |                | appropriate.       |                         |                    |
| Site Based Maintenance: - Ensure water is run down all drains at least once a week Thoroughly clean all surfaces throughout the room and walls in corridor - Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate |             |               |                                    |                |                    |                         |                    |
| Physical Plant Operations: - Evaluate fan on roof and repair as appropriate to alleviate noise  |             |               |                                    |                |                    |                         |                    |
| - NOTE: Work ord  | er EQ021    | 67 generate   | d 10/17/2011 to a                  | ddress roof fa | an                 |                         |                    |
|   |             |               |                                    |                |                    |                         |                    |
|   |             |               |                                    |                |                    |                         |                    |
|   |             |               |                                    |                |                    |                         |                    |

|                          |           | Northeast Hig          | h School                         |                         | Evaluat | ion Requested            | September 21, 2011 |
|--------------------------|-----------|------------------------|----------------------------------|-------------------------|---------|--------------------------|--------------------|
| Time of Day              | 1:00 PM   |                        |                                  |                         | E       | Evaluation Date          | October 6, 2011    |
| Outdoor Condi            | tions Tem | perature               | 85.1                             | Relative Humidit        | ty 51.6 | S Ambie                  | nt CO2 445         |
|                          |           | Range Rela             | tive Humidity                    | Range                   | CO2     | Ran                      |                    |
| 212                      | 68.9      | 2 - 78                 | 51.4                             | 30% - 60%               | 805     | Max 700                  | > Ambient 2        |
| Noticeable Od            | lor Yes   |                        | Visible water<br>nage / staining | Visible mic<br>? growth |         | Amount o material affect |                    |
| Ceiling Type             | Open Tect | um                     | No                               | No                      | ]       |                          | None               |
| Wall Type                | Plaster   |                        | No                               | No                      | ]       |                          | None               |
| Flooring                 | Carpet    |                        | No                               | No                      | ]       |                          | None               |
|                          | Clean     | Minor Dust<br>/ Debris | Needs<br>Cleaning                |                         | Correc  | ctive Action Re          | equired            |
| Ceiling                  |           |                        |                                  |                         |         | N/A                      |                    |
| Walls                    | No        | Yes                    | Yes                              |                         | Clea    | an as appropri           | ate                |
| Flooring                 | Yes       | No                     | No                               |                         |         |                          |                    |
| HVAC Supply              | Grills No | Yes                    | Yes                              |                         | Cle     | ean with Wexci           | ide                |
| HVAC Return              | Grills No | Yes                    | Yes                              |                         | Cle     | ean with Wexci           | ide                |
| Ceiling at Sup<br>Grills | ply       |                        |                                  |                         |         | N/A                      |                    |
| Surfaces in Ro           | oom No    | Yes                    | Yes                              |                         | Clea    | an as appropri           | ate                |

1241

**Location Number** 

## **Observations**

## Findings

- Temperature was low at the time of the assessment
- Dust build up on walls, ceiling and surfaces throughout the room
- Heavy dust build up on HVAC supply and return grills.
- FISH 212C, 212J, 212K, 212L and 212N Visible microbial growth on walls and ceilings. Two dehumidifiers were not running in 212N due to full pans.

#### Site Based Maintenance:

- Thoroughly clean walls, ceiling and all surfaces throughout the room
- Clean HVAC supply and return grills with Wexcide disinfectant solution
- Clean walls and ceilings in FISH 212C, 212J, 212K, 212L and 212N and ensure dehumidifier pans are emptied regularly.
- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

## Physical Plant Operations:

- Evaluate HVAC system for proper operation and repair as appropriate to increase temperature
- NOTE: Work order EQ02168 generated 10/17/2011 to address HVAC system

|  |                                    | Northeast High         | n School   |              | Evaluati                               | on Requested [   | September | 21, 2011 |
|--|------------------------------------|------------------------|--|--------------|--|------------------|-----------|----------|
| Time of Day                                      | 1:00 PM                            |                        |  |              | E                                      | valuation Date   | October 6 | 5, 2011  |
| Outdoor Condi                                    | tions Tem                          | perature 8             | 5.1 F  | Relative Hum | nidity 51.6                            | Ambien           | t CO2     | 145      |
| Fish 7 276  Noticeable Od Ceiling Type Wall Type | 73.1 7.  or No  2 x 4 Lay  Plaster | 2 - 78 V dam           | ive Humidity 63.2  (isible water age / staining?  No  No | gro          | CO2<br>827<br>microbial<br>owth?<br>lo |                  | - Ambient | 4        |
| Flooring   | 12 x 12 Vin                        | yl                     | No   | N            | lo                                     |                  | None      |          |
|  | Clean                              | Minor Dust<br>/ Debris | Needs<br>Cleaning  |              | Correc                                 | ctive Action Rec | quired    |          |
| Ceiling  | Yes                                | No                     | No   |              |  |                  |           |          |
| Walls  | No                                 | Yes                    | Yes  |              | Clea                                   | an as appropria  | te        |          |
| Flooring   | Yes                                | No                     | No   |              |  |                  |           |          |
| HVAC Supply                                      | Grills Yes                         | No                     | No   |              |  |                  |           |          |
| HVAC Return (                                    | Grills No                          | Yes                    | Yes  |              | Cle                                    | an with Wexcid   | le        |          |
| Ceiling at Sup<br>Grills                         | ply No                             | Yes                    | Yes  |              | Clea                                   | an as appropria  | te        |          |
| Surfaces in Ro                                   | om No                              | Yes                    | Yes  |              | Clea                                   | an as appropria  | te        |          |
| hearvations                                      |                                    |                        |  |              |  |                  |           |          |

1241

**Location Number** 

# Observations

# Findings

- Dust build up on walls and surfaces throughout the room
- Dust build up on HVAC return grills and ceiling at supply grills
- Yellow spotty staining on corner bookcase
- Humidity level was slightly elevated at the time of the assessment

## Site Based Maintenance:

- Thoroughly clean walls and all surfaces throughout the room
- Clean HVAC return grills with Wexcide disinfectant solution and clean ceiling at supply grills
- Clean bookcase as appropriate
- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

# Physical Plant Operations:

- Evaluate HVAC system for proper operation and repair as appropriate to lower humidity
- NOTE: Work order EQ02168 generated 10/17/2011 to address HVAC system

1241 **IAQ Assessment Location Number Evaluation Requested** September 21, 2011 Northeast High School **Evaluation Date** October 6, 2011 Time of Day 1:00 PM **Outdoor Conditions Temperature** 85.1 **Relative Humidity** 51.6 **Ambient CO2** 445 **Temperature Fish** CO<sub>2</sub> Range **Relative Humidity** # Occupants Range Range 287 71.2 59.6 882 72 - 78 2 30% - 60% Max 700 > Ambient Visible water Visible microbial **Amount of Noticeable Odor** No damage / staining? growth? material affected 2 x 4 Lay In None **Ceiling Type** No No **Wall Type Plaster** None No No 12 x 12 Vinyl **Flooring** None No No Needs Clean **Minor Dust Corrective Action Required** Cleaning / Debris Yes No No Ceiling Yes No No Walls Yes No Yes **Flooring** Clean as appropriate **HVAC Supply Grills** No Yes Clean with Wexcide Yes **HVAC Return Grills** No Yes Yes Clean with Wexcide **Ceiling at Supply** No Yes Yes Clean as appropriate **Grills Surfaces in Room** No Yes Yes Clean as appropriate **Observations** Findings Dust build up on floor and surfaces throughout the room Dust build up on HVAC supply and return grills. Site Based Maintenance: - Thoroughly clean floor and all surfaces throughout the room Clean HVAC supply and return grills with Wexcide disinfectant solution Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

|                           |             | r ter areast r ng.     |                                   |              |                                  | · .                      | •         |             |
|---------------------------|-------------|------------------------|-----------------------------------|--------------|----------------------------------|--------------------------|-----------|-------------|
| Time of Day               | 1:00 PM     |                        |                                   |              | E                                | Evaluation Date          | October   | 6, 2011     |
| Outdoor Conditi           | ions Ten    | nperature 8            | <b>35.1</b>                       | Relative Hum | idity 51.6                       | S Ambier                 | nt CO2    | 445         |
| 308 Noticeable Odd        | 67.5        | 2 - 78 dam             | 52.6 /isible water age / staining | ? gro        | CO2<br>604<br>microbial<br>owth? | Amount of material affec | > Ambient | Occupants 2 |
| Ceiling Type L            | Plaster     |                        | Yes                               |              | lo l                             |                          | None      |             |
| Flooring                  | 12 x 12 Vir |                        | No                                | _            | <u> </u>                         |                          |           |             |
| Flooring L                | 12 X 12 VII | ıyı                    | No                                |              | lo                               |                          | None      |             |
|                           | Clean       | Minor Dust<br>/ Debris | Needs<br>Cleaning                 |              | Correc                           | ctive Action Re          | quired    |             |
| Ceiling                   | No          | Yes                    | Yes                               |              | Clea                             | an as appropria          | ate       |             |
| Walls                     | No          | Yes                    | Yes                               |              | Clea                             | an as appropria          | ate       |             |
| Flooring                  | Yes         | No                     | No                                |              |                                  |                          |           |             |
| HVAC Supply G             | Grills Yes  | No                     | No                                |              |                                  |                          |           |             |
| HVAC Return G             | Grills Yes  | No                     | No                                |              |                                  |                          |           |             |
| Ceiling at Supp<br>Grills | No No       | Yes                    | Yes                               |              | Clea                             | an as appropria          | ate       |             |
| Surfaces in Roc           | om No       | Yes                    | Yes                               |              | Clea                             | an as appropria          | ate       |             |

Northeast High School

1241

Evaluation Requested | September 21, 2011 |

**Location Number** 

## **Observations**

## Findings

- Temperature was low at the time of the assessment
- Visible microbial growth on computer desks and wall surfaces.
- Stained ceiling tiles in FISH 308 and 308A
- Paint on wall surfaces is blistered and peeling
- Hallway has heavy condensation dripping from ceiling and metal access covers. Water stains on walls and concrete floor. Possible air leak above ceiling.

## Site Based Maintenance:

- · Continue to wipe down walls, ceiling and all surfaces throughout the room
- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

# Physical Plant Operations:

- Evaluate HVAC system for proper operation and repair as appropriate to increase temperature
- Evaluate for cause of stained ceiling tiles (roof leak?) and repair as appropriate. Remove and replace ceiling tiles as necessary
- Evaluate HVAC controls to ensure shut down with unit
- Evaluate for cause of condensation on plaster ceiling corridor outside of FISH 308 and repair as appropriate
- Once cause of condensation and water intrusion is identified and repaired, paint rooms with anti-microbial paint

NOTE: Work orders EQ01846-1848 generated 9/2/2011 (from previous assessment 8/30/11)