

Aston A. Henry, Supervisor **Risk Management Department**

managing risk with responsibility

754 321-1900 Telephone: Fax:

754 321-1917

September 14, 2	009 Signature on File
TO:	Mr. John LaCasse, Principal Nova High School
FROM:	Robert Krickovich, Coordinator, LEA Facilities and Construction Management
SUBJECT:	Indoor Air Quality (IAQ) Assessment FISH 192, 192A and 192B

Custodial Issues Addressed
Custodial Issues Not Addressed
Custodial issues i vot Addressed

On August 21, 2009 I conducted an assessment of FISH 192, 192A and 192B at Nova High School. This evaluation included observations of the flooring system, ceiling tiles, false ceiling plenum, environmental surfaces, interior and exterior walls, and the accessible ventilation equipment. Additionally, environmental parameter measurements were taken to include temperature, relative humidity, and carbon dioxide. The detailed findings, along with the recommended corrective action can be found on the attached IAQ Assessment Worksheets.

The IAQ assessment did identify one or more existing conditions impacting IAQ and has generated appropriate work orders to correct deficiencies in systems and maintenance that could contribute to decreased indoor air quality. At the time of the assessment, these concerns were not an immediate health or safety concern to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Please ensure that your Head Facilities Serviceperson receives a copy of this correspondence so that the recommendations requiring their attention can be addressed. In an attempt to separate IAQ issues from general maintenance items, the attached assessment may contain direction for site based staff to generate a work order through COMPASS. Within two weeks a representative from the Custodial/Grounds Department will conduct a follow-up visit to ensure that all issues have been appropriately addressed.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact me at 754-321-1638.

cc: Dr. Joel Herbst, Area Superintendent Steven Friedman, Area Director Jeffrey S. Moquin, Executive Director, Support Operations Aston Henry, Supervisor, Risk Management Scott Gillen, Project Manager, Facilities and Construction Management Diane Watts, Broward Teachers Union Roy Jarrett, Federation of Public Employees Mark Dorsett, Manager 1, Physical Plant Operations Division, Zone 1 Roy Norton, Manager Custodial/Grounds, Physical Plant Operations Division

RK/tc Enc.

			IAQ Ass	sessment	Location Number	1281
		Nova High	n School		Evaluation Requested	August 20, 2009
Time of Day	9:35 a.m.				Evaluation Date	August 21, 2009
Outdoor Condi	itions Ten	nperature 8	9.7	Relative Humidity	67.3 Ambie	ent CO2 471
Fish	Temperature	Range Relat	ive Humidity	Range	CO2 Ran	nge # Occupants
192	70.6 7	2 - 78	72.8	30% - 60%	426 Max 700	> Ambient 2
Noticeable Od	lor No		'isible water age / staining	Visible micro ? growth?	bial Amount o material affec	
Ceiling Type	Plaster		No	No		None
Wall Type	Plaster		No	No		None
Flooring	Carpet		Yes	No		Various
	Clean	Minor Dust / Debris	Needs Cleaning		Corrective Action Re	equired
Ceiling	Yes	Νο	No			
Walls	Yes	No	No			
Flooring	No	Yes	Yes		Clean and sanitiz	ze
HVAC Supply	Grills Yes	Νο	No			
HVAC Return	Grills No	Yes	Yes	CI	ean with Wexcide dis	infectant
Ceiling at Sup Grills	ply Yes	No	No			
Surfaces in Ro	oom No	Yes	Yes		Clean as appropri	ate

Observations

Findings:

- Visible microbial growth on 2'x2'x1' homemade wooden podium - advised to discard at the time of the assessment

- Carpet severely stained from tape, spills, etc.
- Dust build up on environmental surfaces
- Dust and debris on HVAC return grills
- Temperature was low and humidity level was elevated at the time of the assessment

Recommendations:

Site Based Maintenance:

- Discard wooden podium

- Thoroughly clean and sanitize carpet. Do not use tape on carpet and refrain from eating or drinking in carpeted rooms.

- Clean environmental surfaces as appropriate
- Clean HVAC return grills with Wexcide disinfectant solution

- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

Physical Plant Operations:

- Evaluate HVAC system for proper operation and repair as appropriate to increase temperature and lower humidity.

			IAQ As	sessment	Location Number	1281
		Nova High	n School		Evaluation Requested	August 20, 2009
Time of Day	9:35 a.m.				Evaluation Date	August 21, 2009
Outdoor Condi	itions Ten	nperature 8	9.7	Relative Humidity	67.3 Ambi	ent CO2 471
Fish	Temperature	Range Relat	ive Humidity	Range	CO2 Ra	inge # Occupants
192A	70.5	/2 - 78	71.6	30% - 60%	434 Max 70	0 > Ambient 2
Noticeable Od	lor No	-	'isible water age / staining	Visible micro ? growth?	/ une une	
Ceiling Type	Plaster		No	No		None
Wall Type	Plaster		No	No		None
Flooring	Carpet		Yes	No		Various
	Clean	Minor Dust / Debris	Needs Cleaning		Corrective Action F	Required
Ceiling	Yes	No	No			
Walls	No	Yes	Yes		Clean as approp	riate
Flooring	No	Yes	Yes		PPO to replace ca	arpet
HVAC Supply	Grills Yes	No	No			
HVAC Return	Grills No	Yes	Yes	C	lean with Wexcide di	sinfectant
Ceiling at Sup Grills	ply Yes	No	No			
Surfaces in Ro	oom No	Yes	Yes		Clean as approp	riate

Observations

Findings:

- Cob webs and dust on walls. Excessive dust on open storage cabinets. Walls stained - tape marks, tape pieces, poster glue, gum, etc. Hole in wall - appears to have been pushed in or kicked.

- Carpet is old, buckled, rippled and severely stained. J work order generated by site to replace carpet.

- Dust build up on environmental surfaces
- Dust and debris on HVAC return grills
- Temperature was low and humidity level was elevated at the time of the assessment
- Gap over door at ceiling allowing dust and air intrusion

Recommendations:

Site Based Maintenance:

- Thoroughly clean walls to remove dust, stains, etc.
- Contact COMPASS to generate a work order to repair hole in wall
- Work order generated by site to replace carpet
- Thoroughly clean environmental surfaces as appropriate
- Clean HVAC return grills with Wexcide disinfectant solution

- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

Physical Plant Operations:

- Evaluate HVAC system for proper operation and repair as appropriate to increase temperature and lower humidity.

- Evaluate gap over door at ceiling and repair as appropriate to prevent air and dust intrusion

			IAQ Ass	sessment	Location Number	1281
		Nova Higl	n School		Evaluation Requested	August 20, 2009
Time of Day	9:35 a.m.]			Evaluation Date	August 21, 2009
Outdoor Condi	itions Te	mperature 8	9.7	Relative Humidity	67.3 Ambie	ent CO2 471
Fish	Temperature	Range Relat	ive Humidity	Range	CO2 Rai	nge # Occupants
192B	70	72 - 78	74.1	30% - 60%	447 Max 700	> Ambient 2
Noticeable Od	lor No	-	/isible water age / staining?	Visible micro ? growth?	bial Amount o material affe	
Ceiling Type	Plaste	r	No	No		None
Wall Type	Plaste	r	No	No		None
Flooring	Carpe	t	Yes	No		Various
	Clean	Minor Dust / Debris	Needs Cleaning		Corrective Action R	equired
Ceiling	No	Yes	Yes		Clean as appropr	iate
Walls	No	Yes	Yes		Clean as appropr	iate
Flooring	No	Yes	Yes		PPO to replace ca	rpet
HVAC Supply	Grills Yes	No	No			
HVAC Return	Grills No	Yes	Yes	CI	ean with Wexcide dis	infectant
Ceiling at Sup Grills	ply Yes	No	No			
Surfaces in Ro	oom No	Yes	Yes		Clean as appropr	iate

Observations Findings:

- Cob webs and dust on walls. Excessive dust on open storage cabinets. Walls stained - tape marks, tape pieces, poster glue, gum, etc.

- Carpet is old, buckled, rippled and severely stained. J work order generated by site to replace carpet.

- Dust build up on environmental surfaces
- Dust and debris on HVAC return grills
- Temperature was low and humidity level was elevated at the time of the assessment
- Light fixtures hanging loose from ceiling allowing dust and air intrusion

Recommendations:

Site Based Maintenance:

- Thoroughly clean walls to remove dust, stains, etc.
- Work order generated by site to replace carpet
- Thoroughly clean environmental surfaces as appropriate

- Clean HVAC return grills with Wexcide disinfectant solution

- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

Physical Plant Operations:

- Evaluate HVAC system for proper operation and repair as appropriate to increase temperature and lower humidity

- Evaluate light fixtures and repair as appropriate to secure tight to ceiling to prevent dust and air intrusion