

November 21, 2007

# managing risk with responsibility

Telephone: 754-321-3200

Jeffrey S. Moquin, Director Risk Management Department

Facsimile: 754-321-3290

TO: Mr. Alan Strauss, Principal

**South Broward High School** 

Signature on File

FROM: Edward See, Project Manager

Risk Management Department

SUBJECT: Indoor Air Quality (IAQ) Assessment

FISH 308, 310 and 621

<u>Fo</u>	or Custodial Supervisor Use Only
	Custodial Issues Addressed
	Custodial Issues Not Addressed
-	

On September 28, 2007 I conducted an assessment of FISH 308, 310 and 621 at **South Broward High School**. This evaluation included observations of the flooring system, ceiling tiles, false ceiling plenum, environmental surfaces, interior and exterior walls, and the accessible ventilation equipment. Additionally, environmental parameter measurements were taken to include temperature, relative humidity, and carbon dioxide. The detailed findings, along with the recommended corrective action can be found on the attached IAQ Assessment Worksheets.

The IAQ assessment did identify one or more existing conditions impacting IAQ and has generated appropriate work orders to correct deficiencies in systems and maintenance that could contribute to decreased indoor air quality. At the time of the assessment, these concerns were not an immediate health or safety concern to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Please ensure that your Head Facilities Serviceperson receives a copy of this correspondence so that the recommendations requiring their attention can be addressed. Within two weeks a representative from the Custodial/Grounds Department will conduct a follow-up visit to ensure that all issues have been appropriately addressed.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact me at 754-321-3200.

cc: Dr. Joel Herbst, Area Superintendent

Valerie Wanza, Area Director

Jeffrey S. Moquin, Director, Risk Management

Bob Sharps, Project Manager, Facilities and Construction Management

Jamie Daniels, Broward Teachers Union

Roy Jarrett, Federation of Public Employees

Mark Dorsett, Manager 1, Physical Plant Operations Division, Zone 1

Roy Norton, Manager Custodial/Grounds, Physical Plant Operations Division

Robert Krickovich, Coordinator, LEA, Facilities and Construction Management

ES/tc Enc.

South Broward High School				d High School		on Requested	Septembe	er 17, 2007	
Time of Day 1:30 pm					E	valuation Date	Septembe	er 28, 2007	
Outdoor Cond	itions	Te	emperature	89	Relative Humidity	55.9	Ambie	nt CO2	433
	Tempe		Range	Relative Humidity	Range	CO2	Ran	ge #	Occupants
308	71	1.8	72 - 78	71.1	30% - 60%	640	Max 700	> Ambient	2
Noticeable Oc	dor	Yes		Visible water damage / staining	Visible micro g? growth?		Amount of mat affected	erial	
Ceiling Type	\	Wood Pa	anels	No	No	[		None	
Wall Type		Wood		Yes	Yes		Sporadic on all walls		lls
Flooring		Concre	ete	No	No	[		None	
	(	Clean	Minor D / Debr		l	Correc	tive Action Re	quired	
Ceiling		Yes	No	No					
Walls		No	Yes	Yes	С	lean with	n Wexcide disi	nfectant	
Flooring		Yes	No	No					
HVAC Supply	Grills	Yes	No	No					
HVAC Return	Grills	Yes	No	No					
Ceiling at Sup Grills	ply	Yes	No	No					
Surfaces in Re	oom	No	Yes	Yes		Clea	ın as appropria	ate	

IAQ Assessment

0171

**Evaluation Requested** September 17, 2007

**Location Number** 

#### **Observations**

## Findings: (wood shop)

- Musty odor in room
- Temperature was low and humidity level was elevated
- Visible microbial growth and staining on all 4 walls
- Visible microbial growth on chilled water lines
- Dust build up on environmental surfaces
- FISH 307 (AHU room) drain pan and coils were clean

## Recommendations:

#### Site Based Maintenance:

- Wipe down walls and chilled water lines with Wexcide disinfectant solution
- Clean environmental surfaces
- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

### Physical Plant Operations

- Evaluate HVAC for proper operation and repair as appropriate to increase temperature and lower humidity and CO2 level.
- Evaluate cause of staining on walls and growth on walls and chilled water lines

NOTE: EQ01070 Generated to address Physical Plant Operations recommendations

Time of Day	1:30 pm				Ev	aluation Date September 28, 2007			
Outdoor Condit	ions Tei	mperature	89 R	Relative Humidity	55.9	Ambient CO2 433			
Fish T	emperature	Range Rela	tive Humidity	Range	CO2	Range # Occupants			
310	74	72 - 78	66.9	30% - 60%	901	Max 700 > Ambient 26			
Noticeable Odd		dan dan	/isible water nage / staining?	Visible micro growth?		Amount of material affected			
Ceiling Type	2 x 4 Lay	/ In	No	No		None			
Wall Type	Drywa	II	No	No		None			
Flooring	12 x 12 V	inyl	No	No		None			
	Clean	Minor Dust / Debris	Needs Cleaning		Correct	ive Action Required			
Ceiling	Yes	No	No						
Walls	Yes	No	No						
Flooring	Yes	No	No						
HVAC Supply (	Grills Yes	No	No						
HVAC Return G		Yes	Yes	С	lean with	Wexcide disinfectant			
Ceiling at Supp Grills	oly Yes	No	No						
Surfaces in Ro	om Yes	No	No						
L Observations									
Findings: - Musty odor in room - Humidity level was slightly elevated - Dust and debris on HVAC return grills									
Recommendation	Recommendations:								
Site Based Maintenance: - Clean HVAC return grills with Wexcide disinfectant solution - Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate									
Physical Plant Operations - Evaluate HVAC for proper operation and repair as appropriate to increase temperature and lower humidity and CO2 level.									
NOTE: EQ01070 Generated to address Physical Plant Operations recommendations									
I									

**IAQ Assessment** 

South Broward High School

0171

September 17, 2007

**Location Number** 

**Evaluation Requested** 

	Sou	th Broward Hig	n School		⊏vaiuat	ion Requested	September	17, 2007	
Time of Day	1:30 pm				E	Evaluation Date	September	28, 2007	
Outdoor Condi	tions Tem	perature	89	Relative Humid	dity 55.9	Ambie	nt CO2	433	
Fish	Temperature F	Range Rela	tive Humidity	Range	CO2	Ran	ige # 0	Occupants	
621			47.4	30% - 60%	<b>931</b>		Max 700 > Ambient 27		
Noticeable Od				isible microbial Amou		terial			
Ceiling Type	e 2 x 4 Lay In		Yes	Yes	Yes		Various		
Wall Type	Drywall		No	No		None			
Flooring	12 x 12 Vir	nyl	No	No	No		None		
	Clean	Minor Dust / Debris	Needs Cleaning		Correc	ctive Action Re	equired		
Ceiling	No	Yes	Yes	Remove and replace ceiling tiles					
Walls	Yes	No	No						
Flooring	Yes	No	No						
HVAC Supply	Grills Yes	No	No						
HVAC Return	Grills Yes	No	No						
Ceiling at Sup Grills	ply No	Yes	Yes		Remove a	and replace cei	iling tiles		
Surfaces in Ro	oom No	Yes	Yes		Clea	an as appropri	ate		
bservations									

IAQ Assessment

0171

**Location Number** 

## O

## Findings:

- Teacher and head facilities serviceperson advised that A/C was broken on a weekend and humid air was being pulled into the
- Ceiling grids throughout the room are rusted
- Visible staining and microbial growth on numerous ceiling tiles
- Build up on environmental surfaces

## Recommendations:

#### Site Based Maintenance:

- Wipe down environmental surfaces throughout the room
- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

## Physical Plant Operations

· Evaluate cause of rusted ceiling grids and stained ceiling tiles and repair as appropriate. Remove and replace stained ceiling tiles.