

managing risk with responsibility

Jeffrey S. Moquin, Director Risk Management Department Telephone: 754-321-3200 Facsimile: 754-321-3290

August 11, 2008	Signature on File
TO:	Dr. David Basile, Principal South Plantation High School
FROM:	Edward See, Project Manager Risk Management Department
SUBJECT:	Indoor Air Quality (IAQ) Assessment FISH 150, 150A, 150B, 150F and 158A

F	or Custodial Supervisor Use Only
	Custodial Issues Addressed
	Custodial Issues Not Addressed

On August 6, 2008 I conducted an assessment of FISH 150, 150A, 150B, 150F and 158Aat **South Plantation High School**. This evaluation included observations of the flooring system, ceiling tiles, false ceiling plenum, environmental surfaces, interior and exterior walls, and the accessible ventilation equipment. Additionally, environmental parameter measurements were taken to include temperature, relative humidity, and carbon dioxide. The detailed findings, along with the recommended corrective action can be found on the attached IAQ Assessment Worksheets.

The IAQ assessment did identify one or more existing conditions impacting IAQ and has generated appropriate work orders to correct deficiencies in systems and maintenance that could contribute to decreased indoor air quality. At the time of the assessment, these concerns were not an immediate health or safety concern to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Please ensure that your Head Facilities Serviceperson receives a copy of this correspondence so that the recommendations requiring their attention can be addressed. Within two weeks a representative from the Custodial/Grounds Department will conduct a follow-up visit to ensure that all issues have been appropriately addressed.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact me at 754-321-3200.

cc: Dr. Verda Farrow, Area Superintendent Fran Bolden, Area Director Jeffrey S. Moquin, Director, Risk Management Wayne Thrasher, Project Manager, Facilities and Construction Management Juana Romanuik, Project Manager, Facilities and Construction Management Ralph Eckhardt, Broward Teachers Union Roy Jarrett, National Federation of Public and Private Employees Mark Dorsett, Manager 1, Physical Plant Operations Division, Zone 1 Roy Norton, Manager Custodial/Grounds, Physical Plant Operations Division Robert Krickovich, Coordinator, LEA, Facilities and Construction Management

ES/tc Enc.

			IAQ As	sessment	Locat	ion Number	2351	
	South	Plantation Hi	gh School		Evalua	tion Requested	August	5, 2008
Time of Day	0:50 am					Evaluation Date	August	6, 2008
Outdoor Condition	is Terr	perature	83.7	Relative Hum	nidity 74	Ambie	nt CO2	355
Fish Tem	perature	Range Rel	ative Humidity	Range	CO2	Ran	ige #	Occupants
150	70.1 7	2 - 78	56.8	30% - 60%	406	Max 700	> Ambient	2
Noticeable Odor	No		Visible water mage / staining		microbial wth?	Amount of ma affected	terial	
Ceiling Type	2 x 4 Lay	In	Yes	Ν	10	2 c	eiling tiles	
Wall Type	Drywall/Pla	ster	Νο	Ν	10		None	
Flooring	Carpet		Yes	N	10		Various	
	Clean	Minor Dust / Debris	Needs Cleaning		Corre	ective Action Re	equired	
Ceiling	Νο	Yes	Yes		Remove	and replace ce	iling tile	
Walls	Yes	No	No					
Flooring	Νο	Yes	Yes		C	lean and sanitiz	ze	
HVAC Supply Gril	Is Yes	No	No					
HVAC Return Gril	ls Yes	No	No					
Ceiling at Supply Grills	Yes	No	No					
Surfaces in Room	Yes	No	No					

Findings:

- Temperature was low at the time of assessment

- 2 stained ceiling tiles
- 3 ceiling tiles not installed correctly

- Multiple food stains on carpet

Recommendations:

Site Based Maintenance:

- Adjust thermostat to increase temperature

- Remove and replace stained ceiling tiles and adjust ceiling tiles that are not installed correctly

- Thoroughly clean and sanitize carpet

- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

Physical Plant Operations:

- Evaluate cause of stained ceiling tiles and repair as appropriate. Replace stained ceiling tiles as necessary.

			IAQ Ass	sessment	Locatio	on Number	2351	
	South	n Plantation I	High School		Evaluati	on Requested	August	t 5, 2008
Time of Day	10:50 am				E	valuation Date	August	t 6, 2008
Outdoor Conditio	ns Ten	nperature [83.7	Relative Humidit	y 74	Ambie	nt CO2	355
Fish Ten	nperature	Range R	elative Humidity	Range	CO2	Ran	ige #	Occupants
150A	81.7 7	/2 - 78	40.4	30% - 60%	417	Max 700	> Ambient	2
Noticeable Odor	No	d	Visible water lamage / staining	Visible mic ? growth		Amount of ma affected	terial	
Ceiling Type	2 x 4 Lay	In	No	No	[None	
Wall Type	Drywall/Pla	ster	No	No	[None	
Flooring	12 x 12 Vi	nyl	No	No			None	
	Clean	Minor Dus / Debris	st Needs Cleaning		Correc	tive Action Re	equired	
Ceiling	Yes	No	No					
Walls	Yes	No	No					
Flooring	Yes	No	No					
HVAC Supply Gri	ills Yes	No	No					
HVAC Return Gri	lls Yes	No	No					
Ceiling at Supply Grills	Yes	No	No					
Surfaces in Roon	n Yes	No	No					

Findings:

- Temperature was elevated at the time of assessment. Room is being used as a computer hardware/server room (rack room).
- 1 stained ceiling tile
- Minor stains on carpet
- Potted plant in room. Water stain on carpet from plant being over watered.
- No visible microbial growth on books. HFSP advised that books had been wiped down with Wexcide.
- Clutter on floor and on desk area

Recommendations:

Site Based Maintenance:

- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

Facilities and Construction Management:

- Expedite project for installation of separate air handler unit for rack room

			IAQ As	sessment	Locati	on Number	2351	
	South	n Plantation Hig	gh School		Evalua	tion Requested	August	t 5, 2008
Time of Day	10:50 am					Evaluation Date	August	6, 2008
Outdoor Condition	ns Ten	perature	83.7	Relative Humi	idity 74	Ambie	nt CO2	355
Fish Tem	nperature	Range Rela	ative Humidity	Range	CO2	Ran	ge #	Occupants
150B	71 7	2 - 78	54.9	30% - 60%	453	Max 700	> Ambient	2
Noticeable Odor	No		Visible water nage / staining		nicrobial wth?	Amount of mat affected	terial	
Ceiling Type	2 x 4 Lay	In	Yes	N	0	4 ce	eiling tiles	
Wall Type	Drywall/Pla	ster	No	N	0		None	
Flooring	Carpet		Yes	N	0		Various	
	Clean	Minor Dust / Debris	Needs Cleaning		Corre	ctive Action Re	equired	
Ceiling	No	Yes	Yes		Remove	and replace ce	iling tile	
Walls	Yes	No	No					
Flooring	No	Yes	Yes		C	ean and sanitiz	e	
HVAC Supply Gri	lls Yes	No	No					
HVAC Return Gri	lls Yes	Νο	No					
Ceiling at Supply Grills	Yes	No	No					
Surfaces in Room	Yes	No	No					

Findings:

- Temperature was low at the time of assessment
- 4 stained ceiling tiles
- Minor stains on carpet
- 2 potted plants in room

Recommendations:

Site Based Maintenance:

- Adjust thermostat to increase temperature

- Remove and replace stained ceiling tiles

- Thoroughly clean and sanitize carpet

- Remove potted plants from room. Soil is a source of microbial growth

- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

Physical Plant Operations:

- Evaluate cause of stained ceiling tiles and repair as appropriate. Replace stained ceiling tiles as necessary.

			IAQ As	sessment	Locati	on Number	2351	
	South	Plantation Hig	h School		Evaluat	tion Requested	August	5, 2008
Time of Day	10:50 am				l	Evaluation Date	August	6, 2008
Outdoor Conditio	ons Terr	perature	33.7	Relative Humi	dity 74	Ambie	nt CO2	355
Fish Te	mperature	Range Rela	tive Humidity	Range	CO2	Ran	ge #	Occupants
150F	68.9 7	2 - 78	58.1	30% - 60%	418	Max 700	> Ambient	2
Noticeable Odor	No		/isible water nage / staining		nicrobial wth?	Amount of mat affected	terial	
Ceiling Type	2 x 4 Lay	In	Yes	N	0	1 c	eiling tile	
Wall Type	Drywall/Pla	ster	No	No	0		None	
Flooring	Carpet		No	Ν	0		None	
	Clean	Minor Dust / Debris	Needs Cleaning		Corre	ctive Action Re	equired	
Ceiling	No	Yes	Yes		Remove	and replace ce	iling tile	
Walls	Yes	No	No					
Flooring	Yes	No	No					
HVAC Supply Gr	rills Yes	No	No					
HVAC Return Gr	ills Yes	No	No					
Ceiling at Supply Grills	y Yes	No	No					
Surfaces in Room	m Yes	Νο	No					

Findings:

- Temperature was low at the time of assessment

- 1 stained ceiling tile

m

Recommendations:

Site Based Maintenance:

- Adjust thermostat to increase temperature

- Remove and replace stained ceiling tiles

- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

Physical Plant Operations:

- Evaluate cause of stained ceiling tiles and repair as appropriate. Replace stained ceiling tiles as necessary.

			IAQ As	sessment	Locat	ion Number	2351	
	South	n Plantation Hig	h School		Evalua	tion Requested	August 5	5, 2008
Time of Day	10:50 am					Evaluation Date	August 6	3, 2008
Outdoor Conditio	ons Terr	perature 8	33.7	Relative Hum	nidity 74	Ambie	nt CO2 🤤	355
Fish Te	mperature	Range Rela	tive Humidity	Range	CO2	Ran	ige # C	Occupants
158A	69.4 7	2 - 78	57.9	30% - 60%	405	Max 700	> Ambient	1
Noticeable Odor	r No		/isible water age / staining		microbial wth?	Amount of ma affected	terial	
Ceiling Type	2 x 4 Lay	In	Yes	Ν	No	1 c	eiling tile	
Wall Type	Drywall/Pla	ster	No	Ν	No		None	
Flooring	Carpet		No	Ν	No		None	
	Clean	Minor Dust / Debris	Needs Cleaning		Corre	ective Action Re	equired	
Ceiling	Νο	Yes	Yes		Remove	and replace ce	iling tile	
Walls	Yes	No	No					
Flooring	Yes	No	No					
HVAC Supply G	rills Yes	No	No					
HVAC Return Gr	rills Yes	No	No					
Ceiling at Supply Grills	y Yes	No	No					
Surfaces in Roo	m Yes	Νο	No					

Findings:

- Temperature was low at the time of assessment
- 1 stained ceiling tile
- Minor stains on carpet
- Potted plant in room. Water stain on carpet from plant being over watered.
- No visible microbial growth on books. HFSP advised that books had been wiped down with Wexcide.
- Clutter on floor and on desk area

Recommendations:

Site Based Maintenance:

- Adjust thermostat to increase temperature
- Remove and replace stained ceiling tiles
- Remove potted plants from room. Soil is a source of microbial growth
- Encourage occupant to reduce clutter to assist with clean efforts

- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

Physical Plant Operations:

- Evaluate cause of stained ceiling tiles and repair as appropriate. Replace stained ceiling tiles as necessary.