

managing risk with responsibility

Jeffrey S. Moquin, Director Risk Management Department Telephone: 754-321-3200 Facsimile: 754-321-3290

October 12, 2005

Signature on File

TO: Ms. Aimee Zekofsky, Principal Apollo Middle School

- FROM: Kenneth I. Partee, Project Manager, Occupational Health and Environmental Control Risk Management Department
- SUBJECT: Indoor Air Quality (IAQ) Assessment Portable 996C

On September 22, 2005 the IAQ Assessment Team conducted an assessment of Portable 996C at **Apollo Middle School**. The evaluation consisted of a walkthrough of the identified areas to assess the current condition of the location with regard to indoor air quality. This assessment included observations of the carpet, floor tile, ceiling tile, interior walls, false ceiling plenum, and accessible ventilation equipment.

Attached are the findings of this assessment along with recommendations for further assessment, remediation, or corrective actions, if needed.

Generally, the IAQ Assessment did not identify any existing conditions significantly impacting IAQ and thereby presenting immediate health and safety concerns to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact me at 754-321-3200.

 Sam Gregg, Area Superintendent Margaret Underhill, Area Director Jeffrey S. Moquin, Director, Risk Management David DeWald, Project Manager II, Facilities and Construction Management Diane Watts, Broward Teachers Union Mark Dorsett, Manager 1, Physical Plant Operations Division, Zone 1 Roy Norton, Manager Custodial/Grounds, Physical Plant Operations Division Robert Krickovich, Coordinator, LEA, Facilities and Construction Management

KP/tc Enc.

	IAQ Assessment			Locatio	Location Number			
Apollo Middle Scho					Evaluat	ion Requested	Septembe	er 21, 2005
Time of Day	11:45 pm				E	Evaluation Date	Septembe	er 22, 2005
Outdoor Condition	ons Ten	nperature	39.1	Relative Humi	dity 59.6	Ambie	nt CO2	661
		Range Rela	tive Humidity	Range	CO2	Ran	ge #	Occupants
996C	73 7	2 - 78	49.1	30% - 60%	539	Max 700	> Ambient	0
Noticeable Odor No			Visible water Visible micr damage / staining? growth?					
Ceiling Type	Ceiling Type 2 x 4 Lay In		Yes	Yes Yes		Various		
Wall Type	I Type Tackable		Yes		es	All		
Flooring	Tile		No	N	No		None	
	Clean	Minor Dust / Debris	Needs Cleaning		Correc	ctive Action Re	equired	
Ceiling	No	Yes	Yes		Replace stained tiles as appropriate			
Walls	No	Yes	Yes		Replace all tackable surfaces			
Flooring	Yes	No	No					
HVAC Supply G	rills No	Yes	Yes		Clean wit	h Wexcide disi	infectant	
HVAC Return G	rills No	Yes	Yes		Clean wit	h Wexcide disi	infectant	
Ceiling at Suppl Grills	У					N/A		
Surfaces in Roo	m No	Yes	Yes		Clea	an as appropria	ate	

Observations

Findings:

- All tackable walls are saturated (50-90% moisture)
- Visible microbial growth on East wall next to whiteboard
- 25-40% moisture readings in insulation of false ceiling plenum
- Stained ceiling tiles
- Stained light cover (diffuser)
- Dust and debris on HVAC supply and return grills
- Dust and debris on environmental surfaces throughout the room
- Hinges on closet doors are broken

Recommendations:

Site Based Maintenance:

- Clean HVAC supply and return grills with Wexcide disinfectant solution
- Clean environmental surfaces as appropriate
- Initiate a work order to repair closet doors

- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

Physical Plant Operations Division:

- Remove and replace all tackable wall surfaces for high moisture content
- Evaluate for leaks and repair as appropriate
- Remove saturated insulation in false ceiling plenum and replace as appropriate
- Evaluate for roof leaks and repair and replace ceiling tiles and light fixtures (diffuser) as appropriate