

managing risk with responsibility

Telephone: 754-321-3200 Facsimile: 754-321-3290

March 10, 2009	Signature on File
TO:	Ms. Carletha Shaw, Principal Attucks Middle School
FROM:	Robert Krickovich, Coordinator, LEA Facilities and Construction Management
SUBJECT:	Indoor Air Quality (IAQ) Assessment FISH 242 and 853

Custodial Issues Addressed
Custodial Issues Addressed
Custodial Issues Not Addressed

On February 12, 2009 I conducted an assessment of FISH 242 and 853 at **Attucks Middle School**. This evaluation included observations of the flooring system, ceiling tiles, false ceiling plenum, environmental surfaces, interior and exterior walls, and the accessible ventilation equipment. Additionally, environmental parameter measurements were taken to include temperature, relative humidity, and carbon dioxide. The detailed findings, along with the recommended corrective action can be found on the attached IAQ Assessment Worksheets.

The IAQ assessment did identify one or more existing conditions impacting IAQ and has generated appropriate work orders to correct deficiencies in systems and maintenance that could contribute to decreased indoor air quality. At the time of the assessment, these concerns were not an immediate health or safety concern to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Please ensure that your Head Facilities Serviceperson receives a copy of this correspondence so that the recommendations requiring their attention can be addressed. Within two weeks a representative from the Custodial/Grounds Department will conduct a follow-up visit to ensure that all issues have been appropriately addressed.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact me at 754-321-1638.

cc: Dr. Joel Herbst, Area Superintendent
Dr. Gina Eyerman, Area Director
Jeffrey S. Moquin, Executive Director, Support Operations
Bob Sharps, Project Manager, Facilities and Construction Management
Jamie Daniels, Broward Teachers Union
Roy Jarrett, Federation of Public Employees
Mark Dorsett, Manager 1, Physical Plant Operations Division, Zone 1
Roy Norton, Manager Custodial/Grounds, Physical Plant Operations Division

RK/tc Enc.

			IAQ Ass	sessment	Location	Number	0343	
		Attucks Mid	dle School		Evaluatio	n Requested	February	/ 11, 2009
Time of Day	2:18 pm				Eva	aluation Date	February	/ 12, 2009
Outdoor Conditior	ns Temp	perature	80.8	Relative Humidit	y <u>63</u>	Ambie	nt CO2	433
Fish Tem	perature R	ange Re	lative Humidity	Range	CO2	Ran	nge #	Occupants
242	68.2 72	2 - 78	62	30% - 60%	1096	Max 700	> Ambient	26
Noticeable Odor	No	da	Visible water mage / staining	Visible mic ? growth	-	Amount of ma affected	terial	
Ceiling Type	2 x 4		Yes	No		4 c	eiling tiles	
Wall Type	Plaster		Yes	No		Und	er Window	
Flooring	12 x 12 Vin	yl	No	No			None	
	Clean	Minor Dust / Debris	Needs Cleaning		Correcti	ve Action Re	equired	
Ceiling	Νο	Yes	Yes	Rem	ove and re	place stained	d ceiling til	es
Walls	Yes	No	No					
Flooring	Yes	No	No					
HVAC Supply Gri	lls Yes	No	No					
HVAC Return Gril	Is Yes	No	No					
Ceiling at Supply Grills	Yes	No	No					
Surfaces in Room	Yes	No	No					

Observations

Findings:

 Complaint of mold under window. Area under the window was previously repaired but never painted. Wall in question is a solid block wall. No visible microbial growth. Spots on wall are paint or stucco primer.
 4 stained ceiling tiles

Recommendations:

Site Based Maintenance:

- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

Physical Plant Operations:

- Evaluate cause of stained ceiling tiles along window wall and repair as appropriate. Remove and replace stained ceiling tiles as necessary. Note: Window wall is an interior corridor wall not exposed to weather.

- FInish repairs to wall and paint as appropriate - work order J356033

			IAQ Ass	sessment	Location N	umber	0343	
		Attucks Mic	ddle School		Evaluation I	Requested	February	/ 11, 2009
Time of Day	2:18 pm]			Eval	uation Date	February	/ 12, 2009
Outdoor Conditi	ons Ter	nperature	80.8	Relative Humidity	63	Ambie	nt CO2	433
Fish Te	emperature	Range Ro	elative Humidity	Range	CO2	Ran	ige #	Occupants
853	72.9	72 - 78	52.1	30% - 60%	1242] Max 700	> Ambient	25
Noticeable Odo	r No]d	Visible water amage / staining	Visible micro ? growth?	· · · · · · · · · · · · · · · · · · ·	nount of ma affected	terial	
Ceiling Type	2 x 4		Yes	No		2 c	eiling tiles	
Wall Type	Drywal	I	No	No			None	
Flooring	12 x 12 Vi	inyl	No	No			None	
	Clean	Minor Dus / Debris	t Needs Cleaning		Corrective	e Action Re	equired	
Ceiling	No	Yes	Yes	Remo	ove and repl	ace stained	d ceiling til	es
Walls	Yes	No	No					
Flooring	Yes	No	No					
HVAC Supply G	rills No	Yes	Yes	C	lean with W	excide dis	infectant	
HVAC Return G	rills Yes	No	No					
Ceiling at Suppl Grills	ly Yes	No	No					
Surfaces in Roo	om Yes	No	No					

Observations

Findings:

- Complaint of itching and rash on arms when in room
- CO2 level was slightly elevated at the time of the assessment
- Non-approved chemicals in room (Elmer's spray glue, Lysol cleaner, Glade spray and Glade plug-in)
- Minor dust and debris on HVAC supply grills
- 2 stained ceiling tiles
- Teachers desk chair is missing one arm rest and other arm rest is damaged
- FISH 860 (air handler unit room) pan, coils and interior of unit were clean

Recommendations:

Site Based Maintenance:

- Clean HVAC supply grills with Wexcide disinfectant solution
- Replace teachers desk chair

- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

Physical Plant Operations:

- Evaluate cause of stained ceiling tiles and repair as appropriate. Remove and replace stained ceiling tiles as necessary. - Evaluate HVAC for proper operation and repair as appropriate to lower CO2 level