

managing risk with responsibility

Jeffrey S. Moquin, Director Risk Management Department Telephone: 754-321-3200 Facsimile: 754-321-3290

Signature on File

October 24, 2006

TO: Ms. Ellen Etling, Principal Bair Middle School

- FROM: Aston A. Henry, Jr., Supervisor Risk Management Department
- SUBJECT: Indoor Air Quality (IAQ) Assessment FISH 193, 193A, 206 and 207

On October 4, 2006 Kenneth Partee conducted an assessment FISH 193, 193A, 206 and 207 at **Bair Middle School**. This evaluation included observations of the flooring system, ceiling tiles, false ceiling plenum, environmental surfaces, interior and exterior walls, and the accessible ventilation equipment. The detailed findings, along with the recommended corrective action can be found on the attached IAQ Assessment Worksheets.

The IAQ assessment did identify one or more existing conditions impacting IAQ and has generated appropriate work orders to correct deficiencies in systems and maintenance that could contribute to decreased indoor air quality. At the time of the assessment, these concerns were not an immediate health or safety concern to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact me at 754-321-3200.

CC: Dr. Harry LaCava, Area Superintendent
 Fran Bolden, Area Director
 Jeffrey S. Moquin, Director, Risk Management
 Charles Ricks, Project Manager, Facilities and Construction Management
 Gary Itzkowitz, Broward Teachers Union
 Mark Dorsett, Manager 1, Physical Plant Operations Division, Zone 1
 Roy Norton, Manager Custodial/Grounds, Physical Plant Operations Division
 Robert Krickovich, Coordinator, LEA, Facilities and Construction Management

AAH/tc Enc.

		IAQ Assessment		Locati	Location Number			
		Bair Midd	le School		Evaluat	ion Requested	Octobe	r 3, 2006
Time of Day	7:48 a.m.				I	Evaluation Date	Octobe	r 4, 2006
Outdoor Condition	ns Temp	erature	83.8	Relative Humi	idity 50.5	Ambie	nt CO2	515
	perature Ra	ange Rela	ative Humidity	Range	CO2	Ran	ge #	Occupants
193 & 193A	72.5 72	- 78	55.3	30% - 60%	565	Max 700	> Ambient	2
Noticeable Odor	No		Visible water nage / staining		nicrobial wth?	Amount of mat affected	terial	
Ceiling Type	2 x 4 Lay In	1	No	N	0		None	
Wall Type	Plaster		No	lo No		None		
Flooring	Tile		No	N	0		None	
	Clean	Minor Dust / Debris	Needs Cleaning		Corre	ctive Action Re	equired	
Ceiling	Νο	Yes	Yes		Cle	an as appropria	ate	
Walls	Yes	No	No					
Flooring	Yes	No	No					
HVAC Supply Gril	ls No	Yes	Yes		Clean wit	h Wexcide disi	nfectant	
HVAC Return Gril	ls No	Yes	Yes		Clean wit	h Wexcide disi	nfectant	
Ceiling at Supply Grills	Νο	Yes	Yes		Cle	an as appropria	ate	
Surfaces in Room	No	Yes	Yes		Cle	an as appropria	ate	

Observations

Findings:

- Dust build up on ceiling tiles
- Dust and debris on HVAC supply and return grills and on ceiling at supply grills
- Dust build up on environmental surfaces.
- Damaged ceiling tile around vent hood
- Dust inside of cabinets
 Old food items in sink
- Damaged ceiling tile around HVAC supply grill in FISH 193A

Recommendations:

Site Based Maintenance:

- Dust ceiling tiles
- Clean HVAC supply and return grills with Wexcide disinfectant solution
- Clean environmental surfaces throughout the room.
- Clean inside of cabinets
- Thoroughly clean sink
- Ensure that all food items are stored in airtight containers

- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

Physical Plant Operations:

- Remove and replace damaged ceiling tiles around vent hood

- Remove and replace damaged ceiling tiles around HVAC supply grill in FISH 193A

		IAQ Assessment		Location Number	2611
	Bai	r Middle School		Evaluation Requested	October 3, 2006
Time of Day 7:4	48 a.m.			Evaluation Date	October 4, 2006
Outdoor Conditions	Temperatur	e 83.8	Relative Humidity	50.5 Ambie	ent CO2 515
Fish Tempe	erature Range	Relative Humidity	Range	CO2 Rar	nge # Occupants
206 7	70.6 72 - 78	64	30% - 60%	534 Max 700	> Ambient 1
Noticeable Odor	Yes	Visible water damage / staining	Visible micro g? growth?	bial Amount of ma affected	terial
Ceiling Type	2 x 4 Lay In	No	No		None
Wall Type C	Wall Type Carpet/Concrete		No		None
Flooring	Tile	No	No		None
	Clean Minor / Del		l	Corrective Action Re	equired
Ceiling	Yes	No			
Walls	No	s Yes		Remove carpet from	walls
Flooring	Yes	No			
HVAC Supply Grills	Yes	No			
HVAC Return Grills	No	s Yes	CI	ean with Wexcide disi	infectant
Ceiling at Supply Grills	Yes	No			
Surfaces in Room	No	s Yes		Clean as appropri	ate

Observations

Findings:

- Dust and debris on HVAC return grills
- Dust build up on environmental surfaces
- Teacher is using Damp Rid to control humidity
- Temperature was low and humidity level was slightly elevated.
- Room was previously used for music and walls are carpeted for soundproofing

Recommendations:

Site Based Maintenance:

- Clean HVAC return grills with Wexcide disinfectant solution
- Clean environmental surfaces throughout the room.
- Remove Damp Rid
- Adjust thermostat to increase temperature and lower humidity level. Continue to monitor condition and initiate a work order to Physical Plant Operations to evaluate the HVAC system if temperature does not improve.
- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

Physical Plant Operations:

- Evaluate and remove carpet from all walls if soundproofing is no longer necessary

			IAQ As	sessment	Locatio	n Number	2611	
		Bair Middl	e School		Evaluatio	on Requested	Octobe	r 3, 2006
Time of Day	7:48 a.m.				E	valuation Date	Octobe	r 4, 2006
Outdoor Condition	is Tem	perature 8	33.8	Relative Humidit	y 50.5	Ambie	nt CO2	515
Fish Tem	perature R	ange Rela	tive Humidity	Range	CO2	Ran	nge #	Occupants
207	71.2 7 2	2 - 78	64.9	30% - 60%	528	Max 700	> Ambient	1
Noticeable Odor	Yes		/isible water nage / staining	Visible mic g? growth		Amount of ma affected	terial	
Ceiling Type	2 x 4 Lay I	n	No	No] [None	
Wall Type	Wall Type Carpet/Concrete		No] [None		
Flooring	Tile		No	No] [None	
	Clean	Minor Dust / Debris	Needs Cleaning		Correct	tive Action Re	equired	
Ceiling	Yes	Νο	No					
Walls	No	Yes	Yes		Remov	e carpet from	walls	
Flooring	Yes	No	No					
HVAC Supply Gril	ls Yes	No	No					
HVAC Return Gril	Is No	Yes	Yes		Clean with	Wexcide disi	nfectant	
Ceiling at Supply Grills	Yes	Νο	No					
Surfaces in Room	No	Yes	Yes		Clea	n as appropri	ate	

Observations

Findings:

- Dust build up on walls around wood trim
- Dust and debris on HVAC return grills
- Dust build up on environmental surfaces
- Temperature was low and humidity level was slightly elevated.
- Room was previously used for music and walls are carpeted for soundproofing

Recommendations:

Site Based Maintenance:

- Clean walls around wood trim

- Clean HVAC return grills with Wexcide disinfectant solution

- Clean environmental surfaces throughout the room.

- Adjust thermostat to increase temperature and lower humidity level. Continue to monitor condition and initiate a work order to Physical Plant Operations to evaluate the HVAC system if temperature does not improve.

- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

Physical Plant Operations:

- Evaluate and remove carpet from all walls if soundproofing is no longer necessary