

# managing risk with responsibility

Jeffrey S. Moquin, Director Risk Management Department Telephone: 754-321-3200 Facsimile: 754-321-3290

August 22, 200	7 Signature on File
TO:	Mr. Vincent Alessi,, Principal Deerfield Beach Middle School
FROM:	Robert Krickovich, Coordinator, LEA Facilities and Construction Management
SUBJECT:	Indoor Air Quality (IAQ) Assessment <b>FISH 501, 502, 502A, 502B and 503</b>

Fo	or Custodial Supervisor Use Only
	Custodial Issues Addressed
	Custodial Issues Not Addressed

On August 17, 2007 I conducted an assessment of FISH 501, 502, 502A, 502B and 503 at **Deerfield Beach Middle School**. This evaluation included observations of the flooring system, ceiling tiles, false ceiling plenum, environmental surfaces, interior and exterior walls, and the accessible ventilation equipment. Additionally, environmental parameter measurements were taken to include temperature, relative humidity, and carbon dioxide. The detailed findings, along with the recommended corrective action can be found on the attached IAQ Assessment Worksheets.

The IAQ assessment did identify one or more existing conditions impacting IAQ and has generated appropriate work orders to correct deficiencies in systems and maintenance that could contribute to decreased indoor air quality. At the time of the assessment, these concerns were not an immediate health or safety concern to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Please ensure that your Head Facilities Serviceperson receives a copy of this correspondence so that the recommendations requiring their attention can be addressed. Within two weeks a representative from the Custodial/Grounds Department will conduct a follow-up visit to ensure that all issues have been appropriately addressed.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact me at 754-321-1638.

cc: Dr. Joanne Harrison, Area Superintendent David Hall, Area Director Jeffrey S. Moquin, Director, Risk Management Sam Bays, Project Manager, Facilities and Construction Management Lynn Cavall, Broward Teachers Union Roy Jarrett, National Federation of Public and Private Employees Mark Dorsett, Manager 1, Physical Plant Operations Division, Zone 1 Roy Norton, Manager Custodial/Grounds, Physical Plant Operations Division

RK/tc Enc.

			IAQ As	sessment	Locatio	on Number	0911	
	Deerfie	ld Beach Mid	Idle School		Evaluat	ion Requested	August	16, 2007
Time of Day	1:50 pm				I	Evaluation Date	August	17, 2007
Outdoor Conditio	ons Tem	perature	85.6	Relative Humidi	y 87.5	Ambie	nt CO2	468
Fish Te	mperature	Range Re	elative Humidity	Range	CO2	Ran	ige #	Occupants
501	73.9 <b>7</b>	2 - 78	61.7	30% - 60%	516	Max 700	> Ambient	2
Noticeable Odo	r No	da	Visible water amage / staining	Visible mic ? growth		Amount of mat affected	terial	
Ceiling Type	2 x 4 Lay	In	No	No	]		None	
Wall Type	Plaster		No	No	]		None	
Flooring	12 x 12 Vir	nyl	No	No	]		None	
	Clean	Minor Dus / Debris	t Needs Cleaning		Correc	ctive Action Re	equired	
Ceiling	Yes	No	No					
Walls	Yes	No	No					
Flooring	Yes	No	No					
HVAC Supply G	rills No	Yes	Yes		Clean wit	h Wexcide disi	infectant	
HVAC Return G	rills Yes	No	No					
Ceiling at Suppl Grills	у No	Yes	Yes		Clea	an as appropri	ate	
Surfaces in Roo	m Yes	No	No					

#### Findings:

- Musty odor in corridor outside of room
- Dust and debris on HVAC supply grills and on ceiling at supply grills
- Humidity level was elevated

#### -Recommendations:

#### Site Based Maintenance:

- Clean HVAC supply grills with Wexcide disinfectant solution and clean ceiling at supply grills

- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

#### Physical Plant Operations:

- Evaluate HVAC for proper operation and repair as appropriate to lower humidity level. Clean HVAC unit.

			IAQ As	sessment	Location Nu	mber	0911	
	Deerfie	eld Beach Midd	lle School		Evaluation R	equested	August	16, 2007
Time of Day	1:50 pm				Evalu	ation Date	August	17, 2007
Outdoor Condit	ions Terr	perature	85.6	Relative Humidity	87.5	Ambie	nt CO2	468
Fish T	emperature	Range Rela	ative Humidity	Range	CO2	Ran	ge #	Occupants
502	71.4 <b>7</b>	2 - 78	66.8	30% - 60%	502	Max 700	> Ambient	5
Noticeable Odd	or Yes		Visible water nage / staining	Visible micro growth?	obial Am	ount of main affected	terial	
Ceiling Type	2 x 4 Lay	In	Yes	Yes		1 c	eiling tile	
Wall Type	Plaster		No	No			None	
Flooring	12 x 12 Vir	nyl	No	No			None	
	Clean	Minor Dust / Debris	Needs Cleaning		Corrective	Action Re	quired	
Ceiling	Νο	Yes	Yes	R	emove and r	eplace cei	ling tiles	
Walls	Yes	Νο	No					
Flooring	Yes	Νο	No					
HVAC Supply C	Grills Yes	Νο	No					
HVAC Return G	Grills No	Yes	Yes		Clean as	appropri	ate	
Ceiling at Supp Grills	oly Yes	No	No					
Surfaces in Ro	om Yes	No	No					

## Findings:

- Musty odor emanating from HVAC supply grills
- One stained ceiling tile inside doorway
- Dust build up inside of return box
- Humidity level was elevated

#### -Recommendations:

#### Site Based Maintenance:

- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

#### Physical Plant Operations:

- Evaluate cause of stained ceiling tile just inside doorway and repair as appropriate. Remove and replace ceiling tile.
- Clean HVAC unit and clean inside of return box
- Evaluate HVAC for proper operation and repair as appropriate to lower humidity level

			IAQ As	sessment	Location N	umber	0911	
	Deerfie	ld Beach Mide	dle School		Evaluation F	Requested	August	16, 2007
Time of Day	1:50 pm				Evalu	uation Date	August	17, 2007
Outdoor Conditi	ions Tem	perature	85.6	Relative Humidity	87.5	Ambie	nt CO2	468
Fish To	emperature F	Range Rel	ative Humidity	Range	CO2	Ran	ige #	Occupants
502A	74.8 <b>7</b>	2 - 78	62.4	30% - 60%	520	] Max 700	> Ambient	2
Noticeable Odd	or No		Visible water mage / staining	Visible micro ? growth?	/	nount of ma affected		
Ceiling Type	2 x 4 Lay	In	Yes	No		1 c	eiling tile	
Wall Type	Plaster		No	No			None	
Flooring	12 x 12 Vir	ıyl	No	No			None	
	Clean	Minor Dust / Debris	Needs Cleaning		Corrective	Action Re	equired	
Ceiling	No	Yes	Yes	R	emove and	replace cei	ling tiles	
Walls	Yes	No	No					
Flooring	Yes	No	No					
HVAC Supply G	Brills No	Yes	Yes	C	lean with W	excide dis	infectant	
HVAC Return G	Grills No	Yes	Yes	C	lean with W	excide dis	infectant	
Ceiling at Supp Grills	ly No	Yes	Yes		Clean a	s appropri	ate	
Surfaces in Roo	om Yes	No	No					

#### Findings:

- Musty odor in corridor outside of room
- One stained ceiling tile inside doorway
- Dust and debris on HVAC supply and return grills and on ceiling at supply grills
- Humidity level was elevated

## -Recommendations:

#### Site Based Maintenance:

Clean HVAC supply and return grills with Wexcide disinfectant solution and clean ceiling at supply grills
Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

#### Physical Plant Operations:

- Evaluate cause of stained ceiling tile just inside doorway and repair as appropriate. Remove and replace ceiling tile. - Evaluate HVAC for proper operation and repair as appropriate to lower humidity level. Clean HVAC unit.

			IAQ As	sessment	Locati	on Number	0911	
	Deerfield	Beach Middl	e School		Evaluat	tion Requested	August	16, 2007
Time of Day 1	:50 pm				l	Evaluation Date	August	17, 2007
Outdoor Conditions	s Temp	erature 8	5.6	Relative Humi	idity 87.5	5 Ambie	nt CO2	468
Fish Temp	erature Ra	inge Rela	tive Humidity	Range	CO2	Ran	ge #	Occupants
502B	69.9 <b>72</b>	- 78	69.2	30% - 60%	506	Max 700	> Ambient	2
Noticeable Odor	Yes		/isible water age / staining		microbial wth?	Amount of mat affected		
Ceiling Type	2 x 4 Lay In		Yes	N	0	5 ce	eiling tiles	
Wall Type	Plaster		No	Ν	ο		None	
Flooring	12 x 12 Viny		No	N	0		None	
	Clean	Minor Dust / Debris	Needs Cleaning		Corre	ctive Action Re	quired	
Ceiling	Νο	Yes	Yes		Remove	and replace cei	ling tiles	
Walls	Yes	Νο	No					
Flooring	Yes	Νο	No					
HVAC Supply Grills	s No	Yes	Yes		Clean wit	th Wexcide disi	nfectant	
HVAC Return Grills	s No	Yes	Yes		Clean wit	th Wexcide disi	nfectant	
Ceiling at Supply Grills	Νο	Yes	Yes		Cle	an as appropria	ate	
Surfaces in Room	Yes	No	No					

#### Findings:

- Musty odor emanating from HVAC supply grills

- 4 stained ceiling tiles and one missing ceiling tile: one above door, one between sink and time out room, one at exit light, one along wall left of the sink and one missing tile in time out room.

- Dust and debris on HVAC supply and return grills and on ceiling at supply grills

- Temperature was low and humidity level was elevated

#### -Recommendations:

#### Site Based Maintenance:

- Clean HVAC supply and return grills with Wexcide disinfectant solution and clean ceiling at supply grills

- Replace missing ceiling tile in time out room

- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

## Physical Plant Operations:

Evaluate cause of stained ceiling tile just inside doorway and repair as appropriate. Remove and replace ceiling tile.
Evaluate HVAC for proper operation and repair as appropriate to increase temperature and lower humidity level. Clean HVAC unit.

- Remove and replace stained ceiling tiles in various areas outside of rooms. Evaluate for cause of stained ceiling tiles and repair. Building appears to have roof leaks.

			IAQ As	sessment	Location N	lumber	0911	
	Deerfi	eld Beach Mid	dle School		Evaluation	Requested	August	16, 2007
Time of Day	1:50 pm	]			Eval	uation Date	August	17, 2007
Outdoor Condit	tions Ter	mperature	85.6	Relative Humidity	87.5	Ambie	nt CO2	468
Fish T	Temperature	Range Re	lative Humidity	Range	CO2	Ran	ige #	Occupants
503	78	72 - 78	58.1	30% - 60%	508	Max 700	> Ambient	2
Noticeable Ode	or No	] da	Visible water mage / staining	Visible micro growth?		nount of ma affected	terial	
Ceiling Type	2 x 4 Lay	/ In	Yes	No		3 C	eiling tiles	
Wall Type	Plaste	r	No	No			None	
Flooring	12 x 12 V	inyl	No	No			None	
	Clean	Minor Dust / Debris	Needs Cleaning		Corrective	e Action Re	equired	
Ceiling	No	Yes	Yes	R	emove and	replace cei	ling tiles	
Walls	Yes	No	No					
Flooring	Yes	No	No					
HVAC Supply (	Grills No	Yes	Yes	C	lean with W	excide dis	infectant	
HVAC Return C	Grills Yes	No	No					
Ceiling at Supp Grills	oly Yes	No	No					
Surfaces in Ro	om Yes	No	No					

## Findings:

- Musty odor in corridor outside of room

- 1 stained ceiling tile at exit light and two missing ceiling tiles in time out room

- Dust and debris on HVAC supply grills

### -Recommendations:

## Site Based Maintenance:

- Clean HVAC supply grills with Wexcide disinfectant solution

- Replace missing ceiling tiles in time out room

- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

#### Physical Plant Operations:

- Evaluate cause of stained ceiling tile at exit light and repair as appropriate. Remove and replace ceiling tile. - Clean HVAC unit