

Aston A. Henry, Supervisor

managing risk with responsibility

754 321-1900

Telephone:

Risk Manage	ement Department	Fax: 754 321-1917	
March 11, 2	013 Signature on File	For Custodial Supervisor Use Onl	<u>y</u>
TO:	Francine Baugh, Principal Deerfield Beach Middle School	Custodial Issues Addressed Custodial Issues Not Addressed	
FROM:	Richard Rosa, Project Manager Facilities & Construction		
SUBJECT:	Indoor Air Quality (IAQ) Assessment		

On March 6, 2013, I conducted an assessment at **Deerfield Beach Middle School**. Attached are findings and recommendations for further assessment, remediation, or corrective actions needed.

The IAQ assessment did identify one or more existing conditions impacting IAQ and has generated appropriate work orders to correct deficiencies in systems and maintenance that could contribute to decreased indoor air quality. At the time of the assessment, these concerns were not an immediate health or safety concern to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Please ensure that your Head Facilities Serviceperson receives a copy of this correspondence so that the recommendations requiring their attention can be addressed. In an attempt to separate IAQ issues from general maintenance items, the attached assessment may contain direction for site based staff to generate a work order through COMPASS. Within two weeks a representative from the Custodial/Grounds Department will conduct a follow-up visit to ensure that all site based custodial issues have been appropriately addressed.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact us at 754-321-1907.

cc: Directors, School Performance & Accountability
Shelley Meloni, Task Assigned Chief Facilities & Construction Officer, Facilities & Construction
Mark Dorsett, Manager, Zone 1, Physical Plant Operations Division
Roy Norton, Manager, Custodial/Grounds, Physical Plant Operations Division
Aston Henry, Supervisor, Risk Management
Sonja Coley, Senior Project Manager, Facilities & Construction
Broward Teachers Union
Federation of Public Employees

RR/tc Enc.

IAQ Assessment

Deerfield Beach	Middle Evaluation Da	March 6, 2013	Time of Day 12	:15
Outdoor Conditions Temperature	e 79.7 Relativ	re Humidity 49.3	Ambient CO2 42	1
Fish Temperature Range 851 73 72 - 78		Range CO ² 0% - 60% 472	Range # Occ MAX 700 > Ambient	cupants
Noticeable Odor No	Visible water damage / staining?	Visible microbial growth?	Amount of material affected	
Ceiling 2' x 4'	Yes	No	4 ceiling tiles	
Walls Drywall	Yes	No	< 1 sq ft	
Floor 12" x 12" Vinyl	No	No		
Ceiling Clean No Walls Clean No	HVAC Supply Grills Clean	Yes	HVAC Return Grills Clean	Yes
Flooring Clean No	Inside of Supply Duct Clean	Yes	Inside of Return Duct Clean	Yes
Room Surfaces No Clean	Ceiling at Supply Grills Clean	Yes		
Trash Removed Yes	Exhaust Fans Working	N/A	Unapproved Chemicals / Cleaners in Room	No
Signs of Pests No	Drain Traps Wet	N/A	Air Fresheners	
Room Cluttered No	Food if Stored in Room is in Sealed Containers	N/A	in Room	No
Mechanical Equipment Location Ba	ard like HVAC system in cla	assroom	Mechanical Room Clean	N/A
Filters Installed Properly N/A	Filters Clean	N/A	Inside of HVAC Unit Clean	N/A
Condensate Pan Clean N/A	Cooling Coil Clean	N/A		
Fresh Air Intake Location	hind Bard unit/Exterior wa	all 🔻	Fresh Air Intake Free of Obstruction	Yes
Pollutant Sources Near Air Intake)	▼	or obstruction	
Observations				
The humidstat is set at 80% behind the return air grill. Repair or reset humidistat due to the contrast of humidity levels between outside and inside levels. The lower left corner of the South window is wet per moisture meter. I recommend that a roofer evaluate the water integrity of the roof.				
Corrective Actions to be Completed	d by Site Based Staff	Corrective Action	ns to be Completed by PP0)

Corrective Actions to be completed by one based of	٠	
Replace stained ceiling tiles after roofrepairs		
Thoroughly clean and sanitize flooring	▼	
Clean dust buildup on surfaces and window blinds	▼	
	▼	
	•	
	▼	
	▼	
	▼	

Corrective Actions to be completed by 1.1.	
Repair HVAC to reduce humidity level	▼
Evaluate and repair cause of stained ceiling tiles	▼
Remove/replace interior water damaged walls	▼
	▼
	▼
	▼
	▼
	▼

IAQ Assessment

Deerfield Be	each Middle Evaluation Dat	te March 6, 2013	Time of Day1	2:15
Outdoor Conditions Tempera	ature 79.7 Relative	e Humidity 49.3	Ambient CO2 4	21
		Range CO ² 3211		ccupants
Noticeable Odor No	Visible water damage / staining?	Visible microbial growth?	Amount of material affected	
Ceiling 2' x 4'	Yes	No	8 ceiling tiles	
Walls Drywall	Yes	No	< 1 sq ft	
Floor 12" x 12" Vinyl	No	No		
Ceiling Clean No Walls Clean No	HVAC Supply Grills Clean	Yes	HVAC Return Grills Clean	No
Flooring Clean No	Inside of Supply Duct Clean	Yes	Inside of Return Duct Clean	Yes
Room Surfaces No Clean	Ceiling at Supply Grills Clean	No		
Trash Removed Yes	Exhaust Fans Working	N/A	Unapproved Chemicals / Cleaners in Room	No
Signs of Pests No	Drain Traps Wet	N/A		
Room Cluttered No	Food if Stored in Room is in Sealed Containers	N/A	Air Fresheners in Room	No
Mechanical Equipment Location	Bard like HVAC system in class	ssroom	Mechanical Room Clean	N/A
Filters Installed Properly N/A	Filters Clean	N/A	Inside of HVAC Unit Clean	N/A
Condensate Pan Clean N/A	Cooling Coil Clean	N/A		
Fresh Air Intake Location	Behind Bard unit/Exterior wal	II ▼	Fresh Air Intake Free of Obstruction	Yes
Pollutant Sources Near Air Intake	No	▼	oi obstruction	
Observations				
The HVAC system was not runni least two weeks. The unit's elect grill. The damaged wall is locate	trical disconnect has a lock out d under the glass block and the	t tag. The humidstat is	s set at 80% behind the re	eturn air

Corrective Actions to be Completed by Site Based Staff

ан
•
•
•
▶
•
•
▼
▼

Corrective Actions to be Completed by PPO

Corrective Actions to be completed by 11 c		
Repair HVAC to reduce humidity level		
Repair HVAC to reduce CO2 level	▼	
Remove/replace interior water damaged walls	▼	
Evaluate and repair cause of stained ceiling tiles		
	▼	
	▼	
	▼	
	▼	