

managing risk with responsibility

Telephone: 754-321-3200 Facsimile: 754-321-3290

Jeffrey S. Moquin, Director Risk Management Department

September 6, 2006 Signature on File

TO: Mr. James McDermott, Principal

Forest Glen Middle School

FROM: Robert J. Krickovich, Coordinator, LEA

Facilities and Construction Management, Environmental Division

SUBJECT: Indoor Air Quality (IAQ) Assessment

FISH 223 and 516

On August 11, 2006 I conducted an assessment of FISH 223 and 516 at Forest Glen Middle School. This evaluation included observations of the flooring system, ceiling tiles, false ceiling plenum, environmental surfaces, interior and exterior walls, and the accessible ventilation equipment. Additionally, environmental parameter measurements were taken to include temperature, relative humidity, and carbon dioxide. The detailed findings, along with the recommended corrective action can be found on the attached IAQ Assessment Worksheets.

The IAQ assessment did identify one or more existing conditions impacting IAQ and has generated appropriate work orders to correct deficiencies in systems and maintenance that could contribute to decreased indoor air quality. At the time of the assessment, these concerns were not an immediate health or safety concern to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact me at 754-321-1638.

cc: Dr. Joanne Harrison, Area Superintendent
Jackie Haywood, Area Director
Jeffrey S. Moquin, Director, Risk Management
Paul Bach, Project Manager, Facilities and Construction Management
Ruby Fitzgerald, Broward Teachers Union
Mark Dorsett, Manager 1, Physical Plant Operations Division, Zone 1
Roy Norton, Manager Custodial/Grounds, Physical Plant Operations Division

RK/tc Enc.

	F	Forest Glen Mi	ddle School		Evaluat	ion Requested Augu	st 11, 2006
Time of Day	2:30 pm				ı	Evaluation Date Augu	st 11, 2006
Outdoor Cond	itions Te	emperature	90.4	Relative Humidity	58.5	Ambient CO2	560
Fish	Temperature	Range R	elative Humidity	Range	CO2	Range	# Occupants
223	72.6	72 - 78	63.4	30% - 60%	530	Max 700 > Ambie	nt 3
Noticeable Oc	dor Yes		Visible water lamage / staining	Visible micro growth?		Amount of material affected	
Ceiling Type	2 x 2 La	ay In	No	No		None	
Wall Type	Plast	er	No	No		None	
Flooring	Carpe	et	No	No		None	
	Clean	Minor Dus	st Needs Cleaning	l	Corre	ctive Action Required	
Ceiling	Yes	No	No				
Walls	Yes	No	No				
Flooring	Yes	No	No				
HVAC Supply	Grills Yes	No	No				
HVAC Return	Grills Yes	No	No	С	lean insi	ide of HVAC return duc	t
Ceiling at Sup Grills	oply Yes	No	No				
Surfaces in Ro	oom No	Yes	Yes				

IAQ Assessment

3051

Location Number

Observations

Findings:

- Visible microbial growth on instrument cases, numerous instruments and sheet music and books.
- Dust build up on environmental surfaces
- Heavy dust build up on inside of HVAC return duct (FISH 222 and 223)
- Humidity level was elevated

Recommendations:

Site Based Maintenance:

- Discard approximately 40 instrument cases that cannot be cleaned. Discard sheet music and books.
- Thoroughly clean instrument cases that can be cleaned with Wexcide disinfectant solution
- Clean environmental surfaces throughout the room
- Instruments will be sent out to vendor for cleaning
- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

Physical Plant Operations:

- Provide custodial assistance
- Clean inside of HVAC return duct (FISH 222 and 223)
- Evaluate and repair HVAC system to lower humidity level

Note: EQ00736 - Cleaning assistance

<u> </u>	J	Forest Glen Mi	ddle School		Evaluation Requested	August 11, 2006	
Time of Day	2:30 pm				Evaluation Date	August 11, 2006	
Outdoor Cond	itions Te	emperature	90.4	Relative Humidity	58.5 Ambie	ent CO2 560	
l	Temperature	Range R	elative Humidity	Range		nge # Occupants	
516	73.7	72 - 78	68.5	30% - 60%	575 Max 700) > Ambient 4	
Noticeable O	dor No		Visible water lamage / staining	Visible micro growth?	bial Amount of ma affected		
Ceiling Type 2 x 2 Lay In		ay In	No No			None	
Wall Type	Wall Type Plaster		No			None	
Flooring	Carpe	et	No	No		None	
	Clean	Minor Dus / Debris	st Needs Cleaning		Corrective Action R	equired	
Ceiling	Yes	No	No				
Walls	Yes	No	No				
Flooring	Yes	No	No				
HVAC Supply	Grills Yes	No	No				
HVAC Return	Grills Yes	No	No				
Ceiling at Supply No Year		Yes	Yes Re		eplace ceiling tiles as appropriate		
Surfaces in R	oom Yes	No	No				
) Dbservations							
Findings:							
- Visible microb	ial growth on w						
	HVAC supply						
- Humidity level	ont wall does no was elevated	y gloze brober	ıy				
Recommendat	ions:						
	esk with Wexci			obial growth returns rowth as well as dus	dispose of desk. t and debris accumulat	ion and clean as	

Physical Plant Operations:

- Remove and replace ceiling tiles at HVAC supply grills

- Evaluate and repair front wall window

Note: EQ00736 - Cleaning assistance

- Evaluate and repair HVAC system to lower humidity level

IAQ Assessment

3051

Location Number