

managing risk with responsibility

Jeffrey S. Moquin, DirectorTelephone: 754-321-3200Risk Management DepartmentFacsimile: 754-321-3290

July 17, 2007	Signature on File	For Custodial Supervisor Use Only
TO:	Mr. James McDermott,, Principal Forest Glen Middle School	Custodial Issues Addressed Custodial Issues Not Addressed
FROM:	Robert Krickovich, Coordinator, LEA Facilities and Construction Management	
SUBJECT:	Indoor Air Quality (IAQ) Assessment FISH 215	

On June 28, 2007 I conducted an assessment of FISH 215 at **Forest Glen Middle School**. This evaluation included observations of the flooring system, ceiling tiles, false ceiling plenum, environmental surfaces, interior and exterior walls, and the accessible ventilation equipment. Additionally, environmental parameter measurements were taken to include temperature, relative humidity, and carbon dioxide. The detailed findings, along with the recommended corrective action can be found on the attached IAQ Assessment Worksheets.

The IAQ assessment did identify one or more existing conditions impacting IAQ and has generated appropriate work orders to correct deficiencies in systems and maintenance that could contribute to decreased indoor air quality. At the time of the assessment, these concerns were not an immediate health or safety concern to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Please ensure that your Head Facilities Serviceperson receives a copy of this correspondence so that the recommendations requiring their attention can be addressed. Within two weeks a representative from the Custodial/Grounds Department will conduct a follow-up visit to ensure that all issues have been appropriately addressed.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact me at 754-321-1638.

cc: Dr. Joanne Harrison, Area Superintendent
Jackie Haywood, Area Director
Jeffrey S. Moquin, Director, Risk Management
Paul Bach, Project Manager, Facilities and Construction Management
Ruby Fitzgerald, Broward Teachers Union
Roy Jarrett, National Federation of Public and Private Employees
Mark Dorsett, Manager 1, Physical Plant Operations Division, Zone 1
Roy Norton, Manager Custodial/Grounds, Physical Plant Operations Division

RK/tc Enc.

Forest Glen Middle School								Eva	Evaluation Requested June 26, 2007					
Time of Day	2:05	pm							Eva	luation Dat	e Ju	ne 28	3, 2007	
Outdoor Cond	litions	Te	emperature	79.6		Relative H	lumidity	, [84.6	Amb	ient CO2		495	
Fish	Tempera	ture	Range	Relative	Humidity	' Range		CO)2	R	ange	# (Occupa	ants
215	70.1		72 - 78	52	2.8	30% - 60%	6	91	2	Max 70	0 > Amb	ient	1	
Noticeable Odor No Visible water Visible microbial Amount of material damage / staining? growth? affected														
Ceiling Type	2	x 2 La	ıy In		No		No				None			┚╽
Wall Type	St	ruck E	Block								Unknown			□
Flooring	12	x 12 \	/inyl								Unknown	1		$\supset $
	CI	ean	Minor D / Debr		Needs Cleaning	I		C	orrectiv	e Action	Required			
Ceiling		Yes	No]	No									$\Box \mid$
Walls]					Unabl	e to deteri	nine			$\Box \Big $
Flooring]					Unabl	e to deteri	nine			$\Box $
HVAC Supply	Grills [No	Yes]	Yes		C	lear	n with V	Vexcide d	sinfecta	nt		$\exists $
HVAC Return	Grills []					Unabl	e to deteri	nine			$\exists $
Ceiling at Sup Grills	oply [No	Yes]	Yes				Clean	as approp	riate			
Surfaces in R	oom [Unabl	e to deteri	nine			
bservations														
Findings: - Room is @ 28' x 12' and was packed solid with boxes and other stored items. Only a 4' x 4' area at the door was open to enter the room Unable to determine status of walls, flooring, HVAC return grills and environmental surfaces due to the boxes and other items Dust and debris on HVAC supply grills and on ceiling at supply grills - Temperature was low at the time of the assessment -Recommendations:														

Clean HVAC supply grill with Wexcide disinfectant solution and clean ceiling as appropriate

- Evaluate HVAC for proper operation and repair as appropriate to increase temperature

Reduce storage in room and thoroughly clean walls, flooring, HVAC return grills and environmental surfaces

Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as

Site Based Maintenance:

Physical Plant Operations:

appropriate

IAQ Assessment

3051

Location Number