

June 22, 2009

## managing risk with responsibility

Aston A. Henry, Supervisor	Telephone:	754 321-1900
Risk Management Department	Fax:	754 321-1917

TO: Ms. Debra Patterson, Principal Gulfstream Middle School

Signature re on File

FROM: Edward See, Project Manager Risk Management Department

SUBJECT: Indoor Air Quality (IAQ) Assessment

Portable 33C and QP1009C

On May 20, 2009 I conducted an assessment of Portable 33C and QP1009C at **Gulfstream Middle School**. This evaluation included observations of the flooring system, ceiling tiles, false ceiling plenum, environmental surfaces, interior and exterior walls, and the accessible ventilation equipment. Additionally, environmental parameter measurements were taken to include temperature, relative humidity, and carbon dioxide. The detailed findings, along with the recommended corrective action can be found on the attached IAQ Assessment Worksheets.

Generally, the IAQ Assessment did not identify any existing conditions significantly impacting IAQ and thereby presenting immediate health and safety concerns to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Please ensure that your Head Facilities Serviceperson receives a copy of this correspondence so that the recommendations requiring their attention can be addressed. Within two weeks a representative from the Custodial/Grounds Department will conduct a follow-up visit to ensure that all issues have been appropriately addressed.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact me at 754-321-1900.

cc: Dr. Joel Herbst, Area Superintendent

Dr. Gina Eyerman Area Director

Jeffrey S. Moquin, Executive Director, Support Operations

Aston A. Henry, Supervisor, Risk Management

Steve Dowling, Project Manager, Facilities and Construction Management

Jamie Daniels, Broward Teachers Union

Roy Jarrett, Federation of Public Employees

Mark Dorsett, Manager 1, Physical Plant Operations Division, Zone 1

Roy Norton, Manager Custodial/Grounds, Physical Plant Operations Division Robert Krickovich, Coordinator, LEA, Facilities and Construction Management

ES/tc Enc.

	G	Sulfstream Middle	e School	Evaluati	on Requested	April 13, 2009
Time of Day	11:40 am	]	_	E	valuation Date	May 20, 2009
Outdoor Condition	ons Ter	mperature 8	4.2 R	elative Humidity 62.6	Ambie	nt CO2 364
Fish Te P-33C  Noticeable Odo Ceiling Type Wall Type Flooring	77.7	72 - 78 dam	ive Humidity 54.8 3 (isible water age / staining? No No No	Range CO2 2503 Visible microbial growth? No No	Max 700 Amount o	> Ambient 23
	12 X 12 V	,	NO	NO		None
	Clean	Minor Dust / Debris	Needs Cleaning	Correc	ctive Action Re	equired
Ceiling	Yes	No	No			
Walls	Yes	No	No			
Flooring	Yes	No	No			
HVAC Supply G	rills Yes	No	No			
HVAC Return G	rills No	Yes	Yes	Clean with	h Wexcide dis	infectant
Ceiling at Suppl Grills	ly				N/A	
Surfaces in Roo	om No	Yes	Yes	Clea	an as appropri	ate
L Observations						
Findings:						

**IAQ Assessment** 

3931

**Location Number** 

## O

- Only one A/C unit was on at the time of the assessment. Turned on second unit during assessment.
- Old water stains on two light fixture covers
- Dust build up on environmental surfaces
- Dust and debris on A/C filter West A/C unit
- Dust build up on A/C return grills

## Recommendations:

## Site Based Maintenance:

- Ensure that both A/C units remain on to control temperature and CO2 levels
- Clean light fixture covers to remove staining
- Clean environmental surfaces throughout the room
- Remove and replace A/C filter West A/C unit
- Clean A/C return grills with Wexcide disinfectant solution
- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

	Gulfstream Middle Sch	<u>100l</u>	Evaluation Requested April 13, 2009			
Time of Day 11:	:40 am		Evaluation Date May 20, 2009			
Outdoor Conditions	Temperature 84.2	Relative Humidity	62.6 Ambient CO2 364			
	72 - 78  Yes  Visible damage / 9  2 x 4 Lay In  Orywall/Plaster  No	30% - 60% e water Visible micro staining? growth? es	material affected Various None			
Flooring	12 x 12 Vinyl No	o No	None			
Ceiling Walls Flooring	/ Debris Cl	Needs leaning Yes  No  No	Corrective Action Required			
HVAC Supply Grills	Yes No	No				
HVAC Return Grills	Yes No	No				
Ceiling at Supply Grills			N/A			
Surfaces in Room	No Yes [	Yes	Clean as appropriate			
Findings: - Various stained ceiling tiles throughout the portable. Active roof leaks. Currently Physical Plant Operations is working on repairing the roof Musty odor in room from roof leak - Dust build up on environmental surfaces  Recommendations: Site Based Maintenance: - Clean environmental surfaces throughout the room - Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate						

**IAQ** Assessment

3931

**Location Number**