

RISK MANAGEMENT...

managing risk with responsibility

Jeffrey S. Moquin, Director
Risk Management Department

Telephone: 754-321-3200
Facsimile: 754-321-3290

January 4, 2008

Signature on File

TO: Mr. Frank Zagari, Principal
Indian Ridge Middle School

FROM: Edward See, Project Manager
Risk Management Department

SUBJECT: Indoor Air Quality (IAQ) Assessment
Portable 397C

<u>For Custodial Supervisor Use Only</u>	
<input type="checkbox"/>	Custodial Issues Addressed
<input type="checkbox"/>	Custodial Issues Not Addressed

On November 2, 2007 I conducted a follow up assessment of Portable 397C at **Indian Ridge Middle School**. The assessment consisted of a reevaluation walkthrough of the previously identified area to assess the current condition of the location with regard to indoor air quality. This assessment included reviewing previously generated work orders, if applicable, as well as observation of the area of concern as stated in the IAQ Assessment performed on July 26, 2006. Attached are the findings of this assessment along with recommendations for further assessment, remediation, or corrective actions, if needed.

The IAQ assessment did identify one or more existing conditions impacting IAQ and has generated appropriate work orders to correct deficiencies in systems and maintenance that could contribute to decreased indoor air quality. At the time of the assessment, these concerns were not an immediate health or safety concern to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Please ensure that your Head Facilities Serviceperson receives a copy of this correspondence so that the recommendations requiring their attention can be addressed. Within two weeks a representative from the Custodial/Grounds Department will conduct a follow-up visit to ensure that all issues have been appropriately addressed.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact me at 754-321-3200.

cc: Dr. Verda Farrow, Area Superintendent
Margaret Underhill, Area Director
Jeffrey S. Moquin, Director, Risk Management
James Carballo, Project Manager, Facilities and Construction Management
Ralph Eckhardt, Broward Teachers Union
Roy Jarrett, Federation of Public Employees
Mark Dorsett, Manager 1, Physical Plant Operations Division, Zone 1
Roy Norton, Manager Custodial/Grounds, Physical Plant Operations Division
Robert Krickovich, Coordinator, LEA, Facilities and Construction Management

ES/tc
Enc.

IAQ Assessment

Location Number
 Evaluation Requested
 Evaluation Date

Indian Ridge Middle School

Time of Day

Outdoor Conditions Temperature Relative Humidity Ambient CO2

Fish	Temperature	Range	Relative Humidity	Range	CO2	Range	# Occupants
<input type="text" value="P-397C"/>	<input type="text" value="69"/>	<input type="text" value="72 - 78"/>	<input type="text" value="56.4"/>	<input type="text" value="30% - 60%"/>	<input type="text" value="813"/>	<input type="text" value="Max 700 > Ambient"/>	<input type="text" value="2"/>
Noticeable Odor		Visible water damage / staining?		Visible microbial growth?		Amount of material affected	
<input type="text" value="No"/>		<input type="text" value="Yes"/>		<input type="text" value="No"/>		<input type="text" value="Light Grids"/>	
Ceiling Type	<input type="text" value="2 x 4 Lay In"/>		<input type="text" value="Yes"/>	<input type="text" value="No"/>		<input type="text" value="None"/>	
Wall Type	<input type="text" value="Tackable"/>		<input type="text" value="No"/>	<input type="text" value="No"/>		<input type="text" value="None"/>	
Flooring	<input type="text" value="12X12 Vinyl"/>		<input type="text" value="No"/>	<input type="text" value="No"/>		<input type="text" value="None"/>	

	Clean	Minor Dust / Debris	Needs Cleaning	Corrective Action Required
Ceiling	<input type="text" value="Yes"/>	<input type="text" value="No"/>	<input type="text" value="No"/>	<input type="text"/>
Walls	<input type="text" value="No"/>	<input type="text" value="Yes"/>	<input type="text" value="Yes"/>	<input type="text" value="Repair/replace wall material"/>
Flooring	<input type="text" value="Yes"/>	<input type="text" value="No"/>	<input type="text" value="No"/>	<input type="text"/>
HVAC Supply Grills	<input type="text" value="Yes"/>	<input type="text" value="No"/>	<input type="text" value="No"/>	<input type="text"/>
HVAC Return Grills	<input type="text" value="Yes"/>	<input type="text" value="No"/>	<input type="text" value="No"/>	<input type="text"/>
Ceiling at Supply Grills	<input type="text" value="Yes"/>	<input type="text" value="No"/>	<input type="text" value="No"/>	<input type="text"/>
Surfaces in Room	<input type="text" value="Yes"/>	<input type="text" value="No"/>	<input type="text" value="No"/>	<input type="text"/>

Observations

Findings:

- Temperature was low at the time of the assessment and was adjusted locally
- Multiple light grids are rusted
- Elevated moisture in East and West walls (25-45% WME). No visible water stains. Walls slightly bulging.

Recommendations:

Site Based Maintenance:

- Temperature should be set to between 72-78 degrees
- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

Physical Plant Operations

- Evaluate cause of rusted light grids and repair as appropriate. Repair/replace light grids as appropriate.
- Evaluate cause of elevated moisture in East and West walls and repair as appropriate. Repair/replace wall material as appropriate.

Previous assessment 7/26/06