

managing risk with responsibility

Telephone: 754-321-3200 Facsimile: 754-321-3290

Jeffrey S. Moquin, Director Risk Management Department

October 25, 2006 Signature on File

TO: Mr. Washington Collado, Principal

Lyons Creek Middle School

FROM: Aston A. Henry, Jr., Supervisor

Risk Management Department

SUBJECT: Indoor Air Quality (IAQ) Assessment

Portable 44N and 998C

On October 9, 2006 I conducted an assessment of Portable 44N and 998C at **Lyons Creek Middle School**. This evaluation included observations of the flooring system, ceiling tiles, false ceiling plenum, environmental surfaces, interior and exterior walls, and the accessible ventilation equipment. The detailed findings, along with the recommended corrective action can be found on the attached IAQ Assessment Worksheets.

The IAQ assessment did identify one or more existing conditions impacting IAQ and has generated appropriate work orders to correct deficiencies in systems and maintenance that could contribute to decreased indoor air quality. At the time of the assessment, these concerns were not an immediate health or safety concern to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact me at 754-321-3200.

cc: Dr. Joanne Harrison, Area Superintendent

Sharon Airaghi, Area Director

Jeffrey S. Moquin, Director, Risk Management

Dave DeWald, Project Manager, Facilities and Construction Management

Jamie Daniels, Broward Teachers Union

Mark Dorsett, Manager 1, Physical Plant Operations Division, Zone 1

Roy Norton, Manager Custodial/Grounds, Physical Plant Operations Division Robert Krickovich, Coordinator, LEA, Facilities and Construction Management

AAH/tc Enc.

	Lyc	ons Creek Midd	lie School		Evaluati	ion Requested	October	9, 2000
Time of Day	12:54 pm]			E	Evaluation Date	October	9, 2006
Outdoor Condi	tions Ten	nperature	89.1 F	Relative Humid	dity 46.1	Ambie	nt CO2	375
Fish	Temperature	Range Rela	ative Humidity	Range	CO2	Ran	ge # C	Occupants
P-44N		72 - 78	44.6	30% - 60%	2633	 -	> Ambient	17
Noticeable Odor Yes			Visible water Visible micro damage / staining? growth?			, initiality of material		
Ceiling Type	Gypsum B	oard	No	No			None	
Wall Type	Gypsum B	oard	Yes			Various		
Flooring	Tile	Tile No		No)	None		
	Clean	Minor Dust / Debris	Needs Cleaning		Correc	ctive Action Re	equired	
Ceiling	Yes	No	No					
Walls	No	Yes	Yes		Repair/re	eplace as appr	opriate	
Flooring	Yes	No	No					
HVAC Supply	Grills No	Yes	Yes		Clean wit	h Wexcide disi	infectant	
HVAC Return	Grills					N/A		
Ceiling at Sup Grills	ply Yes	No	No					
Surfaces in Ro	oom Yes	No	No					

IAQ Assessment

3101

Location Number

Observations

Findings:

- Elevated moisture content in East wall under A/C unit and South wall under all windows
- Dust and debris on HVAC supply grills
- Dust and debris on HVAC coils
- Rotted wood on exterior of portable around windows
- A/C unit on the East wall is leaking water into the classroom and wall cavity
- CO2 level was elevated

Recommendations:

Site Based Maintenance:

- Clean HVAC supply grills with Wexcide disinfectant solution
- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

Physical Plant Operations:

- Evaluate cause of water intrusion in East and South walls and repair. Repair/replace wall material as appropriate.
- Clean HVAC coils
- Repair/replace rotted wood on exterior of portables around all windows to prevent water intrusion
- Evaluate and repair A/C unit on the East wall to stop leak
- Evaluate HVAC system for proper operation and repair as appropriate to lower CO2 level

			yons Creek	Middle School		Evaluat	ion Requested	October 9, 2006
Time of Day [12:3	30 pm				i	Evaluation Date	October 9, 2006
Outdoor Condi	itions	Т	emperature	89.1	Relative Hu	midity 46.1	Ambie	nt CO2 375
l	Temper		Range	Relative Humi	^{dity} Range	CO2	Ran	ige # Occupants
P-998C	73	3.6	72 - 78	48.2	30% - 60%	2377	Max 700	> Ambient 27
Noticeable Od	dor [Yes		Visible wat damage / staiı		e microbial rowth?	Amount of ma affected	terial
Ceiling Type		2 x 4 L	ay In	No		No		None
Wall Type	e Tackable		ble	Yes		No		/arious
Flooring	oring Tile			No		No	None	
	C	Clean	Minor I / Deb			Correc	ctive Action Re	equired
Ceiling		Yes	No	No				
Walls		No	Yes	Yes	S	Repair/r	eplace as appr	opriate
Flooring		Yes	No	No				
HVAC Supply	Grills	No	Yes	Yes	s	Clean wit	h Wexcide dis	infectant
HVAC Return	Grills						N/A	
Ceiling at Sup Grills	ply	Yes	No	No				
Surfaces in Ro	oom	Yes	No	No				
L								

IAQ Assessment

3101

Location Number

Observations

Findings:

- Elevated moisture content in North wall under windows and entire South wall
- Dust and debris on HVAC supply grills
- Dust and debris on HVAC coils
- Dust and debris on A/C filters
- Exterior siding on portable is damaged
- CO2 level was elevated

Recommendations:

Site Based Maintenance:

- Clean HVAC supply grills with Wexcide disinfectant solution
- Remove and replace A/C filters
- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

Physical Plant Operations:

- Evaluate cause of water intrusion in North and South walls and repair. Repair/replace wall material as appropriate.
- Clean HVAC coils
- Inspect exterior of portable including siding and fascia board
- Evaluate all windows for leaks and repair as appropriate
- Evaluate HVAC system for proper operation and repair as appropriate to lower CO2 level