

# managing risk with responsibility

Jeffrey S. Moquin, DirectorTelephone: 754-321-3200Risk Management DepartmentFacsimile: 754-321-3290

May 21, 2007 **Signature on File** 

TO: Mr. Washington Collado,, Principal

**Lyons Creek Middle School** 

FROM: Edward See, Project Manager

Risk Management Department

SUBJECT: Indoor Air Quality (IAQ) Assessment

FISH 001, Portable 87N, 112 and 876C

<u>I</u>	For Custodial Supervisor Use Only
	Custodial Issues Addressed
	Custodial Issues Not Addressed

On April 26, 2007 I conducted an assessment of FISH 001 and Portable 87N, 112 and 876C at Lyons Creek Middle School. This evaluation included observations of the flooring system, ceiling tiles, false ceiling plenum, environmental surfaces, interior and exterior walls, and the accessible ventilation equipment. Additionally, environmental parameter measurements were taken to include temperature, relative humidity, and carbon dioxide. The detailed findings, along with the recommended corrective action can be found on the attached IAQ Assessment Worksheets.

The IAQ assessment did identify one or more existing conditions impacting IAQ and has generated appropriate work orders to correct deficiencies in systems and maintenance that could contribute to decreased indoor air quality. At the time of the assessment, these concerns were not an immediate health or safety concern to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Please ensure that your Head Facilities Serviceperson receives a copy of this correspondence so that the recommendations requiring their attention can be addressed. Within two weeks a representative from the Custodial/Grounds Department will conduct a follow-up visit to ensure that all issues have been appropriately addressed.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact me at 754-321-3200.

cc: Dr. Joanne Harrison, Area Superintendent

Sharon Airaghi, Area Director

Jeffrey S. Moquin, Director, Risk Management

Marshall Washington, Project Manager, Facilities and Construction Management

Jamie Daniels, Broward Teachers Union

Roy Jarrett, Federation of Public Employees

Mark Dorsett, Manager 1, Physical Plant Operations Division, Zone 1

Roy Norton, Manager Custodial/Grounds, Physical Plant Operations Division

Robert Krickswich, Coordinator, LEA, Escilities and Construction Management

Robert Krickovich, Coordinator, LEA, Facilities and Construction Management

ES/tc Enc.

	Lyons Creek N	Middle School		Evaluation Requested	
Time of Day 8:	30 am			Evaluation Date April	26, 2007
Outdoor Conditions	Temperature	78.8	Relative Humidity	65.4 Ambient CO2	570
Noticeable Odor  Ceiling Type  Wall Type  Flooring	Range 73.4 72 - 78  No  2 x 4 Lay In  Drywall  Vinyl  Clean Minor D / Debri		Range 30% - 60%  Visible micro growth?  No  No  No	651 Max 700 > Ambier	# Occupants nt 10
Ceiling					
Walls Flooring	Yes No	No No			
HVAC Supply Grills		No			
HVAC Return Grills					
Ceiling at Supply Grills	Yes No	No			
Surfaces in Room	Yes No	No			
-Recommendations:	e time of the assessmonth : ance:		rowth as well as dus	t and debris accumulation and cle	ean as

3101

**Location Number** 

	Ly	ons Creek N	/liddle School		Evaluat	ion Requested
Time of Day	8:30 am				E	Evaluation Date April 26, 2007
Outdoor Condi	tions Te	mperature	78.8	Relative Humidity	65.4	Ambient CO2 570
Fish	Temperature	Range	Relative Humidity	/ Range	CO2	Range # Occupants
P-87N	78.6	72 - 78	59.5	30% - 60%	538	Max 700 > Ambient 2
Noticeable Od	lor No	]	Visible water damage / staining	Visible micro g? growth?		Amount of material affected
Ceiling Type	Wood Pa	nels	Yes	No		2 Ceiling Tiles
Wall Type	Tackab	le	No	No		None
Flooring	Carpe	t	Yes	No		At both doors
	Clean	Minor Du		}	Corre	ctive Action Required
Ceiling	No	Yes	Yes	Remo	ve and	replace stained ceiling tiles
Walls	Yes	No	No			
Flooring	No	Yes	Yes		Cle	an as appropriate
HVAC Supply	Grills No	Yes	Yes	С	lean wit	h Wexcide disinfectant
HVAC Return	Grills Yes	No	No			
Ceiling at Sup Grills	ply No	Yes	Yes	Remo	ove and	replace stained ceiling tiles
Surfaces in Ro	oom Yes	No	No			

3101

**Location Number** 

## **Observations**

#### Findings:

- 2 stained ceiling tiles at West A/C shaker unit
- Dust and debris on carpet and stains at each door
- Dust and debris on HVAC supply grills
- Dust and debris on coils of West A/C shaker unit. East A/C shaker unit not working causing elevated temperature.
- Pest droppings on East bookshelf and above circuit breaker
- Elevated moisture content (18) in North wall under dry erase board). Erase board is bowing.
- Baseboard on South wall missing 1/4 inch gap to outside
- Visible microbial growth on West light panel
- Exterior door is rotted/chipped off and fascia is rotted

#### -Recommendations:

# Site Based Maintenance:

- Thoroughly clean and sanitize carpet
- Clean HVAC supply grills with Wexcide disinfectant solution
- Clean areas to remove pest droppings
- Clean West light panel to remove microbial growth
- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

# Physical Plant Operations:

- Evaluate cause of stained ceiling tiles and repair as appropriate. Replace stained ceiling tiles as necessary.
- Evaluate East A/C shaker unit for proper operation and repair as appropriate. Clean coils on West A/C shaker unit.
- Initiate a work order for pest control to visit site
- Evaluate cause of elevated moisture content in North wall and repair as appropriate. Repair/replace wall material as appropriate.
- Replace baseboard on South wall
- Evaluate cause of rotted door and fascia (exterior) and repair as appropriate to prevent water intrusion

	Lyor	ns Creek Middle	School		⊏vaiuati	ion Requested		
Time of Day	8:30 am				E	Evaluation Date	April 2	26, 2007
Outdoor Condi	tions Tem	perature 7	8.8	Relative Hun	nidity 65.4	Ambie	nt CO2	570
Fish	Temperature R	ange Relat	ive Humidity	Range	CO2	Ran	ge #	Occupants
P-112	71.1 72	2 - 78	61.4	30% - 60%	543	Max 700	> Ambien	t 2
Noticeable Od	lor No		isible water age / staining		microbial owth?	Amount of mat affected	erial	
Ceiling Type	2 x 4 Lay I	n	Yes		No	3 Ce	iling Tiles	
Wall Type	Tackable		No	1	No		None	
Flooring	Vinyl		No		No		None	
	Clean	Minor Dust / Debris	Needs Cleaning		Correc	ctive Action Re	quired	
Ceiling	No	Yes	Yes	Ī	Remove and r	eplace stained	l ceiling ti	les
Walls	Yes	No	No					
Flooring	Yes	No	No					
HVAC Supply	Grills No	Yes	Yes		Clean wit	h Wexcide disi	nfectant	
HVAC Return	Grills No	Yes	Yes		Clean wit	h Wexcide disi	nfectant	
Ceiling at Sup Grills	ply Yes	No	No					
Surfaces in Ro	oom Yes	No	No					
hservations								

3101

**Location Number** 

# Findings:

- Portable is being used as a storage room
- 3 stained ceiling tiles
- Pest droppings
- Visible water stains in light panel
- Exterior fascia is rotted
- Seal on West A/C shaker unit is damaged
- Temperature was low and humidity level was slightly elevated

#### Recommendations:

#### Site Based Maintenance:

- Adjust the thermostat to increase the temperature. Continue to monitor condition and initiate a work order for Physical Plant Operations to evaluate the HVAC system if temperature and humidity does not improve.
- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

# Physical Plant Operations:

- Evaluate cause of stained ceiling tiles and repair as appropriate. Replace stained ceiling tiles as necessary.
- Initiate a work order for pest control to visit site
- Evaluate cause of water stains in light panel and repair as appropriate
- Evaluate exterior fascia and repair as appropriate to prevent water intrusion
- Evaluate seal on West A/C shaker unit and repair as appropriate

		<del>,</del>	- Inidaio Conoci					
Time of Day	8:30 am				E	Evaluation Date April 26, 2007		
Outdoor Condi	tions T	emperature	78.8	Relative Humidi	ty 65.4	Ambient CO2 570		
Fish	<b>Temperature</b>	Range	Relative Humidity	' Range	CO2	Range # Occupants		
P-876C	69.4	72 - 78	62.1	30% - 60%	533	Max 700 > Ambient 2		
Noticeable Odor No			Visible water damage / staining	Visible mid g? growth		Amount of material affected		
Ceiling Type	2 x 4 L	ay In	Yes	No	]	2 Ceiling Tiles		
Wall Type	Tacka	able	No	No		None		
Flooring	Vin	yl	No	No	]	None		
	Clean	Minor D		ı	Correc	ctive Action Required		
Ceiling	No	Yes	Yes	Rem	nove and i	replace stained ceiling tiles		
Walls	Yes	No	No					
Flooring	Yes	No	No					
HVAC Supply	Grills No	Yes	Yes		Clean wit	h Wexcide disinfectant		
HVAC Return	Grills No	Yes	Yes		Clean wit	h Wexcide disinfectant		
Ceiling at Support Grills	ply Yes	No	No					
Surfaces in Ro	oom No	Yes	Yes		Clea	an as appropriate		

Lyons Creek Middle School

3101

Location Number

Evaluation Requested

# **Observations**

#### Findings:

- 2 stained ceiling tiles
- East A/C shaker unit coils were iced over at the time of the assessment. Temperature was low and humidity level was slightly elevated.
- No insulation in false ceiling plenum
- Light grids throughout the portable are rusted
- Dust and debris on HVAC supply and return grills
- Dust build up on environmental surfaces

#### -Recommendations:

## Site Based Maintenance:

- · Clean HVAC supply and return grills with Wexcide disinfectant solution
- Clean environmental surfaces
- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

#### Physical Plant Operations:

- Evaluate cause of stained ceiling tiles and repair as appropriate. Replace stained ceiling tiles as necessary.
- Evaluate East A/C shaker unit for proper operation and repair as appropriate. Coils iced over.
- Evaluate false ceiling plenum and insulate as appropriate
- Evaluate rusted light grids and repair/replace as appropriate