

managing risk with responsibility

Telephone: 754-321-3200 Facsimile: 754-321-3290

Jeffrey S. Moquin, Director Risk Management Department

April 12, 2005

TO: Ms. Bettye Brown, Principal

Margate Middle School

FROM: Kenneth I. Partee, Project Manager, Occupational Health and Environmental

Control

Risk Management Department

SUBJECT: Indoor Air Quality (IAQ) Assessment

FISH 103, 120F and 225

On April 4 and 5, 2005 the IAQ Assessment Team conducted an assessment of FISH 103, 120F, and 225 at Margate Middle School. The evaluation consisted of a walkthrough of the identified areas to assess the current condition of the location with regard to indoor air quality. This assessment included observations of the carpet, floor tile, ceiling tile, interior walls, false ceiling plenum, and accessible ventilation equipment.

Attached are the findings of this assessment along with recommendations for further assessment, remediation, or corrective actions, if needed.

Generally, the IAQ Assessment did not identify any existing conditions significantly impacting IAQ and thereby presenting immediate health and safety concerns to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact me at 754-321-3200.

cc: Dr. Joanne Harrison, Area Superintendent

Sharon Airaghi, Area Director

Jeffrey S. Moquin, Director, Risk Management

Philip Kaufold, Project Manager II, Facilities and Construction Management

Ruby Fitzgerald, Broward Teachers Union

Mark Dorsett, Manager 1, Physical Plant Operations Division, Zone 1

Roy Norton, Manager Custodial/Grounds, Physical Plant Operations Division Robert Krickovich, Coordinator, LEA, Facilities and Construction Management

KP/tc Enc.

IAQ Assessment

		Margate Middle	e School		Evaluati	ion Requested /	April 4, 2005
Time of Day	3:05 pm				E	Evaluation Date /	April 4, 2005
Outdoor Cond	litions To	emperature	77.5	Relative Humidity	41.1	Ambient CO	2 455
Fish	Temperature	Range R	Relative Humidity	Range	CO2	Range	# Occupants
103	77.5	72 - 78	43	30% - 60%	936	< 1,000 PPM	4
Noticeable Oc	dor No	コ ,	Visible water damage / staining	Visible micro g? growth?		Amount of material affected	
Ceiling Type	2 x 4 La	ay In	Yes	Yes		4 Ceiling 1	Γiles
Wall Type	Plast	er	No	No		None	
Flooring	Carp	et	No	No		None	
	Clean	Minor Du / Debris			Correc	ctive Action Require	d
Ceiling	No	Yes	Yes		Rep	lace Ceiling Tiles	
Walls	Yes	No	No				
Flooring	Yes	No	No				
HVAC Supply	Grills No	Yes	Yes	C	lean wit	h Wexcide Disinfect	ant
HVAC Return	Grills No	Yes	Yes	C	lean wit	h Wexcide Disinfect	ant
Ceiling at Sup Grills	oply No	Yes	Yes		Clea	an as appropriate	
Surfaces in R	oom Yes	No	No				

Observations

Findings:

- Microbial growth on ceiling due to past leak
- Conduits in false ceiling require sealing
- Dust and debris on HVAC supply and return grills
- Minor dust and debris on ceiling at supply grills

Recommendations:

Site Based Maintenance:

- Remove and replace ceiling tiles
- Clean HVAC supply and return grills with wexcide disinfectant solution
- Clean ceiling at supply grills as appropriate
- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

Physical Plant Operations Division:

- Seal two conduits in false ceiling to prevent future leaks

IAQ Assessment

		Margate Mid	dle School		Evaluat	ion Requested	Apr	ril 4, 2005
Time of Day	3:05 pm				I	Evaluation Date	Apr	ril 4, 2005
Outdoor Condit	tions	Temperature	77.5	Relative Humidity	41.1	Ambie	nt CO2 [455
Fish 7	Temperature	Range	Relative Humidity	y Range	CO2	Ran	ge	# Occupants
120F	74.5	72 - 78	44.2	30% - 60%	1033	< 1,000	PPM	5
Noticeable Od	or No		Visible water damage / stainin	Visible micro g? growth?		Amount of mat affected	erial	
Ceiling Type	2 x 4 Lay In		Yes No			Ceiling Tiles at Suppl		ply Grill
Wall Type	Plaster		No	No		None		
Flooring	Car	pet	No	No			None	
	Clean	Minor D			Corre	ctive Action Re	quired	
Ceiling	Yes	No	No					
Walls	Yes	No	No					
Flooring	No	Yes	Yes	Ren	nove Ca	rpet and Replac	ce with 1	Гile
HVAC Supply	Grills Yes	No	No					
HVAC Return (Grills Yes	No	No					
Ceiling at Supp Grills	ply No	Yes	Yes		Replace	Stained Ceilin	g Tiles	
Surfaces in Ro	oom Yes	No	No					

Observations

Findings:

- Stained ceiling tiles at supply grill
- Carpet is stained
- Need HVAC return grill on occupant door
- Missing HVAC supply and return grills
- Possible diverter installed on supply grill

Recommendations:

Site Based Maintenance:

- Remove and replace stained ceiling tiles at supply grill and insulate as needed
- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

Physical Plant Operations Division:

- Remove carpet and replace with tile
- Install return grill to occupant door
- Replace missing HVAC supply and return grills
- Evaluate and repair supply grill as appropriate

IAQ Assessment

	M	largate Middle S	chool		Evaluation R	equested	April 4, 2005
Time of Day	9:30 am				Evalu	ation Date	April 5, 2005
Outdoor Condi	tions Te	mperature 7	'6.6	Relative Humidity	55.8	Ambien	t CO2 459
Fish	Temperature	Range Rela	tive Humidity	Range	CO2	Rang	e # Occupants
225	68.2	72 - 78	63.2	30% - 60%	848	< 1,000	PPM 8
Noticeable Od	lor No		/isible water nage / staining?	Visible micro growth?		ount of mate affected	erial
Ceiling Type	2 x 4 Lay	/ In	No	No		N	None
Wall Type	Drywall		No	No None		lone	
Flooring	Tile		No	No		ı	None
	Clean	Minor Dust / Debris	Needs Cleaning		Corrective	Action Req	juired
Ceiling	No	Yes	Yes	Ceiling ti	iles to be rep	laced by H	ead Custodian
Walls	Yes	No	No				
Flooring	No	Yes	Yes		Clean and	Sanitize FI	oor
HVAC Supply Grills No Ye		Yes	Yes	С	Clean with Wexcide Disinfectant		
HVAC Return	Grills				Unable to lo	cate return	grill
Ceiling at Sup Grills	ply No	Yes	Yes	Replac	ce ceiling tile	s with new	ceiling tiles
Surfaces in Ro	oom Yes	No	No				

Observations

Findings:

- School is in the process of replacing ceiling tiles
- Room is very cold
- Exhaust fans in 225B and 225C not functioning properly
- Dust and debris on floor
- Dust and debris on HVAC supply grill

Recommendations:

Site Based Maintenance:

- Remove and replace ceiling tile
- Clean and sanitize floor
- Clean HVAC supply grill with wexcide disinfectant solution
- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

Physical Plant Operations Division:

- Evaluate and repair HVAC and thermostat as appropriate
- Evaluate and repair exhaust fans in 225B and 225C as appropriate