

Aston A. Henry, Supervisor Risk Management Department

TO:

FROM:

# managing risk with responsibility

Telephone: 754 321-1900 Fax: 754 321-1917

April 16, 2012 Signature on File For Custodial Supervisor Use Only Custodial Issues Addressed Bradford Mattair, Principal Parkway Middle School Custodial Issues Not Addressed Richard Rosa, Project Manager Facilities and Construction Management SUBJECT: Indoor Air Quality (IAQ) Assessment

On February 3, 2012, I conducted an assessment at Parkway Middle School. Attached are findings and recommendations for further assessment, remediation, or corrective actions needed.

The IAQ assessment did identify one or more existing conditions impacting IAQ and has generated appropriate work orders to correct deficiencies in systems and maintenance that could contribute to decreased indoor air quality. At the time of the assessment, these concerns were not an immediate health or safety concern to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Please ensure that your Head Facilities Serviceperson receives a copy of this correspondence so that the recommendations requiring their attention can be addressed. In an attempt to separate IAQ issues from general maintenance items, the attached assessment may contain direction for site based staff to generate a work order through COMPASS. Within two weeks a representative from the Custodial/Grounds Department will conduct a follow-up visit to ensure that all site based custodial issues have been appropriately addressed.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact us at 754-321-1907.

Area Superintendent cc:

> Area Directors Shelley Meloni, Executive Director, Facilities and Construction Management Mark Dorsett, Acting Director, Physical Plant Operations Division, Maintenance Sonja Coley, Project Manager III, Facilities and Construction Management Roy Norton, Manager Custodial/Grounds, Physical Plant Operations Division Aston Henry, Supervisor, Risk Management Broward Teachers Union Federation of Public Employees

RR/tc Enc.

			IAQ Ass	sessment	Location Nu	mber		
		Parkway Middl	e School		Evaluation Re	equested	Januar	y 31, 2012
Time of Day	1:00	]			Evalua	ation Date	March	n 3, 2012
Outdoor Cond	litions Ter	nperature 7	5.8	Relative Humidity	66	Ambie	nt CO2	457
Fish	Temperature	Range Rela	tive Humidity	Range	CO2	Ran	ige #	Occupants
140	71.1	72 - 78	51.8	30% - 60%	1670	Max 700	> Ambien	t 27
Noticeable O	dor No	-	'isible water age / stainingʻ	Visible micro ? growth?		Amount or aterial affect		
Ceiling Type	2 x 4 Lay	<sup>,</sup> In	Yes	No		2 ceiling til	es (5 squa	re feet)
Wall Type	Drywal	I	No	No			None	
Flooring	12 x 12 Vi	nyl	No	No			None	
	Clean	Minor Dust / Debris	Needs Cleaning		Corrective	Action Re	equired	
Ceiling	No	Yes	Yes		Remove	and repla	ice	
Walls	Yes	No	No					
Flooring	Yes	Νο	No					
HVAC Supply	Grills No	Yes	Yes		Clean as	appropri	ate	
HVAC Return	Grills No	Yes	Yes		Clean as	appropri	ate	
Ceiling at Sup Grills	oply Yes	No	No					
Surfaces in R	oom No	Yes	Yes		Clean as	appropri	ate	

#### Findings

- Dust build up on surfaces
- Dust build up on HVAC supply and return grills
- Slightly elevated CO2 level
- Stained ceiling tiles

## Site Based Maintenance:

- Thoroughly clean all surfaces throughout the room
- Clean HVAC supply and return grills with Wexcide disinfectant solution
- Remove and replace outside air filters for all units more frequently due to irrigation work outside the classrooms.
- Remove and replace stained ceiling tiles as necessary.

- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

## Physical Plant Operations:

- Evaluate HVAC system for proper operation and repair as appropriate to lower CO2
- Evaluate for cause of stained ceiling tiles and repair as appropriate. Remove and replace ceiling tiles as necessary.

			IAQ Asse	essment	Location Nu	ımber		
		Parkway Middl	e School		Evaluation R	equested	January	y 31, 2012
Time of Day	1:00				Evalua	ation Date	March	n 3, 2012
Outdoor Condi	tions Terr	perature 7	'5.8 R	Relative Humidity	66	Ambie	nt CO2	457
Fish	Temperature	Range Rela	tive Humidity	Range	CO2	Ran	ige #	Occupants
160	73.4 <b>7</b>	2 - 78	53.5 3	30% - 60%	1222	Max 700	> Ambien	t 27
Noticeable Od	lor No		/isible water age / staining?	Visible micro growth?		Amount of aterial affect		
Ceiling Type	2 x 4 Lay	In	No	No			None	
Wall Type	Drywall		No	No			None	
Flooring	12 x 12 Vir	iyl	No	No			None	
	Clean	Minor Dust / Debris	Needs Cleaning		Corrective	Action Re	equired	
Ceiling	Yes	No	No					
Walls	Yes	No	No					
Flooring	Yes	No	No					
HVAC Supply	Grills No	Yes	Yes		Clean as	appropri	ate	
HVAC Return	Grills No	Yes	Yes		Clean as	appropri	ate	
Ceiling at Sup Grills	ply No	Yes	Yes		Clean as	appropri	ate	
Surfaces in Ro	oom No	Yes	Yes		Clean as	appropri	ate	

Findings

- Dust build up on surfaces

- Dust build up on HVAC supply and return grills and ceiling at supply grills

- Slightly elevated CO2 level

## Site Based Maintenance:

- Thoroughly clean all surfaces throughout the room

- Clean HVAC supply and return grills with Wexcide disinfectant solution and wipe down ceiling at supply grills

- Remove and replace outside air filters for all units more frequently due to irrigation work outside the classrooms.

- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

# Physical Plant Operations:

- Evaluate HVAC system for proper operation and repair as appropriate to lower CO2

			IAQ Asso	essment	Location Nu	ımber		
		Parkway Middl	e School		Evaluation R	equested	Januar	y 31, 2012
Time of Day	1:00				Evalu	ation Date	March	n 3, 2012
Outdoor Condi	tions Terr	perature 7	75.8 F	Relative Humidity	66	Ambie	nt CO2	457
Fish	Temperature	Range Rela	tive Humidity	Range	CO2	Ran	nge #	Occupants
161A	73.5 <b>7</b>	2 - 78	74.1	30% - 60%	657	Max 700	> Ambien	nt
Noticeable Od	lor No		/isible water hage / staining?	Visible micro growth?		Amount of aterial affect		
Ceiling Type	2 x 4 Lay	In	No	No			None	
Wall Type	Drywall		No	No			None	
Flooring	12 x 12 Vir	iyl	No	No			None	
	Clean	Minor Dust / Debris	Needs Cleaning		Corrective	Action Re	equired	
Ceiling	Yes	No	No					
Walls	Yes	No	Νο					
Flooring	Yes	No	Νο					
HVAC Supply	Grills No	Yes	Yes		Clean as	appropri	ate	
HVAC Return	Grills No	Yes	Yes		Clean as	appropri	ate	
Ceiling at Sup Grills	ply No	Yes	Yes		Clean as	appropri	ate	
Surfaces in Ro	oom No	Yes	Yes		Clean as	appropri	ate	

#### Findings

- Dust build up on surfaces

- Dust build up on HVAC supply and return grills and ceiling at supply grills

- Humidity level elevated

## Site Based Maintenance:

- Thoroughly clean all surfaces throughout the room

- Clean HVAC supply and return grills with Wexcide disinfectant solution and wipe down ceiling at supply grills

- Remove and replace outside air filters for all units more frequently due to irrigation work outside the classrooms.

- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

## Physical Plant Operations:

- Evaluate HVAC system for proper operation and repair as appropriate to lower humidity

			IAQ Ass	essment	Location Nu	mber		
		Parkway Middl	e School		Evaluation R	equested	Januar	/ 31, 2012
Time of Day	1:00				Evalua	ation Date	March	3, 2012
Outdoor Condi	tions Terr	perature 7	75.8 F	Relative Humidity	66	Ambie	nt CO2	457
Fish	Temperature	Range Rela	tive Humidity	Range	CO2	Ran	ige #	Occupants
162	68.2 <b>7</b>	2 - 78	55.6	30% - 60%	1273	Max 700	> Ambien	t 22
Noticeable Od	lor No		/isible water hage / staining?	Visible micro growth?		Amount of aterial affect		
Ceiling Type	2 x 4 Lay	In	No	No			None	
Wall Type	Drywall		No	No			None	
Flooring	12 x 12 Vir	iyl	No	No			None	
	Clean	Minor Dust / Debris	Needs Cleaning		Corrective	Action Re	equired	
Ceiling	Yes	No	No					
Walls	Yes	No	Νο					
Flooring	Yes	No	No					
HVAC Supply	Grills No	Yes	Yes		Clean as	appropri	ate	
HVAC Return	Grills No	Yes	Yes		Clean as	appropri	ate	
Ceiling at Sup Grills	ply No	Yes	Yes		Clean as	appropri	ate	
Surfaces in Ro	oom No	Yes	Yes		Clean as	appropri	ate	

Findings

- Dust build up on surfaces

- Dust build up on HVAC supply and return grills and ceiling at supply grills

- Slightly elevated CO2 level

## Site Based Maintenance:

- Thoroughly clean all surfaces throughout the room

- Clean HVAC supply and return grills with Wexcide disinfectant solution and wipe down ceiling at supply grills

- Remove and replace outside air filters for all units more frequently due to irrigation work outside the classrooms.

- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

# Physical Plant Operations:

- Evaluate HVAC system for proper operation and repair as appropriate to lower CO2

			IAQ Asse	essment	Location Nu	mber		
		Parkway Middle	e School		Evaluation Re	equested	Januar	y 31, 2012
Time of Day	1:00				Evalua	ation Date	March	ח 3, 2012
Outdoor Cond	itions Ten	nperature 7	5.8 R	elative Humidity	66	Ambie	nt CO2	457
Fish	Temperature	Range Relat	ive Humidity	Range	CO2	Ran	ige #	# Occupants
167	74.3 7	<b>′</b> 2 - 78	76 <b>3</b>	0% - 60%	695	Max 700	> Ambien	t
Noticeable O	dor No		isible water age / staining?	Visible micro growth?		Amount of terial affect		
Ceiling Type	2 x 4 Lay	In	Yes	No		1 so	quare foot	
Wall Type	Drywall		No	No			None	
Flooring	12 x 12 Vir	nyl	No	No			None	
	Clean	Minor Dust / Debris	Needs Cleaning		Corrective	Action Re	equired	
Ceiling	No	Yes	Yes		Remove	and repla	ice	
Walls	Yes	No	Νο					
Flooring	Yes	No	No					
HVAC Supply	Grills No	Yes	Yes		Clean as	appropri	ate	
HVAC Return	Grills No	Yes	Yes		Clean as	appropri	ate	
Ceiling at Sup Grills	oply No	Yes	Yes		Clean as	appropri	ate	
Surfaces in R	oom No	Yes	Yes		Clean as	appropri	ate	

#### Findings

- Dust build up on surfaces
- Dust build up on HVAC supply and return grills
- Humidity level elevated
- Stained ceiling tiles

## Site Based Maintenance:

- Thoroughly clean all surfaces throughout the room
- Clean HVAC supply and return grills with Wexcide disinfectant solution
- Remove and replace outside air filters for all units more frequently due to irrigation work outside the classrooms.
- Remove and replace stained ceiling tiles as necessary.

- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

## Physical Plant Operations:

- Evaluate HVAC system for proper operation and repair as appropriate to lower humidity
- Evaluate for cause of stained ceiling tiles and repair as appropriate. Remove and replace ceiling tiles as necessary.