

managing risk with responsibility

Jeffrey S. Moquin, Director Risk Management Department Telephone: 754-321-3200 Facsimile: 754-321-3290

| September 5, 20 | 007 Signature on File |
|-----------------|-------------------------------------------------------------------------------|
| TO: | Mr. David Olafson,, Principal Plantation Middle School |
| FROM: | Robert Krickovich, Coordinator, LEA Facilities and Construction Management |
| SUBJECT: | Indoor Air Quality (IAQ) Assessment FISH 150C, 152G, 160 and 201 |

| Fo | r Custodial Supervisor Use Only |
|----|---------------------------------|
| | Custodial Issues Addressed |
| 1 | Custodial Issues Not Addressed |
| | |

On August 16, 2007 I conducted an assessment of FISH 150C, 152G, 160 and 201 at **Plantation Middle School**. This evaluation included observations of the flooring system, ceiling tiles, false ceiling plenum, environmental surfaces, interior and exterior walls, and the accessible ventilation equipment. Additionally, environmental parameter measurements were taken to include temperature, relative humidity, and carbon dioxide. The detailed findings, along with the recommended corrective action can be found on the attached IAQ Assessment Worksheets.

The IAQ assessment did identify one or more existing conditions impacting IAQ and has generated appropriate work orders to correct deficiencies in systems and maintenance that could contribute to decreased indoor air quality. At the time of the assessment, these concerns were not an immediate health or safety concern to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Please ensure that your Head Facilities Serviceperson receives a copy of this correspondence so that the recommendations requiring their attention can be addressed. Within two weeks a representative from the Custodial/Grounds Department will conduct a follow-up visit to ensure that all issues have been appropriately addressed.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact me at 754-321-1638.

cc: Dr. Verda Farrow, Area Superintendent Jan Beal, Area Director Jeffrey S. Moquin, Director, Risk Management Wayne Thrasher, Project Manager, Facilities and Construction Management Ruby Fitzgerald, Broward Teachers Union Roy Jarrett, National Federation of Public and Private Employees Mark Dorsett, Manager 1, Physical Plant Operations Division, Zone 1 Roy Norton, Manager Custodial/Grounds, Physical Plant Operations Division

RK/tc Enc.

| | | | IAQ As | sessment | Locati | on Number | 0551 | |
|---------------------------|------------|------------------------|--------------------------------|--------------------------|---------|--------------------------|--------------|-----------|
| | Р | lantation Middle | e School | | Evaluat | tion Requested | August | 10, 2007 |
| Time of Day | 10:10 am | | | | | Evaluation Date | August | 16, 2007 |
| Outdoor Condit | ions Tem | perature 82 | 2.4 | Relative Humidit | y 85.9 | Ambie | nt CO2 | 538 |
| | | ange Relat | ive Humidity | Range | CO2 | Ran | ige # | Occupants |
| 150C | 68.5 72 | 2 - 78 | 56.6 | 30% - 60% | 645 | Max 700 | > Ambient | t 2 |
| Noticeable Odd | or No | | isible water age / staining | Visible mic g? growth | | Amount of ma affected | terial | |
| Ceiling Type | Drywall | | No | Yes |] | Spotty - pr | eviously cl | eaned |
| Wall Type | Drywall | | No | Yes |] | Spotty - pr | eviously cle | aned |
| Flooring | Carpet | | No | No |] | | None | |
| | Clean | Minor Dust / Debris | Needs Cleaning | | Corre | ctive Action Re | equired | |
| Ceiling | Νο | Yes | Yes | | (| Clean and paint | t | |
| Walls | No | Yes | Yes | | (| Clean and paint | 1 | |
| Flooring | Yes | No | No | | | | | |
| HVAC Supply G | Srills Yes | No | No | | | | | |
| HVAC Return G | Grills Yes | No | No | | | | | |
| Ceiling at Supp Grills | ly | | | | | N/A | | |
| Surfaces in Roo | om Yes | No | No | | | | | |

Findings:

- Visible microbial growth on pictures that are hanging on the wall. Growth is behind the glass in the frame.

- Temperature was low. All rooms in this area are also too cold.

- Ceilings and walls in this room as well as all rooms in this area are heavily spotted and stained

-Recommendations:

Site Based Maintenance:

- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

Physical Plant Operations:

- Evaluate HVAC for proper operation and repair as appropriate to increase temperature and lower humidity levels in all rooms within this area.

- Clean/sand ceilings and walls in all rooms in this area and paint with anti-microbial paint

| | | | IAQ As | sessment | Location N | umber | 0551 | |
|---------------------------|---------------|------------------------|----------------------------------|--------------------------|--------------|-------------------------|------------|-----------|
| | F | Plantation Midd | lle School | | Evaluation F | Requested | August | 10, 2007 |
| Time of Day | 10:10 am | | | | Evalu | ation Date | August | 16, 2007 |
| Outdoor Condit | ions Tem | perature | 82.4 | Relative Humidity | 85.9 | Ambie | nt CO2 | 538 |
| Fish T | emperature F | Range Rela | ative Humidity | Range | CO2 | Ran | ge # | Occupants |
| 152G | 69.2 7 | 2 - 78 | 53.7 | 30% - 60% | 1018 | Max 700 | > Ambient | 2 |
| Noticeable Odd | or No | | Visible water mage / staining | Visible micro growth? | obial Arr | nount of ma affected | terial | |
| Ceiling Type | 2 x 4 Lay | In | Yes | No | | N N | /arious | |
| Wall Type | Drywall | | Yes | Yes | | | All | |
| Flooring | 12 x 12 Vir | ıyl | No | No | | | None | |
| | Clean | Minor Dust / Debris | Needs Cleaning | | Corrective | Action Re | equired | |
| Ceiling | No | Yes | Yes | Re | emove and | replace cei | ling tiles | |
| Walls | No | Yes | Yes | | Clean/sa | and and pa | int | |
| Flooring | Yes | Νο | No | | | | | |
| HVAC Supply G | Grills No | Yes | Yes | C | lean with W | excide dis | infectant | |
| HVAC Return G | Grills Yes | Νο | No | | | | | |
| Ceiling at Supp Grills | ly Yes | No | No | | | | | |
| Surfaces in Roo | om Yes | No | No | | | | | |

Findings: Elevator Equipment Room

- Walls are dry with visible minor spotty microbial growth throughout
- Daylight visible through return grill in ceiling
- Stained ceiling tiles
- Water dripping from roof duct bad damper or exhaust fan on roof allowing water into the building
- Dust and debris on HVAC supply grills
- Temperature was low. All rooms in this area are also too cold.

-Recommendations:

Site Based Maintenance:

- Clean HVAC supply grills with Wexcide disinfectant solution
- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

Physical Plant Operations:

- Evaluate return grill in ceiling daylight is visible
- Evaluate and repair cause of water intrusion into room water dripping from roof duct bad damper or exhaust fan on roof. Remove and replace stained ceiling tiles as appropriate.
- Clean/sand all walls and paint with anti-microbial paint

| | | | IAQ Ass | sessment | Locatio | on Number | 0551 | |
|----------------------------|--------------|------------------------|--------------------------------|-----------------------|---------|---------------------------|----------|-----------|
| | Pla | antation Middle | e School | | Evaluat | ion Requested | August | 10, 2007 |
| Time of Day | 10:10 am | | | | E | Evaluation Date | August | 16, 2007 |
| Outdoor Conditio | ons Temp | erature 8 | 2.4 | Relative Humidi | ty 85.9 | Ambie | nt CO2 | 538 |
| | mperature Ra | ange Relat | ive Humidity | Range | CO2 | Ran | ige # | Occupants |
| 160 | 72 | - 78 | | 30% - 60% | | Max 700 | > Ambien | t |
| Noticeable Odo | r No | | isible water age / staining | Visible mi ? growt | | Amount of mat affected | terial | |
| Ceiling Type | Drywall | | Νο | Yes | | | All | |
| Wall Type | Drywall | | No | Yes |] | | All | |
| Flooring | | | No | No |] | | None | |
| | Clean | Minor Dust / Debris | Needs Cleaning | | Correc | ctive Action Re | equired | |
| Ceiling | Νο | Yes | Yes | | S | crape and pain | t | |
| Walls | Νο | Yes | Yes | | S | crape and pain | t | |
| Flooring | Yes | No | No | | | | | |
| HVAC Supply G | rills Yes | No | No | | | | | |
| HVAC Return G | rills Yes | Νο | No | | | | | |
| Ceiling at Suppl Grills | y Yes | No | No | | | | | |
| Surfaces in Roo | m Yes | No | No | | | | | |

Findings:

- HVAC duct is sweating and dripping onto the floor

- Visible microbial growth on ceiling and walls and paint is blistering

-Recommendations:

Site Based Maintenance:

- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

Physical Plant Operations:

- Repair/insulate HVAC duct to prevent sweating and dripping

- Scrape ceiling and walls and paint with anti-microbial paint

| | | | IAQ Ass | sessment | Location | n Number | 0551 | |
|--------------------------|-------------|-----------------------|-----------------------------------|----------------------------|-----------|---------------------------|--------------|-----------|
| | | Plantation Mic | ddle School | | Evaluatio | on Requested | August | 10, 2007 |
| Time of Day | 10:10 am | | | | Ev | valuation Date | August | 16, 2007 |
| Outdoor Cond | itions Te | mperature | 82.4 | Relative Humidity | 85.9 | Ambie | nt CO2 | 538 |
| Fish | Temperature | Range Re | elative Humidity | Range | CO2 | Ran | ge # | Occupants |
| 201 | 68.3 | 72 - 78 | 60.2 | 30% - 60% | 651 | Max 700 | > Ambient | t 1 |
| Noticeable Oc | dor No | da | Visible water amage / staining | Visible micro ? growth? | | Amount of mat affected | terial | |
| Ceiling Type | 2 x 4 La | y In | Νο | No | | | None | |
| Wall Type | Plaste | r | Yes | No | | Concrete w | all near ele | evator |
| Flooring | 12 x 12 V | ′inyl | No | No | Γ | | None | |
| | Clean | Minor Dus / Debris | t Needs Cleaning | | Correct | ive Action Re | equired | |
| Ceiling | Yes | No | No | | | | | |
| Walls | Yes | No | No | | | | | |
| Flooring | Yes | Νο | No | | | | | |
| HVAC Supply | Grills Yes | No | No | | | | | |
| HVAC Return | Grills Yes | Νο | No | | | | | |
| Ceiling at Sup Grills | oply Yes | No | No | | | | | |
| Surfaces in R | oom Yes | No | No | | | | | |

Findings:

- Visible minor spotty microbial growth on concrete wall at elevator

- Temperature was low and humidity level was slightly elevated

-Recommendations:

Site Based Maintenance:

- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

Physical Plant Operations:

- Clean/sand all walls and paint with anti-microbial paint

- Evaluate HVAC for proper operation and repair as appropriate to increase temperature and lower humidity level