

FISH 317, 320 and 323

# managing risk with responsibility

Jeffrey S. Moquin, DirectorTelephone:754-321-3200Risk Management DepartmentFacsimile:754-321-3290

March 17, 2008	Signature on File	For Custodial Supervisor Use Only				
TO:	Ms. Kathryn Sullivan, Principal Silver Lakes Middle School	Custodial Issues Addressed  Custodial Issues Not Addressed				
FROM:	Edward See, Project Manager Risk Management Department					
SUBIECT:	Indoor Air Quality (IAO) Assessment					

On February 13, 2008 I conducted an assessment of FISH 317, 320 and 323 at **Silver Lakes Middle School**. This evaluation included observations of the flooring system, ceiling tiles, false ceiling plenum, environmental surfaces, interior and exterior walls, and the accessible ventilation equipment. Additionally, environmental parameter measurements were taken to include temperature, relative humidity, and carbon dioxide. The detailed findings, along with the recommended corrective action can be found on the attached IAQ Assessment Worksheets.

The IAQ assessment did identify one or more existing conditions impacting IAQ and has generated appropriate work orders to correct deficiencies in systems and maintenance that could contribute to decreased indoor air quality. At the time of the assessment, these concerns were not an immediate health or safety concern to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Please ensure that your Head Facilities Serviceperson receives a copy of this correspondence so that the recommendations requiring their attention can be addressed. Within two weeks a representative from the Custodial/Grounds Department will conduct a follow-up visit to ensure that all issues have been appropriately addressed.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact me at 754-321-3200.

cc: Dr. Joanne Harrison, Area Superintendent
Sharon Airaghi, Area Director
Jeffrey S. Moquin, Director, Risk Management
Denise Cone, Project Manager, Facilities and Construction Management
Ruby Fitzgerald, Broward Teachers Union
Roy Jarrett, Federation of Public Employees
Mark Dorsett, Manager 1, Physical Plant Operations Division, Zone 1
Roy Norton, Manager Custodial/Grounds, Physical Plant Operations Division
Robert Krickovich, Coordinator, LEA, Facilities and Construction Management

ES/tc Enc.

	Si	iver Lakes Middl	e School		Evaluation	Requested Febr	uary 1, 2008
Time of Day	2:45 pm				Eval	uation Date Febru	uary 13, 2008
Outdoor Conditi	ions Ter	mperature 7	2.2	Relative Humidity	74.4	Ambient CO2	475
l	emperature		tive Humidity	- Range	CO2	Range	# Occupants
317	74.6	72 - 78	62.5	30% - 60%	1028	<b>│</b> Max 700 > Ambi	ent 22
Noticeable Odo	or No		/isible water age / staining	Visible micro growth?		nount of material affected	
Ceiling Type	2 x 4 Lay	/ In	Yes	No		2 ceiling tile	es
Wall Type	Wall Type Plaster/Drywall		No No			None	
Flooring	Carpet	i	No	No		None	
	Clean	Minor Dust / Debris	Needs Cleaning		Corrective	e Action Required	
Ceiling	No	Yes	Yes	Remo	ove and rep	lace stained tiles (	PPO)
Walls	Yes	No	No				
Flooring	Yes	No	No				
HVAC Supply G	Grills Yes	No	No				
HVAC Return G	irills No	Yes	Yes	Clea	n with Wex	cide disinfectant (F	PPO)
Ceiling at Supp Grills	ly Yes	No	No				
Surfaces in Roo	om No	Yes	Yes		Clean a	as appropriate	
Observations							
- 2 stained ceiling	g tiles - require s on HVAC retu	ırn grills - elevate					
Recommendation	ons:						

**IAQ Assessment** 

**Location Number** 

# Site Based Maintenance:

- Thoroughly clean all environmental surfaces
- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

- Physical Plant Operations:
   Evaluate HVAC system for proper operation and repair as appropriate to lower humidity level
- Evaluate cause of stained ceiling tiles and repair as appropriate. Replace stained ceiling tiles.
- Clean HVAC return grills with Wexcide disinfectant solution elevated ceiling

Time of Day	2:45 pm				E	valuation Date	February 13	, 2008
Outdoor Condi	tions Tem	perature 7	72.2	Relative Humi	idity 74.4	Ambient	CO2 47	5
Fish 7	Temperature R	Range Rela	ative Humidity	Range	CO2	Range	# Oc	cupants
320	71.6 <b>7</b> 2	2 - 78	68.3	30% - 60%	911	Max 700 > /	Ambient	7
Noticeable Od	or No		Visible water nage / stainingʻ		microbial wth?	Amount of materi affected	ial	
Ceiling Type	Ceiling Type 2 x 4 Lay In		Yes No		<u>o</u> [	1 ceiling tile		
Wall Type	Plaster/Dryv	vall	Yes	Ne	0	East wall at door		
Flooring	Carpet		No	Ne	• [	None		
	Clean	Minor Dust / Debris	Needs Cleaning		Correc	tive Action Requ	uired	
Ceiling	No	Yes	Yes		Remove and replace stained tile			
Walls	No	Yes	Yes		Repair as appropriate		e	
Flooring	Yes	No	No					
HVAC Supply	Grills No	Yes	Yes		Clean with	n Wexcide disinfe	ectant	
HVAC Return (	Grills No	Yes	Yes		Clean as	s appropriate (P	PO)	
Ceiling at Supp Grills	ply No	Yes	Yes		Rem	nove and replace	)	
Surfaces in Ro	oom No	Yes	Yes		Clea	ın as appropriate	)	

IAQ Assessment

Silver Lakes Middle School

2971

February 1, 2008

Location Number
Evaluation Requested

# **Observations**

### Findings:

- Humidity level was elevated at the time of the assessment
- 1 stained ceiling tile
- Water stain on East wall at door and bubbling paint
- Dust and debris on HVAC supply and return grills and on ceiling at supply grills. Heavy dust on return grills and on ceiling tiles at supply grills elevated ceiling
- Dust build up on environmental surfaces

#### Recommendations:

#### Site Based Maintenance:

- Clean HVAC supply grills with Wexcide disinfectant solution
- Thoroughly clean all environmental surfaces
- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

### Physical Plant Operations:

- Evaluate HVAC system for proper operation and repair as appropriate to lower humidity level
- Evaluate cause of stained ceiling tile and repair as appropriate. Replace stained ceiling tile.
- Evaluate cause of water stain and bubbling paint on East wall at door and repair as appropriate. Repair/replace wall material as necessary.
- Clean HVAC return grills to remove heavy dust impaction and replace ceiling tiles at supply grills

		Silver Lakes N	liddle School		Evaluation F	Requested	Februar	y 1, 2008
Time of Day	2:45 pm				Evalu	uation Date	February	/ 13, 2008
Outdoor Cond	litions T	emperature	72.2	Relative Humidity	74.4	Ambie	nt CO2	475
Fish	Temperature	Range	Relative Humidity	Range	CO2	Ran	ge #	Occupants
323	72.1	72 - 78	67	30% - 60%	1032	Max 700	> Ambient	: 1
Noticeable O	dor Yes		Visible water damage / staining	Visible micro growth?	,	nount of mat affected	terial	
Ceiling Type	2 x 4 L	ay In	Yes	No		1 c	eiling tile	
Wall Type	Plaster/D	Drywall	No	No			None	
Flooring	Carp	et	No	No			None	
	Clean	Minor Debri			Corrective	Action Re	equired	
Ceiling	No	Yes	Yes	R	emove and	replace sta	ined tile	
Walls	Yes	No	No					
Flooring	Yes	No	No					
HVAC Supply	Grills Yes	No	No					
HVAC Return	Grills No	Yes	Yes		Clean as a	opropriate	(PPO)	
Ceiling at Sup Grills	oply Yes	No	No					
Surfaces in R	oom No	Yes	Yes		Clean a	s appropri	ate	
hservations								

IAQ Assessment

2971

February 1, 2008

**Location Number** 

Evaluation Requested

### Findings:

- Humidity level was elevated at the time of the assessment
- 1 stained ceiling tile
- Heavy dust and debris on HVAC return grills elevated ceiling
- Dust build up on environmental surfaces
- 3 broken ceiling tiles

# Recommendations:

# Site Based Maintenance:

- Thoroughly clean all environmental surfaces
- Remove and replace broken ceiling tiles
- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

# Physical Plant Operations:

- Evaluate HVAC system for proper operation and repair as appropriate to lower humidity level
- Evaluate cause of stained ceiling tile and repair as appropriate. Replace stained ceiling tile.
- Clean HVAC return grills to remove heavy dust impaction