

## managing risk with responsibility

Telephone: 754 321-3200 Fax: 754 321-3290

March 4, 2009	Signature on File	For Custodial Supervisor Use Only				
TO:	Mr. Israel Canales, Manager Administrative Sites	Custodial Issues Addressed  Custodial Issues Not Addressed				
FROM:	Edward See, Project Manager Risk Management Department					
SUBJECT:	Indoor Air Quality (IAQ) Assessment FISH 250 and 255					

On February 24, 2009 I conducted an assessment of FISH 250 and 255 at **the South Central Area Office**. This evaluation included observations of the flooring system, ceiling tiles, false ceiling plenum, environmental surfaces, interior and exterior walls, and the accessible ventilation equipment. Additionally, environmental parameter measurements were taken to include temperature, relative humidity, and carbon dioxide. The detailed findings, along with the recommended corrective action can be found on the attached IAQ Assessment Worksheets.

Generally, the IAQ Assessment did not identify any existing conditions significantly impacting IAQ and thereby presenting immediate health and safety concerns to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Please ensure that your Head Facilities Serviceperson receives a copy of this correspondence so that the recommendations requiring their attention can be addressed. Within two weeks a representative from the Custodial/Grounds Department will conduct a follow-up visit to ensure that all issues have been appropriately addressed.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact me at 754-321-3200.

cc: Dr. Verda Farrow, Area Superintendent Jeffrey S. Moquin, Executive Director, Support Operations Israel Rodriguez-Soto, Project Manager, Facilities and Construction Management Mark Dorsett, Manager 1, Physical Plant Operations Division, Zone 1 Roy Norton, Manager Custodial/Grounds, Physical Plant Operations Division Robert Krickovich, Coordinator, LEA, Facilities and Construction Management

ES/tc Enc.

		S	outh Cent	al Area C	Office			Evaluati	ion Reques	sted [		
Time of Day	1:3	0 pm						E	Evaluation [	Date [	Februar	ry 24, 2009
Outdoor Condi	tions	Ter	- nperature	76.5	٦	Relative H	umidity	46.4	ļ Δr	- mhiei	nt CO2	393
					<u> </u>	- Noidil Vo 11	unnancy					
	Temper		Range		Humidity	Range		CO2		Ran	_	Occupants
250	76	5.1	72 - 78		3.1	30% - 60%		522	Max	700 :	> Ambien	nt 10
Noticeable Od	or	No			le water / staining		ole micro growth?		Amou material	unt of		
Ceiling Type		2 x 2		_	No		No				None	
Wall Type	D	rywall/Pla	aster		No		No				None	
Flooring		Carpet			No		No				None	
	C	Clean	Minor D		Needs Cleaning			Correc	ctive Actio	on Re	quired	
Ceiling		Yes	No		No							
Walls		Yes	No	]	No							
Flooring		Yes	No		No							
HVAC Supply	Grills	Yes	No		No							
HVAC Return	Grills	Yes	No		No							
Ceiling at Sup Grills	ply	Yes	No		No							
Surfaces in Ro	oom	No	Yes	]	Yes			Cle	an as appı	ropria	ate	
L Observations												
Findings: Building is owned by Stiles and leased by SBBC - Potted plants in room - Dust build up on environmental surfaces. Personal items and storage items hinder cleaning efforts.  Recommendations: Site Based Maintenance: - Remove potted plants from room. Soil is a source of microbial growth Clean elevated surfaces as appropriate. Recommend setting up a dusting schedule to coordinate with occupants to remove and replace personal items to assist custodial staff with cleaning efforts Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate												

**IAQ Assessment** 

**Location Number** 

	South (	Central Area Office	Evaluation Requested				
Time of Day 1:30 pm Evaluation Date February 24, 2009							
Outdoor Condition	ons Tempera	ature 76.5	Relative Humidity 46	.4 Ambient CO2 393			
Fish Tel 255  Noticeable Odor Ceiling Type Wall Type Flooring  Ceiling Walls  Flooring  HVAC Supply G  HVAC Return Gi  Ceiling at Suppl Grills  Surfaces in Roo	2 x 2  Drywall/Plaster  Carpet  Clean Min /  Yes  Yes  Yes  Yes  rills Yes  y Yes	Visible water damage / staining  Yes  No  No  No  No  No  No  No  No  No  N	30% - 60% 536  Visible microbial growth?  No  No  No  Corr	Range # Occupants Max 700 > Ambient 3  Amount of material affected  Adjacent to FISH 250  None  None  ective Action Required			
Surfaces in Roo	m Yes	No No					
- Stained ceiling to Recommendation Site Based Mainton - Remove and rep	tenance: blace stained ceiling	H 250 g tiles	growth as well as dust and	I debris accumulation and clean as			

**IAQ Assessment** 

**Location Number**