Report: PPO

DREW CHARLES FAMILY RESOURCE

Walkthrough Date: 05/10/2006 Temp RH CO2
Outdoor Parameters: 85.5 65.4 369

Room	Priority	Responsible	Answer	Recommendation
108	Inside Parameters:	Temp	RH	CO2
		78.9	64.0	436
	2	PPO	Dropping observed at the time of the assessment.	Physical Plant Operation to initiate work order to evaluate pest issue within location and take appropriate action.
Room	Priority	Responsible	Answer	Recommendation
703	Inside Parameters:	Temp	RH	CO2
		72.4	62.9	552
	1	PPO	Condensation on windows at the time of assessment.	Physical Plant Operations to evaluate and repair as appropriate.
	1	PPO	Condensation on walls or surfaces at the time of assessment. Leak identified.	Physical Plant Operations to evaluate for leaks and repair as appropriate.
	1	PPO	No leaks identified. Signs of previous water intrusion as evidenced by staining.	Physical Plant Operations to evaluate and repair as appropriate.
	1	PPO	Signs of water intrusion. Stained ceiling tiles.	Physical Plant Operations to evaluate for leaks and repair as appropriate and replace ceiling tiles as appropriate.
	2	PPO	Occupant advised that temperature is very hot in the afternoon.	Physical Plant Operations to evaluate and repair as appropriate.
	2	PPO	Teacher is complaining about temperature shifts on a regular basis.	Physical Plant Operations to evaluate and repair as appropriate.
	2	PPO	Humidity was slightly elevated at the time of assessment.	Physical Plant Operations to evaluate and repair as appropriate.
	2	PPO	Environmental parameters were not within acceptable range at the time of assessment	Physical Plant Operations to evaluate and repair as appropriate.