



Jeffrey S. Moquin, Director Risk Management Department Telephone: 754-321-3200 Facsimile: 754-321-3290

October 24, 2006

Signature on File

TO:	Ms. Tracy Lockhart-Talley, Principal			
	Dave Thomas Education Center - West			

- FROM: Robert J. Krickovich, Coordinator, LEA Facilities and Construction Management, Environmental Division
- SUBJECT: Indoor Air Quality (IAQ) Assessment FISH 207 and 237

On October 23, 2006 I conducted an assessment of FISH 207 and 237 at **Dave Thomas Education Center – West**. This evaluation included observations of the flooring system, ceiling tiles, false ceiling plenum, environmental surfaces, interior and exterior walls, and the accessible ventilation equipment. Additionally, environmental parameter measurements were taken to include temperature, relative humidity, and carbon dioxide. The detailed findings, along with the recommended corrective action can be found on the attached IAQ Assessment Worksheets.

Generally, the IAQ Assessment did not identify any existing conditions significantly impacting IAQ and thereby presenting immediate health and safety concerns to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact me at 754-321-1638.

cc: Dr. Harry LaCava, Area Superintendent
Willie Dudley, Area Director
Jeffrey S. Moquin, Director, Risk Management
Joe DeLillo, Project Manager, Facilities and Construction Management
Ruby Fitzgerald, Broward Teachers Union
Mark Dorsett, Manager 1, Physical Plant Operations Division, Zone 1
Roy Norton, Manager Custodial/Grounds, Physical Plant Operations Division

RK/tc Enc.

			IAQ As	sessment	Locatio	on Number	2031	
	Dave Thomas	Education Ce	enter West		Evaluat	ion Requested	October	19, 2006
Time of Day	1:25 pm				I	Evaluation Date	October	23, 2006
Outdoor Conditio	ons Tem	perature	90.1	Relative Humic	dity 51.2	2 Ambie	nt CO2	490
Fish Te	mperature F	Range Rel	ative Humidity	Range	CO2	Ran	ige #	Occupants
207	69.4 7	2 - 78	66.1	30% - 60%	482	Max 700	> Ambient	2
Noticeable Odor	No		Visible water mage / staining	Visible m ? grow		Amount of ma affected	terial	
Ceiling Type	2 x 4 Lay	In	No	No	>		None	
Wall Type	Drywall		No	No	>		None	
Flooring	12 x 12 Vin	yl	Yes	No	>	At	back door	
	Clean	Minor Dust / Debris	Needs Cleaning		Corre	ctive Action Re	equired	
Ceiling	Yes	Νο	No					
Walls	Yes	Νο	No					
Flooring	Yes	Νο	No					
HVAC Supply Gr	ills Yes	No	No					
HVAC Return Gr	ills Yes	Νο	No					
Ceiling at Supply Grills	Y Yes	No	No					
Surfaces in Room	m Yes	No	No					

Observations

Findings:

- 26 Dell computers and 2 Lexmark printers in the room

- Room is exceptionally clean

- Minor water staining on floor and door sill at the back door. The wall material around the door is dry. Staining appears to be from water intrusion uner the door.

- Temperature was low and humidity level was slightly elevated.

Recommendations:

Site Based Maintenance:

- Recognition of site based custodial staff for the exceptional cleanliness of the room.

- Adjust thermostat to increase temperature and lower humidity level. Continue to monitor condition and initiate a work order to Physical Plant Operations to evaluate the HVAC system if temperature does not improve.

- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

Physical Plant Operations:

- Evaluate need for eye brow/awning at back door to prevent water intrusion

			IAQ As	sessment	Locati	on Number	2031	
	Dave Thomas	Education Cer	nter West		Evaluat	tion Requested	October	19, 2006
Time of Day	1:25 pm				I	Evaluation Date	October	23, 2006
Outdoor Conditi	ions Tem	perature	90.1	Relative Hum	idity 51.2	2 Ambie	nt CO2	490
Fish To	emperature F	Range Rela	tive Humidity	Range	CO2	Ran	nge #	Occupants
237	74.6 7	2 - 78	51.6	30% - 60%	706	Max 700	> Ambient	2
Noticeable Odd	or No		/isible water nage / staining		microbial wth?	Amount of ma affected	terial	
Ceiling Type	2 x 4 Lay	In	No	N	lo		None	
Wall Type	Drywall		No	N	lo		None	
Flooring	12 x 12 Vin	yl	No	Ν	lo		None	
	Clean	Minor Dust / Debris	Needs Cleaning		Corre	ctive Action Re	equired	
Ceiling	Yes	No	No					
Walls	Yes	No	No					
Flooring	Yes	No	No					
HVAC Supply G	Grills Yes	No	No					
HVAC Return G	irills Yes	No	No					
Ceiling at Supp Grills	ly Yes	No	No					
Surfaces in Roo	om Yes	No	No					

Observations

Findings:

- 26 Dell computers and 2 Lexmark printers in the room

- Room is exceptionally clean

- Minor water staining on wall on the side of the window sill. The walls, windows and sills are dry. Staining appears to be from cleaning of the window sills.

Recommendations:

Site Based Maintenance:

- Recognition of site based custodial staff for the exceptional cleanliness of the room.

- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate