

## managing risk with responsibility

Aston A. Henry, Director
Risk Management Department

 Telephone:
 754 321-1900

 Fax:
 754 321-1917

August 27, 201	4 Signature on File	For Custodial Supervisor Use Only	
TO:	Michael Gleason, Principal Whispering Pines School	Custodial Issues Addressed	
FROM:	Richard Rosa, Project Manager	Custodial Issues Not Addressed	
	Risk Management Department		
SUBJECT:	Indoor Air Quality (IAQ) Assessment		

On August 20, 2014, I conducted an assessment at **Whispering Pines School**. Attached are findings and recommendations for further assessment, remediation, or corrective actions needed.

The IAQ assessment did identify one or more existing conditions impacting IAQ and has generated appropriate work orders to correct deficiencies in systems and maintenance that could contribute to decreased indoor air quality. At the time of the assessment, these concerns were not an immediate health or safety concern to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends the portable not be occupied until the appropriate follow up of each item identified and listed in the attached evaluation has been completed.

Please ensure that your Head Facilities Serviceperson receives a copy of this correspondence so that the recommendations requiring their attention can be addressed. In an attempt to separate IAQ issues from general maintenance items, the attached assessment may contain direction for site based staff to generate a work order through COMPASS. Within two weeks a representative from the Custodial/Grounds Department will conduct a follow-up visit to ensure that all site based custodial issues have been appropriately addressed.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact us at 754-321-1907.

cc: Shelley Meloni, Executive Director, Facilities & Construction Mark Dorsett, Manager, Zone 1, Physical Plant Operations Division Roy Norton, Manager, Custodial/Grounds, Physical Plant Operations Division Aston Henry, Director, Risk Management Sonja Coley, Senior Project Manager, Facilities & Construction Broward Teachers Union Federation of Public Employees

RR/tc Enc.

	IAQ Assessr	nent				
Whispering	Pines School Evaluation Dat	e August 20, 2014	Time of Day 1	2:30		
Outdoor Conditions Tempe	erature 95.9 Relative	Humidity 54.1	Ambient CO2 4	22		
		Range         CO <sup>2</sup> % - 60%         920	Range # O MAX 700 > Ambient	ccupants 8		
Noticeable OdorYesCeilingHomasoteWallsDrywall	Visible water damage / staining? Yes No	Visible microbial growth? Yes No	Amount of material affected 50 sq ft/2 sq ft			
Floor 12" x 12" Vinyl	Yes	No	640 sq ft			
Ceiling Clean No Walls Clean Yes Flooring Clean No	HVAC Supply Grills Clean Inside of Supply Duct Clean	Yes N/A	HVAC Return Grills Clean Inside of Return Duct Clean	Yes N/A		
Room Surfaces Yes Clean	Ceiling at Supply Grills Clean	Yes				
Trash RemovedYesSigns of PestsNoRoom ClutteredNo	Exhaust Fans Working Drain Traps Wet Food if Stored in Room is in Sealed Containers	N/A N/A	Unapproved Chemicals / Cleaners in Room Air Fresheners in Room	No No		
Mechanical Equipment Locatio	n Window unit		Mechanical Room Clean	N/A		
Filters Installed Properly	es Filters Clean es Cooling Coil Clean	Yes	Inside of HVAC Unit Clean	N/A		
Fresh Air Intake Location Pollutant Sources Near Air Intake	Window unit Grass and landscape	▼	Fresh Air Intake Free of Obstruction	Yes		
Observations						
There was an immediate foul odor when entering classroom. Evaluate the cause of wet flooring when flooring has						

been removed. The HFSP states there are lawn sprinklers in the area, this would be my first area of concern. Provide a vapor barrier before installing new flooring. There is an exterior section of unpainted T111 that needs caulk and paint. The entire floor is wet per moisture meter, areas of floor tile are buckling.

Corrective Actions to be Completed by Site Based Staff

assist maintenance with lawn sprinkler evaluation	▼
	▼
	▼
	▼
	▼
	▼
	▼
	▼

## **Corrective Actions to be Completed by PPO**

e and repair cause of stained ceiling	Evaluate and repair cause of stained ceiling	
eplace water damaged ceiling		
te and repair cause of wet flooring	Εv	
water damaged flooring and sub floor	Repla	
<b>•</b>		
<b>•</b>		
servations for additional information	See	
▼		