

RISK MANAGEMENT...

managing risk with responsibility

Jeffrey S. Moquin, Director
Risk Management Department

Telephone: 754-321-3200
Facsimile: 754-321-3290

February 12, 2008

Signature on File

TO: Ms. Sarah Hausman,, Principal
Wingate Oaks Center

FROM: Edward See, Project Manager
Risk Management Department

SUBJECT: Indoor Air Quality (IAQ) Assessment
FISH 103A, 104A, 905 and 906

<u>For Custodial Supervisor Use Only</u>	
<input type="checkbox"/>	Custodial Issues Addressed
<input type="checkbox"/>	Custodial Issues Not Addressed

On September 14, 2007 I conducted an assessment of FISH 103A, 104A, 905 and 906 at **Wingate Oaks Center**. This evaluation included observations of the flooring system, ceiling tiles, false ceiling plenum, environmental surfaces, interior and exterior walls, and the accessible ventilation equipment. Additionally, environmental parameter measurements were taken to include temperature, relative humidity, and carbon dioxide. The detailed findings, along with the recommended corrective action can be found on the attached IAQ Assessment Worksheets.

The IAQ assessment did identify one or more existing conditions impacting IAQ and has generated appropriate work orders to correct deficiencies in systems and maintenance that could contribute to decreased indoor air quality. At the time of the assessment, these concerns were not an immediate health or safety concern to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Please ensure that your Head Facilities Serviceperson receives a copy of this correspondence so that the recommendations requiring their attention can be addressed. Within two weeks a representative from the Custodial/Grounds Department will conduct a follow-up visit to ensure that all issues have been appropriately addressed.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact me at 754-321-3200.

cc: Dr. Leontine Butler, Area Superintendent
Toni Weissberg, Area Director
Jeffrey S. Moquin, Director, Risk Management
Robert Goode, Project Manager, Facilities and Construction Management
Dane Ramson, Broward Teachers Union
Roy Jarrett, Federation of Public Employees
Mark Dorsett, Manager 1, Physical Plant Operations Division, Zone 1
Roy Norton, Manager Custodial/Grounds, Physical Plant Operations Division
Robert Krickovich, Coordinator, LEA, Facilities and Construction Management

ES/tc
Enc.

IAQ Assessment

Location Number

Wingate Oaks Center

Evaluation Requested

Time of Day

Evaluation Date

Outdoor Conditions Temperature Relative Humidity Ambient CO2

Fish	Temperature	Range	Relative Humidity	Range	CO2	Range	# Occupants
<input type="text" value="103A"/>	<input type="text" value="71"/>	<input type="text" value="72 - 78"/>	<input type="text" value="50.5"/>	<input type="text" value="30% - 60%"/>	<input type="text" value="595"/>	<input type="text" value="Max 700 > Ambient"/>	<input type="text" value="1"/>
Noticeable Odor		Visible water damage / staining?		Visible microbial growth?		Amount of material affected	
<input type="text" value="No"/>		<input type="text" value="No"/>		<input type="text" value="No"/>		<input type="text" value="None"/>	
Ceiling Type	<input type="text" value="Drywall"/>		<input type="text" value="No"/>	<input type="text" value="No"/>	<input type="text" value="None"/>		
Wall Type	<input type="text" value="Drywall"/>		<input type="text" value="No"/>	<input type="text" value="No"/>	<input type="text" value="None"/>		
Flooring	<input type="text" value="12 x 12 Vinyl"/>		<input type="text" value="No"/>	<input type="text" value="No"/>	<input type="text" value="None"/>		

	Clean	Minor Dust / Debris	Needs Cleaning	Corrective Action Required
Ceiling	<input type="text" value="Yes"/>	<input type="text" value="No"/>	<input type="text" value="No"/>	<input type="text"/>
Walls	<input type="text" value="Yes"/>	<input type="text" value="No"/>	<input type="text" value="No"/>	<input type="text"/>
Flooring	<input type="text" value="Yes"/>	<input type="text" value="No"/>	<input type="text" value="No"/>	<input type="text"/>
HVAC Supply Grills	<input type="text" value="Yes"/>	<input type="text" value="No"/>	<input type="text" value="No"/>	<input type="text"/>
HVAC Return Grills	<input type="text" value="Yes"/>	<input type="text" value="No"/>	<input type="text" value="No"/>	<input type="text"/>
Ceiling at Supply Grills	<input type="text" value="Yes"/>	<input type="text" value="No"/>	<input type="text" value="No"/>	<input type="text"/>
Surfaces in Room	<input type="text" value="Yes"/>	<input type="text" value="No"/>	<input type="text" value="No"/>	<input type="text"/>

Observations

Findings: (closet)
 - Vent was recently installed in the door to allow air circulation

Recommendations:

Site Based Maintenance:
 - Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

Note - Work orders are in progress - EQ00935, EQ00936 and EQ00937

IAQ Assessment

Location Number

Wingate Oaks Center

Evaluation Requested

Time of Day

Evaluation Date

Outdoor Conditions Temperature Relative Humidity Ambient CO2

Fish	Temperature	Range	Relative Humidity	Range	CO2	Range	# Occupants
<input type="text" value="104A"/>	<input type="text" value="73.8"/>	<input type="text" value="72 - 78"/>	<input type="text" value="52.3"/>	<input type="text" value="30% - 60%"/>	<input type="text" value="650"/>	<input type="text" value="Max 700 > Ambient"/>	<input type="text" value="3"/>
Noticeable Odor		Visible water damage / staining?		Visible microbial growth?		Amount of material affected	
<input type="text" value="No"/>		<input type="text" value="No"/>		<input type="text" value="No"/>		<input type="text" value="None"/>	
Ceiling Type	<input type="text" value="2 x 4 Lay In"/>		<input type="text" value="No"/>	<input type="text" value="No"/>	<input type="text" value="None"/>		
Wall Type	<input type="text" value="Drywall"/>		<input type="text" value="No"/>	<input type="text" value="No"/>	<input type="text" value="None"/>		
Flooring	<input type="text" value="12 x 12 Vinyl"/>		<input type="text" value="No"/>	<input type="text" value="No"/>	<input type="text" value="None"/>		

	Clean	Minor Dust / Debris	Needs Cleaning	Corrective Action Required
Ceiling	<input type="text" value="Yes"/>	<input type="text" value="No"/>	<input type="text" value="No"/>	<input type="text"/>
Walls	<input type="text" value="Yes"/>	<input type="text" value="No"/>	<input type="text" value="No"/>	<input type="text"/>
Flooring	<input type="text" value="Yes"/>	<input type="text" value="No"/>	<input type="text" value="No"/>	<input type="text"/>
HVAC Supply Grills	<input type="text" value="Yes"/>	<input type="text" value="No"/>	<input type="text" value="No"/>	<input type="text"/>
HVAC Return Grills	<input type="text" value="Yes"/>	<input type="text" value="No"/>	<input type="text" value="No"/>	<input type="text"/>
Ceiling at Supply Grills	<input type="text" value="Yes"/>	<input type="text" value="No"/>	<input type="text" value="No"/>	<input type="text"/>
Surfaces in Room	<input type="text" value="Yes"/>	<input type="text" value="No"/>	<input type="text" value="No"/>	<input type="text"/>

Observations

Findings: (Principal's Office)
 - 5 live plants in room

Recommendations:

Site Based Maintenance:
 - Remove live plants. Soil is a source of microbial growth
 - Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

Note - Work orders are in progress - EQ00935, EQ00936 and EQ00937

IAQ Assessment

Location Number

Wingate Oaks Center

Evaluation Requested

Time of Day

Evaluation Date

Outdoor Conditions Temperature Relative Humidity Ambient CO2

Fish	Temperature	Range	Relative Humidity	Range	CO2	Range	# Occupants
<input type="text" value="905"/>	<input type="text" value="71.7"/>	<input type="text" value="72 - 78"/>	<input type="text" value="58.4"/>	<input type="text" value="30% - 60%"/>	<input type="text" value="668"/>	<input type="text" value="Max 700 > Ambient"/>	<input type="text" value="3"/>
Noticeable Odor		<input type="text" value="Yes"/>	Visible water damage / staining?		Visible microbial growth?		Amount of material affected
Ceiling Type	<input type="text" value="2 x 4 Lay In"/>		<input type="text" value="No"/>		<input type="text" value="No"/>		<input type="text" value="None"/>
Wall Type	<input type="text" value="Drywall"/>		<input type="text" value="No"/>		<input type="text" value="No"/>		<input type="text" value="None"/>
Flooring	<input type="text" value="12 x 12 Vinyl"/>		<input type="text" value="No"/>		<input type="text" value="No"/>		<input type="text" value="None"/>

	Clean	Minor Dust / Debris	Needs Cleaning	Corrective Action Required
Ceiling	<input type="text" value="Yes"/>	<input type="text" value="No"/>	<input type="text" value="No"/>	<input type="text"/>
Walls	<input type="text" value="Yes"/>	<input type="text" value="No"/>	<input type="text" value="No"/>	<input type="text"/>
Flooring	<input type="text" value="Yes"/>	<input type="text" value="No"/>	<input type="text" value="No"/>	<input type="text"/>
HVAC Supply Grills	<input type="text" value="Yes"/>	<input type="text" value="No"/>	<input type="text" value="No"/>	<input type="text"/>
HVAC Return Grills	<input type="text" value="Yes"/>	<input type="text" value="No"/>	<input type="text" value="No"/>	<input type="text"/>
Ceiling at Supply Grills	<input type="text" value="Yes"/>	<input type="text" value="No"/>	<input type="text" value="No"/>	<input type="text"/>
Surfaces in Room	<input type="text" value="Yes"/>	<input type="text" value="No"/>	<input type="text" value="No"/>	<input type="text"/>

Observations

Findings:

- Odor in room from air freshener
- 5 live plants in room
- 3 small areas on tackboard - green substance - appears to be glue. No signs of water intrusion or elevated moisture content.

Recommendations:

Site Based Maintenance:

- Remove air freshener
- Remove live plants. Soil is a source of microbial growth
- Clean tackboard
- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

Note - Work orders are in progress - EQ00935, EQ00936 and EQ00937

IAQ Assessment

Location Number 0991

Wingate Oaks Center

Evaluation Requested

Time of Day 1:00 pm

Evaluation Date September 14, 2007

Outdoor Conditions Temperature 87.4 Relative Humidity 64.7 Ambient CO2 469

Fish	Temperature	Range	Relative Humidity	Range	CO2	Range	# Occupants
906	71.4	72 - 78	65.1	30% - 60%	623	Max 700 > Ambient	5
Noticeable Odor		Visible water damage / staining?		Visible microbial growth?		Amount of material affected	
Ceiling Type		Yes		No		1 ceiling tile	
Wall Type		No		No		None	
Flooring		No		No		None	

	Clean	Minor Dust / Debris	Needs Cleaning	Corrective Action Required
Ceiling	No	Yes	Yes	Remove and replace ceiling tile
Walls	Yes	No	No	
Flooring	Yes	No	No	
HVAC Supply Grills	Yes	No	No	
HVAC Return Grills	Yes	No	No	
Ceiling at Supply Grills	Yes	No	No	
Surfaces in Room	Yes	No	No	

Observations

Findings:
 - Stained ceiling tile at window
 - Humidity level was slightly elevated - work orders have been issued (see below) to correct

Recommendations:

Site Based Maintenance:
 - Remove and replace stained ceiling tile
 - Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

Note - Work orders are in progress - EQ00935, EQ00936 and EQ00937