

Report: PPO

CHALLENGER ELEMENTARY

Walkthrough Date: 03/28/2007 Temp RH CO2

Outdoor Parameters: 76.4 40.2 1165

Room	Priority	Responsible	Answer	Recommendation
103E	Inside Parameters:	Temp 76.4	RH 40.2	CO2 1165
2		PPO	Room is being used as a computer lab. Temperature was elevated with no occupants.	Physical Plant Operations to evaluate air flow and repair as appropriate to introduce more air to the room.
109	Inside Parameters:	Temp 72.8	RH 46.8	CO2 1122
2		PPO	Room is a music room and the ceiling is higher. Evidence of minor dust accumulation on supply registers.	Physical Plant Operations to assist in cleaning of supply grills.
226A	Inside Parameters:	Temp 73.5	RH 52.3	CO2 979
1		PPO	Signs of water intrusion. Stained ceiling tiles.	Physical Plant Operations to evaluate for leaks and repair as appropriate and replace ceiling tiles as appropriate.
402	Inside Parameters:	Temp 72.3	RH 47.1	CO2 1450
1		PPO	Signs of water intrusion identified at East wall near restroom. Staff indicated that there was a previous A/C leak on the second floor that was repaired.	Physical Plant Operations to evaluate and repair as appropriate and replace stained ceiling tiles.