

Report: PPO

COOPER CITY ELEMENTARY

Walkthrough Date: 03/13/2007 Temp RH CO2

Outdoor Parameters: 70.4 60.5 675

Room	Priority	Responsible	Answer	Recommendation
101	Inside Parameters:	Temp	RH	CO2
		70.4	60.5	675

2 PPO Gaps in doors identified at the time of assessment. Physical Plant Operations to evaluate and repair as appropriate.

Room	Priority	Responsible	Answer	Recommendation
134	Inside Parameters:	Temp	RH	CO2
		73.1	55.4	792

1 PPO Signs of water intrusion. 3 Stained ceiling tiles. Physical Plant Operations to evaluate for leaks and repair as appropriate and replace ceiling tiles as appropriate.

Room	Priority	Responsible	Answer	Recommendation
173	Inside Parameters:	Temp	RH	CO2
		71.5	61.1	1296

2 PPO Exhaust fan is not functioning properly in FISH 173B. Exterior door blocked open.. Physical Plant Operations to evaluate and repair as appropriate.

Room	Priority	Responsible	Answer	Recommendation
180	Inside Parameters:	Temp	RH	CO2
		72.5	58.2	1351

2 PPO Exhaust fan is not functioning properly in FISH 180B - noise only. Physical Plant Operations to evaluate and repair as appropriate.

Room	Priority	Responsible	Answer	Recommendation
181	Inside Parameters:	Temp	RH	CO2

		73.1	59.7	1286
2	PPO	No pests observed at the time of assessment. However, exterior door weather stripping is in need of replacement.		Physical Plant Operations to evaluate and replace exterior door weather stripping.
Room	Priority	Responsible	Answer	Recommendation
184	Inside Parameters:	Temp	RH	CO2
		71.1	58.4	1351
1	PPO	Signs of water intrusion. Stained ceiling tile above stove		Physical Plant Operations to evaluate for leaks and repair as appropriate and replace ceiling tiles as appropriate.
2	PPO	Exhaust fan is not functioning properly in FISH 184B - noise only.		Physical Plant Operations to evaluate and repair as appropriate.
Room	Priority	Responsible	Answer	Recommendation
186	Inside Parameters:	Temp	RH	CO2
		71.4	57.3	1272
2	PPO	No pests observed at the time of assessment. However, there was a gap between door frame and window frame.		Physical Plant Operations and to evaluate and repair as appropriate.
Room	Priority	Responsible	Answer	Recommendation
195	Inside Parameters:	Temp	RH	CO2
		70.5	60.9	1267
2	PPO	Exhaust fan is functioning properly in FISH 195B.		Physical Plant Operations to evaluate and repair as appropriate.
Room	Priority	Responsible	Answer	Recommendation
198	Inside Parameters:	Temp	RH	CO2
		71.0	45.9	1193
1	PPO	Signs of water intrusion. Stained ceiling tiles over exterior door.		Physical Plant Operations to evaluate for leaks and repair as appropriate and replace ceiling tiles as appropriate.