

managing risk with responsibility

Aston A. Henry, Supervisor Telephone: Risk Management Department Fax:

May 1, 2012

Signature on File

TO: Paulette Samai, Principal

Cypress Elementary School

FROM: Robert Krickovich, Coordinator I, LEA

Facilities and Construction Management

SUBJECT: Indoor Air Quality (IAQ) Assessment

For Custodial Supervisor Use Only						
	Custodial Issues Addressed					
	Custodial Issues Not Addressed					
-						

754 321-1900

754 321-1917

On November 10, 2011, I conducted an assessment at **Cypress Elementary School**. Attached are findings and recommendations for further assessment, remediation, or corrective actions needed.

The IAQ assessment did identify one or more existing conditions impacting IAQ and has generated appropriate work orders to correct deficiencies in systems and maintenance that could contribute to decreased indoor air quality. At the time of the assessment, these concerns were not an immediate health or safety concern to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Please ensure that your Head Facilities Serviceperson receives a copy of this correspondence so that the recommendations requiring their attention can be addressed. In an attempt to separate IAQ issues from general maintenance items, the attached assessment may contain direction for site based staff to generate a work order through COMPASS. Within two weeks a representative from the Custodial/Grounds Department will conduct a follow-up visit to ensure that all site based custodial issues have been appropriately addressed.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact us at 754-321-1907.

cc: Area Superintendent

Area Directors

Shelley Meloni, Executive Director, Facilities and Construction Management Mark Dorsett, Acting Director, Physical Plant Operations Division, Maintenance Sonja Coley, Project Manager III, Facilities and Construction Management Roy Norton, Manager Custodial/Grounds, Physical Plant Operations Division Aston Henry, Supervisor, Risk Management Broward Teachers Union

Federation of Public Employees

RK/tc Enc.

		Cypress El	iementary		⊏valuat	ion Requested Nover	liber 10, 2011
Time of Day	1:15				E	Evaluation Date Nover	mber 10, 2011
Outdoor Condi	tions Ten	nperature	82.7	Relative Humid	ity 45.1	Ambient CO2	460
		Range Rel	ative Humidity	Range	CO2	Range	# Occupants
134	76	72 - 78	53.4	30% - 60%	1307	Max 700 > Ambi	ent 2
Noticeable Odor Yes			Visible water mage / staining	Visible mi ? growt		Amount of material affected	
Ceiling Type	2 x 4 Lay	In	No	No		None	
Wall Type	Drywal	I	No	No		None	
Flooring	Carpet		No	No		None	
	Clean	Minor Dust / Debris	Needs Cleaning		Correc	ctive Action Required	
Ceiling	Yes	No	No				
Walls	Yes	No	No				
Flooring	Yes	No	No				
HVAC Supply	Grills No	Yes	Yes		Clea	an as appropriate	
HVAC Return	Grills Yes	No	No				
Ceiling at Sup Grills	ply No	Yes	Yes		F	PPO to replace	
Surfaces in Ro	oom Yes	No	No				
bservations							

IAQ Assessment

Location Number

Findings

- Slightly elevated CO2 level
- 1 stained ceiling tile (old stain) requiring cut
- Carpet is damp and has strong odor
- Tile floor in corridors is buckling and has visible calcium deposits on surface
- Dust build up on HVAC supply grills

Site Based Maintenance:

- Clean HVAC supply grills with Wexcide disinfectant solution
- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

Physical Plant Operations:

- Evaluate HVAC system for proper operation and repair as appropriate to lower CO2 level
- Remove and replace stained ceiling requiring cut
- Remove carpet and replace
- NOTE: Work orders EQ02218 through EQ02220 11-10-11