

# RISK MANAGEMENT...

managing risk with responsibility

Jeffrey S. Moquin, Director  
Risk Management Department

Telephone: 754-321-3200  
Facsimile: 754-321-3290

July 24, 2006

**Signature on File**

TO: Ms. Constantina Pettis, Principal  
**Deerfield Park Elementary School**

FROM: Kenneth I. Partee, Project Manager Occupational Health and Environmental Control  
Risk Management Department

SUBJECT: Indoor Air Quality (IAQ) Assessment  
**600 Building**

On July 19, 2006 Aston Henry and I conducted a follow up assessment of the 600 Building at **Deerfield Park Elementary School**. The assessment consisted of a reevaluation walkthrough of the previously identified areas to assess the current condition of the location with regard to indoor air quality. This assessment included reviewing previously generated work orders as well as observations of the areas of concern as stated in the IAQ Assessments performed on July 19 and August 16, 2005 by Robert Krickovich. Attached are the findings of this assessment along with recommendations for further assessment, remediation, or corrective actions, if needed.

The IAQ assessment did identify one or more existing conditions impacting IAQ and has generated appropriate work orders to correct deficiencies in systems and maintenance that could contribute to decreased indoor air quality. At the time of the assessment, these concerns were not an immediate health or safety concern to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact me at 754-321-3200.

cc: Dr. Joanne Harrison, Area Superintendent  
Craig Anderson, Area Director  
Jeffrey S. Moquin, Director, Risk Management  
Ed Beraldi, Project Manager, Facilities and Construction Management  
Jamie Daniels, Broward Teachers Union  
Mark Dorsett, Manager 1, Physical Plant Operations Division, Zone 1  
Roy Norton, Manager Custodial/Grounds, Physical Plant Operations Division  
Robert Krickovich, Coordinator, LEA, Facilities and Construction Management

KP/tc  
Enc.

# IAQ Assessment

Location Number   
 Evaluation Requested   
 Evaluation Date

Deerfield Park Elementary School

Time of Day

Outdoor Conditions      Temperature       Relative Humidity       Ambient CO2

Fish	Temperature	Range	Relative Humidity	Range	CO2	Range	# Occupants
<input type="text" value="600 Bldg"/>	<input type="text"/>	<input type="text" value="72 - 78"/>	<input type="text"/>	<input type="text" value="30% - 60%"/>	<input type="text"/>	<input type="text" value="Max 700 &gt; Ambient"/>	<input type="text"/>
Noticeable Odor		Visible water damage / staining?		Visible microbial growth?		Amount of material affected	
<input type="text" value="No"/>		<input type="text"/>		<input type="text" value="No"/>		<input type="text" value="None"/>	
Ceiling Type	<input type="text" value="2 x 4 Lay In"/>		<input type="text" value="No"/>	<input type="text" value="No"/>		<input type="text" value="None"/>	
Wall Type	<input type="text" value="Plaster"/>		<input type="text" value="No"/>	<input type="text" value="Yes"/>		<input type="text" value="Various"/>	
Flooring	<input type="text" value="Tile"/>		<input type="text" value="No"/>	<input type="text" value="No"/>		<input type="text" value="None"/>	

	Clean	Minor Dust / Debris	Needs Cleaning	Corrective Action Required
Ceiling	<input type="text" value="Yes"/>	<input type="text" value="No"/>	<input type="text" value="No"/>	<input type="text"/>
Walls	<input type="text" value="No"/>	<input type="text" value="Yes"/>	<input type="text" value="Yes"/>	<input type="text" value="Clean with Wexcide disinfectant"/>
Flooring	<input type="text" value="Yes"/>	<input type="text" value="No"/>	<input type="text" value="No"/>	<input type="text"/>
HVAC Supply Grills	<input type="text" value="Yes"/>	<input type="text" value="No"/>	<input type="text" value="No"/>	<input type="text"/>
HVAC Return Grills	<input type="text" value="Yes"/>	<input type="text" value="No"/>	<input type="text" value="No"/>	<input type="text"/>
Ceiling at Supply Grills	<input type="text" value="Yes"/>	<input type="text" value="No"/>	<input type="text" value="No"/>	<input type="text"/>
Surfaces in Room	<input type="text" value="Yes"/>	<input type="text" value="No"/>	<input type="text" value="No"/>	<input type="text"/>

**Observations**

**Findings:**

- Visible microbial growth on walls throughout the hallways of the 600 Building. Custodial staff has wiped walls down several times and growth keeps returning.

**Recommendations:**

**Site Based Maintenance:**

- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

**Physical Plant Operations:**

- Evaluate cause of growth on walls and repair. Clean walls as appropriate.
- Clean duct work

**Note - Previous work order EQ00452**