

Report: PPO

**DREW CHARLES ELEMENTARY**

Walkthrough Date: 03/16/2007 Temp RH CO2

Outdoor Parameters: 74.2 54.9 1157

Room	Priority	Responsible	Answer	Recommendation
130	Inside Parameters:	Temp	RH	CO2
		73.5	60.5	524

- 2 PPO Air supply/return ventilation is not functioning. Physical Plant Operations to evaluate and repair as appropriate.
- 2 PPO Bathroom exhaust fan is not functioning properly. Physical Plant Operations to evaluate and repair as appropriate.

Room	Priority	Responsible	Answer	Recommendation
132	Inside Parameters:	Temp	RH	CO2
		72.1	60.7	1061

- 1 PPO Signs of water intrusion. Leak identified. Physical Plant Operations to evaluate for leaks and repair as appropriate.
- 2 PPO Ceiling tiles damaged or stained and require cut. Physical Plant Operations to replace ceiling tiles as appropriate.

Room	Priority	Responsible	Answer	Recommendation
202	Inside Parameters:	Temp	RH	CO2
		66.5	60.4	960

- 2 PPO Pests observed at the time of assessment. Physical Plant Operation to initiate work order to evaluate pest issue within location and take appropriate action.

Room	Priority	Responsible	Answer	Recommendation
207	Inside Parameters:	Temp	RH	CO2
		77.2	53.7	582

- 2 PPO Occupant advised that room is too hot or too cold. Physical Plant Operations to evaluate and repair as appropriate.
- 2 PPO Air supply/return ventilation is not functioning. Physical Plant Operations to evaluate and repair as appropriate.

2 PPO Bathroom exhaust fan is not functioning properly. Physical Plant Operations to evaluate and repair as appropriate.

Room	Priority	Responsible	Answer	Recommendation
401	Inside Parameters:	Temp 66.5	RH 60.4	CO2 960

2 PPO Bathroom exhaust fan is not functioning properly. Physical Plant Operations to evaluate and repair as appropriate.

Room	Priority	Responsible	Answer	Recommendation
407	Inside Parameters:	Temp 72.6	RH 59.7	CO2 1711

1 PPO Signs of water intrusion. Stained ceiling tiles. Physical Plant Operations to evaluate for leaks and repair as appropriate and replace ceiling tiles as appropriate.

Room	Priority	Responsible	Answer	Recommendation
502	Inside Parameters:	Temp 72.3	RH 57.0	CO2 1662

2 PPO Occupant advised that temperature shifts. Physical Plant Operations to evaluate and repair as appropriate.

2 PPO Bathroom exhaust fan is not functioning properly. Physical Plant Operations to evaluate and repair as appropriate.

Room	Priority	Responsible	Answer	Recommendation
607	Inside Parameters:	Temp 71.8	RH 52.2	CO2 1811

2 PPO Occupant advised temperature shifts. Physical Plant Operations to evaluate and repair as appropriate.

2 PPO Bathroom exhaust fan is not functioning properly. Physical Plant Operations to evaluate and repair as appropriate.