

SUBJECT:

managing risk with responsibility

Aston A. Henry, Director		Telephone:	754 321-1900		
Risk Management Department		Fax:	754 321-1917		
December 12, 2013		Signature on File	For Custodial Supervisor Use Only		
TO:	Michelle Engram, Fairway Elementa	*		ues Addressed ues Not Addressed	
FROM:	Richard Rosa, Proj Risk Management	O			

On December 9, 2013, I conducted an assessment at Fairway Elementary School. Attached are findings and recommendations for further assessment, remediation, or corrective actions needed.

Indoor Air Quality (IAQ) Assessment

The IAQ assessment did identify one or more existing conditions impacting IAQ and has generated appropriate work orders to correct deficiencies in systems and maintenance that could contribute to decreased indoor air quality. At the time of the assessment, these concerns were not an immediate health or safety concern to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Please ensure that your Head Facilities Serviceperson receives a copy of this correspondence so that the recommendations requiring their attention can be addressed. In an attempt to separate IAQ issues from general maintenance items, the attached assessment may contain direction for site based staff to generate a work order through COMPASS. Within two weeks a representative from the Custodial/Grounds Department will conduct a follow-up visit to ensure that all site based custodial issues have been appropriately addressed.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact us at 754-321-1907.

Shelley Meloni, Task Assigned Chief Facilities & Construction Officer, Facilities & Construction cc: Mark Dorsett, Manager, Zone 1, Physical Plant Operations Division Roy Norton, Manager, Custodial/Grounds, Physical Plant Operations Division Aston Henry, Director, Risk Management Sonja Coley, Senior Project Manager, Facilities & Construction **Broward Teachers Union** Federation of Public Employees

RR/tc Enc.

IAQ Assessment

Fairway Ele	ementary Evaluation D	December 9, 2013	Time of Day 1	1:30
Outdoor Conditions Temperatur	re 80.7 Relativ	ve Humidity 65.7	Ambient CO2 4	53
Fish Temperature Rang 770 68.9 72 - 7		Range <u>C0</u> 2 0% - 60% 735		ccupants
Noticeable Odor No Ceiling 2' x 2'	Visible water damage / staining?	Visible microbial growth?	Amount of material affected	
Walls Drywall Floor 12" x 12" Vinyl	No No	No No		
Ceiling Clean Yes Walls Clean Yes	HVAC Supply Grills Clean	No	HVAC Return Grills Clean	No
Flooring Clean Yes	Inside of Supply Duct Clean	Yes	Inside of Return Duct Clean	N/A
Room Surfaces No Clean	Ceiling at Supply Grills Clean	Yes		
Trash Removed Yes Signs of Pests Yes	Exhaust Fans Working		Unapproved Chemicals / Cleaners in Room	No
Signs of Pests Yes Room Cluttered Yes	Drain Traps Wet Food if Stored in Room is in Sealed Containers		Air Fresheners in Room	No
Mechanical Equipment Location FI	ISH 772		Mechanical Room Clean	No
Filters Installed Properly Condensate Pan Clean N/A	Filters Clean Cooling Coil Clean	Yes N/A	Inside of HVAC Unit Clean	N/A
Fresh Air Intake Location	hru exterior wall	▼	Fresh Air Intake Free	Yes
Pollutant Sources Near Air Intake	rass and landscape	▼	or Obstruction	
Observations Cabinetry top, adjacent to window; n/a-not applicable N/A-not accessi		of bird droppings or a	large critter.	
Corrective Actions to be Complete	ed by Site Based Staff	Corrective Actio	ns to be Completed by PF	PO
Clean surfaces in mechanical room ▼ Set temperature to 72 - 78 degrees			▼	
Thoroughly clean horizontal surfaces ▼ Evaluate and repair restroom exhaust fa			pair restroom exhaust fan	
Clean HVAC supply grills wi Vacuum/wipe return				▼
Generate a work order for p				▼
		1		I ⊸ ∃

IAQ Assessment

Fairway	Elementary Evaluation Date	e December 9, 2013	Time of Day1	2:00
Outdoor Conditions Tempera	ature 80.7 Relative	Humidity 65.7	Ambient CO2 45	53
		Range <u>CO</u> ² % - 60 %	Range # Oc MAX 700 > Ambient	cupants
Noticeable Odor No	Visible water damage / staining?	Visible microbial growth?	Amount of material affected	
Ceiling 2' x 4'	No	No		
Walls Drywall	No	No		
Floor 12" x 12" Vinyl	Yes	No	40 sq ft	
Ceiling Clean Yes Walls Clean Yes	HVAC Supply Grills Clean	No	HVAC Return Grills Clean	No
Flooring Clean Yes	Inside of Supply Duct Clean	Yes	Inside of Return Duct Clean	N/A
Room Surfaces No Clean	Ceiling at Supply Grills Clean	Yes		
Trash Removed Yes	Exhaust Fans Working	No	Unapproved Chemicals / Cleaners in Room	No
Signs of Pests Yes	Drain Traps Wet	N/A	Air Fresheners	□ I
Room Cluttered Yes	Food if Stored in Room is in Sealed Containers	N/A	in Room	No
Mechanical Equipment Location	Bard like HVAC system in clas	ssroom	Mechanical Room Clean	n/a
Filters Installed Properly Yes	Filters Clean	Yes	Inside of HVAC Unit Clean	N/A
Condensate Pan Clean N/A	Cooling Coil Clean	N/A		
Fresh Air Intake Location	Behind Bard unit/Exterior wall	▼	Fresh Air Intake Free	Yes
Pollutant Sources Near Air Intake	Grass and landscape	▼	of Obstruction	

Observations

Replace the floor tile down the center of the classroom, concrete crack, filling up with dirt and grime. Insect droppings on window sills. Coordinate a cleaning schedule with the instructor to clean surfaces properly due to clutter. In the NW corner of classroom 9' from the West wall on the North wall, the baseboard is wet. Instructor states when it rains the floor puddles with no wall staining. Recommend roofer to check roof parapet and flashing. Once roof repair is complete, carpenters evaluate baseboard and wall. n/a-not applicable N/A-not accessible

Corrective Actions to be Completed by Site Based Staff

Jian
▼
▼
▼
•
•
•
▼
▼

Corrective Actions to be Completed by PPO

Contoure Actions to be completed by 11 C	
Set temperature to 72 - 78 degrees	▼
Evaluate and repair restroom exhaust fan	▼
Roofers to evaluate parapet roof cap and flashing	▼
Evaluate the cause of wet flooring and repair	▼
Replace damaged floor tile	▼
	▼
See observations for additional information	▼
	▼