

managing risk with responsibility

Aston A. Henry, Director Risk Management Department		Telephone: Fax:	754 321-1900 754 321-1917	
July 31, 2014	Signature on File	For Custodial Supervisor Use Only		
TO:	Janice Crosby, Principal Flamingo Elementary School		ues Addressed ues Not Addressed	
FROM:	Richard Rosa, Project Manager Risk Management Department			
SUBJECT:	Indoor Air Quality (IAQ) Assessment			

On July 22, 2014, I conducted an assessment at **Flamingo Elementary School**. Attached are findings and recommendations for further assessment, remediation, or corrective actions needed.

The IAQ assessment did identify one or more existing conditions impacting IAQ and has generated appropriate work orders to correct deficiencies in systems and maintenance that could contribute to decreased indoor air quality. At the time of the assessment, these concerns were not an immediate health or safety concern to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Please ensure that your Head Facilities Serviceperson receives a copy of this correspondence so that the recommendations requiring their attention can be addressed. In an attempt to separate IAQ issues from general maintenance items, the attached assessment may contain direction for site based staff to generate a work order through COMPASS. Within two weeks a representative from the Custodial/Grounds Department will conduct a follow-up visit to ensure that all site based custodial issues have been appropriately addressed.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact us at 754-321-1907.

cc: Shelley Meloni, Executive Director, Facilities & Construction
Mark Dorsett, Manager, Zone 1, Physical Plant Operations Division
Roy Norton, Manager, Custodial/Grounds, Physical Plant Operations Division
Aston Henry, Director, Risk Management
Sonja Coley, Senior Project Manager, Facilities & Construction
Broward Teachers Union
Federation of Public Employees

RR/tc Enc.

IAQ Assessment

Flamingo Elen	nentary Evaluation Da	te July 22, 2014	Time of Day 2:45				
Outdoor Conditions Temperature	87.2 Relative	e Humidity 76.1	Ambient CO2 412				
Fish Temperature Range 750 70.3 72 - 78		Range <u>CO</u> % - 60% 419					
Noticeable Odor No	Visible water damage / staining?	Visible microbial growth?	Amount of material affected				
Ceiling 2' X 4' Lay in	Yes	No					
Walls Drywall	Yes	No	<1 sq ft				
Floor 12" x 12" Vinyl	No	No					
Ceiling Clean No Walls Clean No	HVAC Supply Grills Clean	Yes	HVAC Return Grills Clean Yes				
Flooring Clean Yes	Inside of Supply Duct Clean	Yes	Inside of Return Duct Clean N/A				
Room Surfaces Yes Clean	Ceiling at Supply Grills Clean	No					
Trash Removed Yes	Exhaust Fans Working	Yes	Unapproved Chemicals / Cleaners in Room				
Signs of Pests Yes Room Cluttered No	Drain Traps Wet Food if Stored in Room is in Sealed Containers	N/A	Air Fresheners No in Room				
Mechanical Equipment Location Bar	rd like HVAC system in cla	ssroom	Mechanical Room Clean N/A				
Filters Installed Properly Yes	Filters Clean	No	Inside of HVAC Unit Clean N/A				
Condensate Pan Clean N/A	Cooling Coil Clean	N/A					
Fresh Air Intake Location Behind Bard unit/Exterior wall ▼ Fresh Air Intake Free of Obstruction Yes							
Pollutant Sources Near Air Intake	ass and landscape	▼					
Observations							
The ceiling tile stains are from an old roof leak. The roofing has been repaired. Repair interior drywall under window sill and repair cause of water intrusion. Spiders were visible under sink in cabinetry.							
Corrective Actions to be Completed by Site Based Staff Corrective Actions to be Completed by PPO							

a11
▼
▼
▼
▼
▼
▼
▼
▼

	▼
	▼
Evaluate the cleaning of the HVAC coil	▼
Repair interior wall damage under window	▼
under window sill	▼
Evaluate and repair cause of water damage	▼
Repair HVAC to reduce humidity level	▼
Set temperature to 72 - 78 degrees	▼
Corrective Actions to be completed by 110	