

Aston A. Henry, Supervisor Risk Management Department

June 22, 2009

TO:

FROM:

SUBJECT:

managing risk with responsibility

Telephone:754 321-1900Fax:754 321-1917

Signature on File	For Custodial Supervisor Use Only			
Ms. Cynthia Novotny, Principal Griffin Elementary School	Custodial Issues Addressed Custodial Issues Not Addressed			
Richard Rosa, Project Manager Facilities and Construction Management				
Indoor Air Quality (IAQ) Assessment Portable 609P				

On April 28, 2009 I conducted an assessment of Portable 609P at **Griffin Elementary School**. This evaluation included observations of the flooring system, ceiling tiles, false ceiling plenum, environmental surfaces, interior and exterior walls, and the accessible ventilation equipment. Additionally, environmental parameter measurements were taken to include temperature, relative humidity, and carbon dioxide. The detailed findings, along with the recommended corrective action can be found on the attached IAQ Assessment Worksheets.

The IAQ assessment did identify one or more existing conditions impacting IAQ and has generated appropriate work orders to correct deficiencies in systems and maintenance that could contribute to decreased indoor air quality. At the time of the assessment, these concerns were not an immediate health or safety concern to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Please ensure that your Head Facilities Serviceperson receives a copy of this correspondence so that the recommendations requiring their attention can be addressed. Within two weeks a representative from the Custodial/Grounds Department will conduct a follow-up visit to ensure that all issues have been appropriately addressed.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact me at 754-321-1637.

cc: Dr. Joel Herbst, Area Superintendent Valerie Wanza, Area Director Jeffrey S. Moquin, Executive Director, Support Operations Aston A. Henry, Supervisor, Risk Management Steve Dowling, Project Manager, Facilities and Construction Management Ralph Eckhardt, Broward Teachers Union Roy Jarrett, Federation of Public Employees Mark Dorsett, Manager 1, Physical Plant Operations Division, Zone 1 Roy Norton, Manager Custodial/Grounds, Physical Plant Operations Division Robert Krickovich, Coordinator, LEA, Facilities and Construction Management

RR/tc Enc.

		IA	Q Assessment	Location	Number	2851	
	Griffir	n Elementary Scho	ol	Evaluation	Requested	March 30, 2009	9
Time of Day 11	1:30 am			Eva	luation Date	April 28, 2009	
Outdoor Conditions	s Tempe	rature 86.7	Relative Hu	imidity 28.3	Ambie	nt CO2 221	
Fish Temp	^{erature} Ran	ge Relative Hu	midity Range	CO2	Ran	ge # Occupa	ints
P-609P	73.2 72 - 7	78 47.9	30% - 60%	298	Max 700	> Ambient 2	
Noticeable Odor	No	Visible v damage / s		le microbial prowth?	Amount of material affect		
Ceiling Type	2 x 4	Yes] [No	<u>11 c</u>	eiling tiles	
Wall Type	Tackable	No] [No		None	
Flooring	12 x 12 Vinyl	Yes] [No		Various	
			eeds aning	Correctiv	ve Action Re	equired	
Ceiling	Νο	Yes	/es	Remove and	l replace cei	ling tiles	
Walls	Yes	No	No				
Flooring	Νο	Yes	/es	Monitor floor	for increase	d cracking	
HVAC Supply Grills	s No	Yes	ſes	Clean with V	Vexcide disi	infectant	
HVAC Return Grills	s No	Yes	/es	Clean with V	Vexcide disi	nfectant	
Ceiling at Supply Grills	No	Yes	/es	Remove and	l replace cei	ling tiles	
Surfaces in Room	No	Yes	/es	Clean	as appropri	ate	

Observations

Findings:

- Three window A/C units in room. One was running at the time of the assessment
- 11 stained ceiling tiles. Staff advised that work orders were called in to evaluate roof and no leaks were found.
- Dust and debris on A/C coils South window unit
- Dust and debris on A/C supply and return grills
- Dust build up on elevated surfaces and window sills
- Non-approved items in room (air freshener, palmolive)

Recommendations:

Site Based Maintenance:

- Remove and replace stained ceiling tiles and contact COMPASS to generate a work order to assist with replacement as needed. Monitor for return of stains. If stains return, contact Physical Plant Operations to evaluate further for cause.

- Clean A/C supply and return grills with Wexcide disinfectant solution
- Clean elevated surfaces and windowsills throughout room
- Remove non-approved items from room

- Continue to monitor this location for any signs of microbial growth as well as dust and debris accumulation and clean as appropriate

Physical Plant Operations:

- Clean coils on South window unit