

managing risk with responsibility

Risk Management Department		Fax:	754 321-1900 754 321-1917	
September 2	24, 2014	Signature on File	For Custodial S	upervisor Use Only
TO:		, Principal e Elementary School		ues Addressed ues Not Addressed
FROM:		osa, Project Manager agement Department		
SUBJECT:	Indoor Ai	r Quality (IAQ) Assessment		

On September 22, 2014, I conducted an assessment at **Hallandale Elementary School**. Attached are findings and recommendations for further assessment, remediation, or corrective actions needed.

The IAQ assessment did identify one or more existing conditions impacting IAQ and has generated appropriate work orders to correct deficiencies in systems and maintenance that could contribute to decreased indoor air quality. At the time of the assessment, these concerns were not an immediate health or safety concern to building occupants. However, due to individual sensitivities and predisposing health factors, it is possible that some building occupants may elicit a health response to agents and / or conditions identified during the evaluation. Therefore, to further improve IAQ, prevent development of future IAQ-related problems, and to reduce the potential for IAQ-related complaints by building occupants, the IAQ Assessment Team recommends appropriate follow up of each item identified and listed in the attached evaluation.

Please ensure that your Head Facilities Serviceperson receives a copy of this correspondence so that the recommendations requiring their attention can be addressed. In an attempt to separate IAQ issues from general maintenance items, the attached assessment may contain direction for site based staff to generate a work order through COMPASS. Within two weeks a representative from the Custodial/Grounds Department will conduct a follow-up visit to ensure that all site based custodial issues have been appropriately addressed.

Should any questions arise, or if the current concerns continue after the attached recommendations have been addressed, please feel free to contact us at 754-321-1907.

cc: Shelley Meloni, Executive Director, Facilities & Construction
Mark Dorsett, Manager, Zone 1, Physical Plant Operations Division
Roy Norton, Manager, Custodial/Grounds, Physical Plant Operations Division
Aston Henry, Director, Risk Management
Sonja Coley, Senior Project Manager, Facilities & Construction
Broward Teachers Union
Federation of Public Employees

RR/tc Enc.

IAQ Assessment

Hallandale	Elementary Evaluation Date	e September 22, 2014	Time of Day 9	:30
Outdoor Conditions Tempera	ture 82.5 Relative	Humidity 88.0	Ambient CO2 46	8
	<u> </u>	Range CO ² % - 60%		cupants 9
Noticeable Odor Yes	Visible water damage / staining?	Visible microbial growth?	Amount of material affected	
Ceiling 2' X 2' Lay in	No	No		
Walls Drywall	No	No		
Floor Carpet	Yes	No	270 sq ft	
Ceiling Clean Yes Walls Clean Yes	HVAC Supply Grills Clean	Yes	HVAC Return Grills Clean	Yes
Flooring Clean No	Inside of Supply Duct Clean	Yes	Inside of Return Duct Clean	No
Room Surfaces No Clean	Ceiling at Supply Grills Clean	Yes		
Trash Removed Yes Signs of Pests No	Exhaust Fans Working Drain Traps Wet	N/A	Unapproved Chemicals / Cleaners in Room	No
Room Cluttered Yes	Food if Stored in Room is in Sealed Containers	N/A	Air Fresheners in Room	No
Mechanical Equipment Location	FISH 338		Mechanical Room Clean	Yes
Filters Installed Properly Yes	Filters Clean	Yes	Inside of HVAC Unit Clean	Yes
Condensate Pan Clean Yes	Cooling Coil Clean	Yes		
Fresh Air Intake Location	Roof top	▼	Fresh Air Intake Free	Yes
Pollutant Sources Near Air Intake	No	▼	of Obstruction	
Observations				
ESE students in room. Carpet hat the room has been restricted, ch 71.7 degrees.				

Corrective Actions to be Completed by Site Based Staff			
Coordinate a schedule with instructor to clean			
properly due to clutter	▼		
	▼		
	▼		
	▼		
	T▼		
	┰		
	▼		

Corrective Actions to be Completed by PPO

corrective reticine to be completed by 110	
Remove carpet and replace with tile	▼
Clean return drop	▼
Check HVAC supply duct work for normal air flow	▼
	▼
	▼
	▼
	▼
	▼

Outdoor Conditions Tempera	ature 82.5 Relative	Humidity 88.0	Ambient CO2 4	68
		Range <u>CO</u> % - 60 % 920		ccupants
Noticeable Odor No	Visible water damage / staining?	Visible microbial growth?	Amount of material affected	
Ceiling 2' X 2' Lay in	No	No		
Walls Drywall	No	No		
Floor Carpet	No	No		
Ceiling Clean Yes Walls Clean Yes	HVAC Supply Grills Clean	Yes	HVAC Return Grills Clean	No
Flooring Clean Yes	Inside of Supply Duct Clean	Yes	Inside of Return Duct Clean	No
Room Surfaces No Clean	Ceiling at Supply Grills Clean	Yes		
Trash Removed Yes	Exhaust Fans Working	N/A	Unapproved Chemicals / Cleaners in Room	No
Signs of Pests No	Drain Traps Wet	N/A	Air Fresheners	No
Room Cluttered Yes	Food if Stored in Room is in Sealed Containers	N/A	in Room	_ 140
Mechanical Equipment Location	FISH 338		Mechanical Room Clean	Yes
Filters Installed Properly Yes	Filters Clean	Yes	Inside of HVAC Unit Clean	Yes
Condensate Pan Clean Yes	Cooling Coil Clean	Yes		
Fresh Air Intake Location	Roof top	▼	Fresh Air Intake Free of Obstruction	Yes
Pollutant Sources Near Air Intake	No	▼	or obstruction	

Observations

This stor	rage area will be a classroo	m for additional ESE stu	idents. @140 square fe	eet of carpet.	

Corrective Actions to be Completed by Site Based Staff

Laii
▼
▼
▼
▼
▼
▼
▼
▼

Corrective Actions to be Completed by PPO

Corrective Actions to be completed by 110	
Remove carpet and replace with tile	▼
Clean return drop	▼
	▼
	▼
	▼
	▼
	▼
	▼