Room	Priority	Concern	Response	Recommendation	
2109	2	Х	Humidity was elevated at the time of the assessment	Evaluate HVAC for proper operation and repair as appropriate.	
2109	2	Х	CO2 was elevated at the time of the assessment.	Evaluate HVAC for proper operation and repair as appropriate.	
505	2	Room is usually comfortable? (If no, please explain in the notes below.)	Humidity was elevated at the time of the assessment	Evaluate HVAC for proper operation and repair as appropriate.	
505A	1	Windows, windowsills and window frames free of continuous condensation?	Signs of water intrusion identified - elevated moisture content - walls.	Evaluate for cause and repair as appropriate to eliminate water intrusion. Repair/replace wall or ceiling material as necessary.	
Moisture detected behind bulleting		Moisture detected behind bulletin board and frame surrounding	in board and frame surrounding window.		
505A	2	Room is free of smell of mold or mildew?	Odor detected at the time of the assessment	Evaluate for cause of odor and initiate repairs as necessary.	
505A	2	Humidity is generally acceptable? (Typically too high if higher than 60% relative humidity [RH] or too low if lower than 30% RH.)	Humidity was elevated at the time of the assessment	Evaluate HVAC for proper operation and repair as appropriate.	
507	2	Х	Humidity was elevated at the time of the assessment	Evaluate HVAC for proper operation and repair as appropriate.	
801	2	Х	Humidity was elevated at the time of the assessment	Evaluate HVAC for proper operation and repair as appropriate.	
801	2	Х	Temperature was not within range at the time of the assessment.	Evaluate HVAC for proper operation and repair as appropriate.	
804	2	Humidity is generally acceptable? (Typically too high if higher than 60% relative humidity [RH] or too low if lower than 30% RH.)	Humidity was elevated at the time of the assessment	Evaluate HVAC for proper operation and repair as appropriate.	
810	2	Х	Humidity was elevated at the time of the assessment	Evaluate HVAC for proper operation and repair as appropriate.	
811	2	Temperature in my classroom is generally comfortable (72F-78F)?	Humidity was elevated at the time of the assessment	Evaluate HVAC for proper operation and repair as appropriate.	

Tools for Schools Phase IX - Indoor Air Quality Follow-up Action Plan for <u>PPO</u>

Walkthrough Date: 5/17/2012	emp	RH	Co2
		DII	C 2
Harbordale Elementary 0491	79.3	82.6	421



Room	Priority	Concern	Response	Recommendation
830	1	Ceiling tiles or walls free of leaks and/or discoloration (discoloration may indicate periodic leaks)?	Signs of water intrusion identified.	Evaluate for cause and repair as appropriate to eliminate water intrusion. Remove and replace stained ceiling tiles.
840	2	Room is free of smell of mold or mildew?	Odor detected at the time of the assessment	Evaluate for cause of odor and initiate repairs as necessary.
			Minor odor	
840	3	Х	Flooring stained, torn or damaged.	Evaluate flooring and repair/replace as appropriate.