

Report: PPO

**HOLLYWOOD HILLS ELEMENTARY**

Walkthrough Date: 03/23/2007 Temp RH CO2

Outdoor Parameters: 73.7 41.7 861

Room	Priority	Responsible	Answer	Recommendation
001	Inside Parameters:	Temp	RH	CO2
		73.7	41.7	861

2 PPO Gaps in doors identified at the time of assessment. Physical Plant Operations to evaluate and repair as appropriate.

Room	Priority	Responsible	Answer	Recommendation
101M	Inside Parameters:	Temp	RH	CO2
		70.9	43.5	929

1 PPO Signs of water intrusion. Stained ceiling tiles. 2 tiles south wall Physical Plant Operations to evaluate for leaks and repair as appropriate and replace ceiling tiles as appropriate.

Room	Priority	Responsible	Answer	Recommendation
107	Inside Parameters:	Temp	RH	CO2
		72.5	48.2	931

1 PPO Signs of water intrusion. Stained ceiling tiles. 3 stained light fixtures 6 ceiling tiles Physical Plant Operations to evaluate for leaks and repair as appropriate and replace ceiling tiles as appropriate.

Room	Priority	Responsible	Answer	Recommendation
108	Inside Parameters:	Temp	RH	CO2
		69.3	43.8	890

2 PPO Environmental parameters were not within acceptable range at the time of assessment.. Physical Plant Operations to evaluate and repair as appropriate.

Room	Priority	Responsible	Answer	Recommendation
117	Inside Parameters:	Temp	RH	CO2
		71.9	48.7	957

1 PPO Signs of water intrusion. Stained ceiling tiles. Physical Plant Operations to evaluate for leaks and repair as appropriate and replace ceiling tiles as appropriate.

Room	Priority	Responsible	Answer	Recommendation

Room	Priority	Responsible	Answer	Recommendation
118B	Inside Parameters:	Temp 71.8	RH 47.8	CO2 905

1 PPO Signs of water intrusion. Stained ceiling tiles. 1 tile  
Physical Plant Operations to evaluate for leaks and repair as appropriate and replace ceiling tiles as appropriate.

Room	Priority	Responsible	Answer	Recommendation
127	Inside Parameters:	Temp 73.7	RH 46.7	CO2 1133

1 PPO No leaks identified. Signs of previous water intrusion as evidenced by stains in cabinet.  
Physical Plant Operations to evaluate and repair as appropriate.

Room	Priority	Responsible	Answer	Recommendation
301	Inside Parameters:	Temp 71.8	RH 51.5	CO2 511

1 PPO Signs of water intrusion. Stained ceiling tiles.  
Physical Plant Operations to evaluate for leaks and repair as appropriate and replace ceiling tiles as appropriate.  
2 PPO Gaps in doors identified at the time of assessment.  
Physical Plant Operations to evaluate and repair as appropriate.

Room	Priority	Responsible	Answer	Recommendation
482C	Inside Parameters:	Temp 78.4	RH 49	CO2 543

2 PPO Pests observed at the time of assessment.  
Physical Plant Operation to initiate work order to evaluate pest issue within location and take appropriate action.

Room	Priority	Responsible	Answer	Recommendation
501	Inside Parameters:	Temp 72.7	RH 44.6	CO2 744

1 PPO Signs of water intrusion. Stained ceiling tiles.  
Physical Plant Operations to evaluate for leaks and repair as appropriate and replace ceiling tiles as appropriate.

Room	Priority	Responsible	Answer	Recommendation
502	Inside	Temp	RH	CO2

Room	Priority	Responsible	Answer	Recommendation
	Parameters:	74.4	55.1	827
1	PPO		Signs of water intrusion. Leak identified.	Physical Plant Operations to evaluate for leaks and repair as appropriate.
1	PPO		Signs of water intrusion. Stained ceiling tiles. 8	Physical Plant Operations to evaluate for leaks and repair as appropriate and replace ceiling tiles as appropriate.
2	PPO		Gaps in windows identified at the time of assessment.	Physical Plant Operations to evaluate and repair as appropriate.
Room	Priority	Responsible	Answer	Recommendation
503	Inside Parameters:	Temp	RH	CO2
		75.9	53.8	1118
1	PPO		Signs of water intrusion. Stained ceiling tiles.	Physical Plant Operations to evaluate for leaks and repair as appropriate and replace ceiling tiles as appropriate.
2	PPO		Gaps in doors identified at the time of assessment.	Physical Plant Operations to evaluate and repair as appropriate.
Room	Priority	Responsible	Answer	Recommendation
505	Inside Parameters:	Temp	RH	CO2
		75.7	47	1344
2	PPO		Pests observed at the time of assessment.	Physical Plant Operation to initiate work order to evaluate pest issue within location and take appropriate action.
1	PPO		Signs of water intrusion. Leak identified.	Physical Plant Operations to evaluate for leaks and repair as appropriate.
1	PPO		Signs of water intrusion. Stained ceiling tiles. 16 tiles	Physical Plant Operations to evaluate for leaks and repair as appropriate and replace ceiling tiles as appropriate.
Room	Priority	Responsible	Answer	Recommendation
506	Inside Parameters:	Temp	RH	CO2
		74.3	46.8	1400
2	PPO		Pests observed at the time of assessment.	Physical Plant Operation to initiate work order to evaluate pest issue within location and take appropriate action.
1	PPO		Signs of water intrusion. Stained ceiling tiles.	Physical Plant Operations to evaluate for leaks and repair as appropriate and replace ceiling tiles as appropriate.
2	PPO		Gaps in windows identified at the time of assessment.	Physical Plant Operations to evaluate and repair as appropriate.

Room	Priority	Responsible	Answer	Recommendation
724C	Inside Parameters:	Temp 72	RH 38.5	CO2 980

1 PPO Signs of water intrusion. Stained ceiling tiles. 11 tiles  
Physical Plant Operations to evaluate for leaks and repair as appropriate and replace ceiling tiles as appropriate.

Room	Priority	Responsible	Answer	Recommendation
985P	Inside Parameters:	Temp 76.2	RH 40.1	CO2 1209

2 PPO Pests observed at the time of assessment.  
Physical Plant Operation to initiate work order to evaluate pest issue within location and take appropriate action.